

## ADA Deficiencies Summary

Region: University  
Location: DeWitt Rest Area  
Date: 01/03/2019

### Accessible Routes

1. Is the route surface stable, firm, slip-resistant, and no gaps or holes greater than 0.5"?
  - *There are gaps in locations of spalled concrete and repaired concrete.*
2. Is the running slope of walking surfaces not greater than 1:20 (5%)? **(402.2)**
  - *Several locations on the walking surface were measured with slopes exceeding 5%.*
3. Is the cross slope of the walking surface not greater than 1:48 (2.08%)? **(403.3)**
  - *Multiple locations were measured with slopes exceeding 2.08%.*

### Parking Spaces

1. Are the reserved accessible spaces located closest to the accessible entrance on an accessible route?
  - *The parking spaces are located on an accessible route but are not closest to the accessible entrance. Other parking spaces are closer.*
2. Are accessible spaces at least 8' wide with an access aisle at least 5' wide? **(502.2 & 502.3)**
  - *All the accessible parking spaces meet the space width. One of the accessible parking spaces does not have an accessible aisle.*
3. Is one van accessible space available for every 6 accessible spaces? Signs identifying van parking spaces shall contain the designation "Van Accessible"?
  - *There is a van accessible parking space (based on dimensions of parking space and access aisle) but there is no van accessible sign.*

### Curb Ramps

1. Is the running slope of the curb ramps no greater than 1:12 (8.33%)? **(406.1 & 405.2)**
  - *The running slope of the curb ramps are approx. 5.15%*
2. Are the counter slopes adjoining gutters immediately adjacent to curb ramps not greater than 1:20 (5%)? **(406.2)**
  - *North curb ramp counter slope is 6.55%*
  - *South curb ramp counter slope is 8.5%*
3. Is there a level landing, slope no greater than 1:48 (2.08%) in all direction, at least 36" deep and as wide as the curb ramp? **(406.4)**
  - *North curb ramp landing has a maximum slope of 3.65%*
  - *There is no curb ramp landing for the south curb ramp.*
4. Are curb ramp flares, where provided, not greater than 1:10 (10%)? **(406.3)**
  - *North curb ramp slope is 5.0%, okay.*
  - *South curb ramp slope is 10.3%.*
5. If the landing at the top is less than 36" deep, are the curb ramp flares no greater than 1:12 (8.33%)? **(406.4)**
  - *South curb ramp flare slope is 10.3%. No landing is present.*
6. Does the curb ramp provide a flush, smooth (less than 0.25" vertical difference) transition to the access aisle?
  - *North curb ramp provides a vertical difference approx. 1.25" where the ramp meets the parking lot.*

## Entry Doors

1. Does the door closer provide 5 seconds minimum from 90 degrees to 12 degrees when closing? **(404.2.8)**
  - *The door closer provides approx. 3 seconds.*

## Telephones

1. Is the highest operable part of the telephone no higher than 48" above the floor surface? **(704.2.2)**
  - *The highest operable part is approx. 51" above the floor surface.*
2. If the bottom edge of the telephone higher than 27" from the floor surface, does it not protrude more than 4" from the wall? **(307.2)**
  - *The bottom of the telephone is approx. 32" from the floor surface and protrudes approx. 7" from the wall.*
3. Does at least one telephone have TTY? **(217.4.1)**
  - *There is no TTY.*
4. Is the touch surface of the TTY keypad at least 34" above the floor surface? **(704.4.1)**
5. Is the TTY identified by the International Symbol of TTY? **(703.3.2.2)**
6. Do signs that provide direction to public telephones also provide direction to the TTY? **(216.9.2)**
  - *There are no TTY signs.*
7. Do telephones that do not have a TTY provide direction to the TTY? **(216.9.2)**
  - *They do not provide any signs to the TTY.*

## Fire Alarms

1. If there are fire alarm systems, do they have both flashing lights and audible signals? **(702.1)**
  - *There are no active fire alarms seen in the building.*

## Bathroom

1. If there is a coat hook, is it no less than 15" and no greater than 48" above the floor? **(603.4)**
  - *There is no coat hook present, but there are holes from where a coat hook previously was approx. 53" from the floor surface.*
2. Is the top of the toilet seat between 17" and 19" from the floor surface measured to the top of the seat? **(604.4)**
  - *The top of the seat is approx. 16.5" above the floor surface.*
3. Is the top of the side mounted grab bar mounted between 33" and 36" from the floor surface? **(609.4)**
  - *The top of the side grab bar is approx. 37" above the floor surface.*
4. Is there at least 12" clearance between the side mounted grab bar and protruding objects above?
  - *The clearance is approx. 7" between.*
5. Is the top of the rear mounted grab bar mounted between 33" and 36" from the floor surface? **(609.4)**
  - *The top of the side grab bar is approx. 37" above the floor surface.*
6. Is the flush control on the open side of the toilet? **(604.6)**
  - *The flush control is mounted in the center of the toilet on the wall.*
7. Is the stall door self-closing? **(604.8.1.2)**
  - *The stall door stays open.*
8. Are there door pulls on both sides of the door that are operable with one hand and do not require tight grasping, pinching, or twisting of the wrist? **(604.8.1.2)**
  - *The inside of the door provides only a locking latch, no pull handle to shut the door. The outside of the door provides a pull handle.*