



1. Division A, excavator loading timbers into trucks in Cell 4.



2. Release point, no sheen noted today.



**3. B5 Sediment Trap, no activity noted at time of overflight.**



**4. Confluence and pond north of confluence, seen observed at both locations.**



**5. MP4.0 and Island E, no activity noted today, sheen observed on island.**



**6. MP4.5 and Island F, minor sheen observed.**



**7. MP5.55 RDB.**



**8. Boom configuration above Ceresco Dam.**



**9. MP5.55, sheen observed within boom.**



**10. MP5.75 RDB, sheen observed within the boom.**



**11. MP15.75, Mill Pond.**



**12. MP15.0 Island, new boom installed, no significant sheen observed.**



**13. MP15.25 Mill Pond, minor sheen noted along LDB.**



**14. MP21.5 Oxbow, sheen observed within boom.**



**15. Delta A, vegetation cutter in operation.**



**16. Morrow Lake Delta, submerged oil recovery.**



**17. MP37.75, submerged oil work continues.**



**18. Sheen trail on Morrow Lake, looking west toward E5.**



**19. Close up of skimmer boat.**



**20. Control Point E6, no sheen, some minor debris observed.**