


July 20-22, 2011 Overflight Photo Log



7/20/2011

Sheen observed within the pond at the Source Area



7/22/2011

Slight sheen observed at the confluence of Talmadge Creek and the Kalamazoo River



7/22/2011 | Lily Pad swamp excavator beginning access work at MP 4.5



7/22/2011 | Overview of submerged oil recovery operations near Ceresco Dam at MP 5.75



7/22/2011

Sheen observed within Mill Pond at MP 15.5



7/22/2011 | Sheen observed within the Oxbow at MP 21.5



7/22/2011 | Overview of submerged oil recovery operations in the Morrow Lake Delta



7/22/2011

Submerged oil recovery operations in the Morrow Lake Delta



7/22/2011 | Overview of Morrow Lake