

Situation Photo Log

Saturday, November 19, 2011

Kalamazoo River / Enbridge Spill

Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Talmadge Creek, soil solidification and loading station just south of Division Drive.



2. Talmadge Creek, excavation and restoration just south of Division Drive.



3. Talmadge Creek, loading excavated sediment into dump truck.



4. Talmadge Creek, piping for creek diversion system just south of Division Drive.



5. Talmadge Creek, discharge point of creek diversion system, just north of Division Drive.



6. Frac-City Soil Cell A.



7. Frac-City Soil Cell A. End loader loading truck with soil from Cell A.



8. Frac-City Soil Cell B. Cell is empty except for some silt curtain.



9. Frac Tank City Decon pad, cleaned containment boom awaiting inspection and repair.



10. Northern decon pad at Frac City. Boat dock section awaiting decon.



11. Southern decon pad at Frac City, workers cleaning dump truck.



12. B5 sediment trap, no sheen or turbidity observed.



13. Close up of sediment trap.



14. Confluence point, no sheen or turbidity observed.