



**Photograph No. 27: Exterior view of the Pole Barn, North Riding Arena and Main Horse Barn buildings.**



**Photograph No. 28: Interior view of typical horse stalls in the Main Horse Barn building.**



**Photograph No. 29:** Exterior view of the Milk House east from the Dairy Cattle building.



**Photograph No. 30:** Interior view of the Milk House building. Picture shows a refrigeration unit.



04/21/2009

**Photograph No. 31:** Interior view of the typical animal stalls in the Multi-Livestock building.



04/21/2009

**Photograph No 32:** Interior view of the storage of benches and trash barrels in the southern half of the Multi-Livestock building.




**Photograph No. 33:** View of the paved area east of the Multi-Livestock building and the fence on the eastern boundary of the subject Site looking north.



**Photograph No. 34:** View of the South Riding Arena.



**Photograph No. 35:** Exterior view of the former Electrical building and Whitehall building.



**Photograph No 36:** View of paint can storage in the Whitehall building.



**Photograph No. 37: View of the chemical strippers within the Whitehall building.**




**Photograph No. 38: View of the holes in the roof from the interior of the Whitehall building.**




**Photograph No 39: View of the damaged wood floor in the Whitehall building.**



**Photograph No. 40: View of the Poultry building from the southwest mechanical room roof access of the Coliseum.**



**Photograph No. 41: View of the pond within the Poultry building.**



**Photograph No. 42: View of the staircase going to the second floor within the Poultry building.**



**Photograph No. 43:** Exterior view of the new electrical substation showing the Coliseum in the background.



**Photograph No. 44:** View of the Goat Barns (north and south) with the Poultry building behind.



**Photograph No. 45: View of the World's Largest Stove.**



**Photograph No. 46: View of the Outdoor Skills Center. No access was available.**



**Photograph No. 47: Exterior view of the Community Arts building from the north looking south with the State Fair and Palmer Lane Apartments behind.**




**Photograph No. 48: View of the exhibit hall within the Community Arts building. The exhibit hall was being setup for a science fair for the Head Start program.**



**Photograph No. 49:** View of the significant damage to the asbestos containing plaster ceiling within the projector room of the Community Arts building.



**Photograph No. 50:** Exterior view of the Administration Building.



**Photograph No. 51:** View from the interior of the Administration Building looking at the 1<sup>st</sup> floor reception and office area.



**Photograph No. 52:** View of the Administration Building 1<sup>st</sup> Floor mechanical room.