

Photograph No. 53: Exterior view of Ulysses S. Grant's house.



Photograph No. 54: Exterior view of the Bandshell.



Photograph No. 55: View of drums containing hydraulic oil on the backside of the Bandshell.




Photograph No. 56: View of two AST's (one gasoline and one diesel) to the east of the Bandshell.



Photograph No. 57: View of semi trucks and tractor trailers to the east of the Bandshell (no access).




Photograph No. 58: View of various trailers and medical response vehicles (no access).



Photograph No. 59: Exterior view of the Volunteer Building housing the Youth Connection program.



Photograph No 60: View of the interior of the Volunteer Building. Currently under renovation.




Photograph No 61: View of the boiler in the mechanical room of the Volunteer Building.




Photograph No. 62: Exterior view of the Dodge (Ford) Pavilion looking east.



Photograph No. 63: View of the “showroom” in the Dodge Pavilion.




Photograph No. 64: View of the electrical room in the Dodge Pavilion.



Photograph No. 65: View of the mechanical room of the Dodge Pavilion showing the significantly damaged asbestos containing material.



Photograph No. 66: View of the Plaza Toilet Building north of the Dodge Pavilion. Also show are pole mounted transformers.




Photograph No. 67: Exterior view of the White Brick Comfort Station.



Photograph No. 68: Exterior view of the Exhibit Building looking south with the State Fair Apartments behind.



Photograph No. 69: View from the interior of the Exhibit Building showing storage of materials.



Photograph No. 70: View of the restrooms east of the Volunteer Building.



Photograph No. 71: View of the former UST location.



Photograph No. 72: View of fenced in transformers near the former UST location.




Photograph No. 73: View of the interior of the West Mall.



Photograph No. 74: View from the north looking south of the East Mall. This area is used for parking for the adjacent Agriculture Building.



Photograph No. 75: Exterior view of the Agriculture Building (Joe Dumar's Fieldhouse) from the northeast looking west.



Photograph No 76: Interior view of the Agriculture Building (Joe Dumar's Fieldhouse) showing the basketball courts.



Photograph No. 77: Exterior view of the south entrance to the Michigan Mart.



Photograph No. 78: View of the interior southern portion of the Michigan Mart showing the football turf.



Photograph No. 79: View of the northwest entrance to the Michigan Mart.



Photograph No 80: View of north interior section of the Michigan Mart showing the Next Shot Golf, LLC business.