




View of sidewalk and west side of site, looking northwest.
Photo taken by Jeffrey Guzick on October 5, 2009.



View of southern portion of property and adjacent alley, looking east.
Photo taken by Jeffrey Guzick on October 5, 2009.



View of sidewalk and curb along intersection of Warren Avenue and 24th Street.
Photo taken by Jeffrey Guzick on October 5, 2009.



View of former southern UST pump island, looking northeast.
Photo taken by Jeffrey Guzick on October 5, 2009.



View of concrete overlying USTs, looking north.
Photo taken by Jeffrey Guzick on October 5, 2009.



Southern UST fill port.
Photo taken by Jeffrey Guzick on October 6, 2009.



Usher Oil preparing to pump liquids inside USTs.
Photo taken by Jeffrey Guzick on October 6, 2009.



View inside vault on top of Southern UST.
Photo taken by Jeffrey Guzick on October 6, 2009.



Removing surface concrete cover neat USTs, looking southwest.
Photo taken by Jeffrey Guzick on October 6, 2009.



Stockpiling impacted soils overlying USTs, looking north.
Photo taken by Jeffrey Guzick on October 6, 2009.



Piping associated with USTs, looking north.
Photo taken by Jeffrey Guzick on October 6, 2009.



View of the top of Southern UST, looking north.
Photo taken by Jeffrey Guzick on October 6, 2009.



View of the top of Southern and Middle USTs.
Photo taken by Jeffrey Guzick on October 6, 2009.



Pumping liquids from inside of Northern UST.
Photo taken by Jeffrey Guzick on October 6, 2009.



Piping associated with Northern UST, looking northeast.
Photo taken by Jeffrey Guzick on October 6, 2009.



Elevating Southern UST out of excavation with view of impacted soils, looking north.
Photo taken by Jeffrey Guzick on October 8, 2009.



Lifting the Southern UST out of the excavation, looking south.
Photo taken by Jeffrey Guzick on October 8, 2009.



Loading impacted soils into truck for off-site disposal, looking west.
Photo taken by Jeffrey Guzick on October 8, 2009.



Technical Service Professionals (TSP) installing fence on site, looking south.
Photo taken by Jeffrey Guzick on October 7, 2009.



TSP digging fence post holes on west side of site, looking west.
Photo taken by Jeffrey Guzick on October 7, 2009.



Staging emptied USTs on plastic sheeting, looking northeast.
Photo taken by Jeffrey Guzick on October 8, 2009.



Dropping off backfill at eastern side of site, looking south.
Photo taken by Jeffrey Guzick on October 8, 2009.



Water with visible sheen accumulating in the excavation following rainfall.
Photo taken by Jeffrey Guzick on October 12, 2009.



Pumping water with sheen into tanker truck.
Photo taken by Jeffrey Guzick on October 12, 2009.



View of stockpiled backfill, looking southeast.
Photo taken by Jeffrey Guzick on October 7, 2009.



Holes cut in sides of USTs for venting fumes, looking west.
Photo taken by Jeffrey Guzick on October 8, 2009.



Putting dry ice inside USTs, looking north.
Photo taken by Jessica Brandeberry on October 9, 2009.



Cleaning USTs after venting, looking north.
Photo taken by Jeffrey Guzick on October 12, 2009.



Loading USTs on truck for off-site disposal, looking east.
Photo taken by Jeffrey Guzick on October 12, 2009.



View of west portion of excavation and former Southern pump island, looking west.
Photo taken by Jeffrey Guzick on October 12, 2009.



View of excavation near former Middle pump island, looking east.
Photo taken by Jeffrey Guzick on October 14, 2009.



Excavating piping near former Middle pump island, looking east.
Photo taken by Jeffrey Guzick on October 14, 2009.



Northern portion of excavation, looking north.
Photo taken by Jeffrey Guzick on October 14, 2009.



Former North pump island, looking east.
Photo taken by Jeffrey Guzick on October 14, 2009.



View of piping, concrete and impacted soil from northern portion of excavation.
Photo taken by Jeffrey Guzick on October 14, 2009.



Backfilling northern portion of the excavation, looking east.
Photo taken by Jeffrey Guzick on October 14, 2009.



Compacting lifts of backfill in the excavation, looking east.
Photo taken by Jeffrey Guzick on October 15, 2009.



Spreading gravel over compacted backfill, looking southeast.
Photo taken by Jeffrey Guzick on October 16, 2009.



Compacting gravel over backfill, looking south.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of excavation after gravel compaction completed.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of northern portion of excavation following backfill and gravel compaction.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of southern portion of site following backfill and gravel compaction, looking east.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of sidewalk along Warren Avenue following excavation, looking east.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of swept surface concrete with excavation area in background, looking south.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of sidewalk along 24th Street following excavation, looking north.
Photo taken by Jeffrey Guzick on October 16, 2009.



View of eastern portion of the site following the excavation, looking east.
Photo taken by Jeffrey Guzick on October 16, 2009.