



1. Standing water in Division A staging area due to overnight rain.



2. Release point and Talmadge Creek. Creek level is over the banks.



3. Standing water at north end of Frac Tank City.



4. Frac-City Soil Cells, standing water in southwest corner of staging area.




5. Frac City decon area, boom and boat staged for decon.



6. B5 Sediment Trap, water levels higher than containment.



7. Confluence, no sheen observed.



8. House Demolition/cleanup at MP2.25 for future river public access point.



9. Island A, island is partially under water due to overnight rains.



10. Island E, boom remains on downstream side of island.



11. MP4.5 Overview.



12. MP5.55 submerged oil activities above Ceresco Dam.



13. MP5.55 submerged oil recovery.



14. Ceresco Dam. Sheen observed within containment.



15. Swamp buggy working near MP8.0.



16. MP9.5 Island, work has been completed.



17. MP10.5. Swamp buggy conducting submerged oil work.



18. MP10.75, close up of swamp buggy with water jet attachment.



19. MP11.25R1, no activity noted.



20. MP11.25R2, road mat removal continues. Much of area under water.



21. MP11.25R2, mat road removal.



22. MP12.6, shoreline restoration work appears complete.



23. MP14.35, overview of boom configuration.



24. MP15.00, sheen observed within containment.



25. MP14.35, vegetation / debris removal.



26. MP15.75, sheen from upstream activities observed going over spillway.



27. MP21.5 Oxbow, GAC system set up.



28. Morrow Lake Delta, no activity noted in Delta A.



29. Central portion of Morrow Lake Delta.



30. Marsh Master parked on sand bar in Morrow Lake Delta.



31. Towing in a broken airboat on Morrow Lake Delta.



32. Control Point E4.5, boom maintenance.



33. Control Point E6.0. No sheen or debris noted.



34. Skimmer boat in northeastern portion of Morrow Lake.



35. South shore of Morrow Lake Delta. No sheen observed.