



1. Talmadge Creek RI continued.



2. Talmadge Creek RI continued.



3. B5 Sediment Trap no activity or sheen observed.



4. Confluence slight sheen observed.



5. MP2.25 public river access progress.



6. MP4.5 excavation work continued.



7. MP4.5 excavation work.



8. MP4.5 Excavation work.



9. MP4.5 excavation work, boom deployed sheen observed.



10. MP5.55 submerged oil work, boom at MP5.55N has been removed.



11. MP5.55 submerged oil recovery work.



12. MP5.63 submerged oil recovery work.



13. MP5.75 submerged recovery oil work.



14. MP5.63 submerged oil recovery work.



15. Ceresco Dam sheen heading to Chevron boom.



16. MP5.55N submerged oil recovery work.



17. MP14.25 submerged oil recovery work.



18. Sheen being generated by submerged oil recovery operations at MP14.25.



19. MP14.5 submerged oil recovery work.



20. MP15.0 sheen observed within river channel.



21. MP21.5 Oxbow excavation work.



22. MP21.5 Oxbow sheen observed within boom.



23. MP21.5 Oxbow excavation work.



24. MP21.5 Oxbow sheen observed behind swamp excavator outside of sheet piling.



25. Morrow Lake Delta submerged oil recovery work.



26. Morrow Lake Delta submerged oil recovery work.



27. Morrow Lake Delta submerged oil recovery work.



28. Continued assembly of the pontoon excavators.



29. Morrow Lake submerged oil recovery work.



30. Morrow Lake submerged oil recovery work woody debris removal.



31. Morrow Lake submerged oil recovery work woody debris removal.



32. Morrow Lake boom staged out in lake.