

Situation Photo Log

Saturday, October 8, 2011


Kalamazoo River / Enbridge Spill

Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Talmadge Creek, Geoprobe crew sampling near MP0.25.



2. Frac tank city decon area. Boom decon.



3. Soil staging area. Soils have been removed. Three roll-off boxes and boom observed.



4. The first of two Talmadge Creek RI crews near MP1.5 collecting soil samples with Geoprobe rig.



5. The second of two Talmadge Creek RI crews near MP1.5 collecting soil samples with Geoprobe rig.



6. Talmadge Creek materials staging yard.



7. Confluence, no oil sheen or activity noted.



8. Island A, submerged oil recovery work in progress.



9. Close up of spray bar operating on shore of Island A.



10. MP4.18 LDB, crews have demob'd from this location back to Island A.



11. Crews conducting boom deployment across from MP4.18 LDB.



12. MP5.65 above Ceresco Dam, one sweeper boat continues to work above dam.



13. MP5.8, submerged oil recovery work below Ceresco Dam continues. Sheen observed within containment.



14. Boom configuration below Ceresco Dam.



15. Overbank crews observed at Lonely Tree, MP11.75 LDB.



16. MP15.0, overview of submerged oil recovery work in southern end of Mill Pond. Some sheen observed within containment.



17. MP15.5, overview of south Mill Pond. No activity observed.



18. MP15.75, no activity observed.



19. MP21.5, no sheen observed.



20. MP36.25, submerged oil recovery just east of 35th Street Bridge.



21. Overview of submerged oil recovery and vegetation removal west of 35th Street bridge.



22. Excavators with spray bars and support boats in Channel 1 of Morrow Lake Delta.



23. Woody debris removal along northern shore of Morrow Lake Delta.



24. Southwest corner of Morrow Lake Delta, pumper boats continuing submerged oil recovery.



25. Northeast corner of Morrow Lake, pontoon excavators conducting submerged oil recovery.



26. Pumper boats in Morrow Lake fan.