

Summary of Violations
 Fall Fatality at Wayne State University Construction Site, Detroit
 March 24 through May 13, 2008
 (Inspections: 308948298; 308948306; 308948314; 308948348; and 308948330)

TNT's Excavating, #308948298

Rule/Standard	Classification	Description	Penalty
Part 1, General Rules, Rule 114(1)	Serious	Employer did not develop and implement an Accident Prevention Program.	\$2,100
Part 45, Fall Protection 1926.503(a)(1)	Serious	Inadequate fall protection training.	\$2,100
Part 45, Fall Protection 1926.501(b)(1)	Serious	No fall protection - unguarded edge.	\$2,100
Part 45, Fall Protection 1926.502(b)(1)	Serious	Top rail of guardrail system is not at proper height.	\$2,100
Part 45, Fall Protection 1926.502(b)(2)	Serious	No mid-rail installed.	grouped
Part 45, Fall Protection 1926.502(b)(3)	Serious	Guardrail was loose.	grouped
Part 45, Fall Protection 1926.502(i)(3)	Serious	Roof covers were not secured.	\$2,100
Part 45, Fall Protection 1926.502(i)(4)	Serious	Roof covers were not identified.	grouped
Part 45, Fall Protection 1926.503(b)(1)	Other	No fall protection training certification.	\$450
		Total	\$10,950

Houseman Construction Co., #308948306

Rule/Standard	Classification	Description	Penalty
Part 45, Fall Protection 1926.501(b)(1)	Repeat/Serious	No fall protection - unguarded edge.	\$4,000
Part 1, General Rules, Rule 114(2)(c)	Serious	Employer did not adequately inspect for hazards.	\$2,000
Part 45, Fall Protection 1926.503(c)(1)(2)(3)	Serious	Fall protection retraining.	\$1,000
Part 45, Fall Protection 1926.501(b)(14)	Serious	Wall openings not guarded.	grouped

Part 45, Fall Protection 1926.501(c)(1)(2)(3)	Serious	No falling object protection.	grouped
Part 45, Fall Protection 1926.502(b)(1)	Serious	Top rail of guardrail system is not at proper height.	\$2,000
Part 45, Fall Protection 1926.502(b)(2)	Serious	No mid-rail installed.	grouped
Part 45, Fall Protection 1926.502(b)(3)	Serious	Guardrail was loose.	grouped
Part 45, Fall Protection 1926.502(i)(3)	Serious	Roof covers were not secured.	\$2,000
Part 45, Fall Protection 1926.502(i)(4)	Serious	Roof covers were not identified.	grouped
Part 1, General Rules, Rule, 132(1)	Other	Improper 300A Summary recordkeeping.	\$300
Part 1, General Rules, Rule, 130(1)	Other	No separate 300 Log for project.	grouped
		Total	\$11,300

Probuild of Delton LLC, #308948314

Rule/Standard	Classification	Description	Penalty
Part 1, General Rules, Rule, 114(2)(b)	Serious	Inadequate Accident Prevention Program	\$750
Part 45, Fall Protection 1926.503(c)(1)(2)(3)	Serious	Fall protection retraining.	\$1,500
Part 45, Fall Protection 1926.501(b)(1)	Serious	No fall protection - unguarded edge.	\$750
Part 45, Fall Protection 1926.502(b)(1)	Serious	Top rail of guardrail system is not at proper height.	\$1,500
Part 45, Fall Protection 1926.502(b)(2)	Serious	No mid-rail installed.	grouped
Part 45, Fall Protection 1926.502(b)(3)	Serious	Guardrail was loose.	grouped
Part 45, Fall Protection 1926.502(i)(3)	Serious	Roof covers were not secured.	\$1,500
Part 45, Fall Protection 1926.502(i)(4)	Serious	Roof covers were not identified.	grouped
Part 45, Fall Protection 1926.503(b)(1)	Other	Fall protection certification.	0
		Total	\$6,000

Assemblers Inc., #308948348

Rule/Standard	Classification	Description	Penalty
----------------------	-----------------------	--------------------	----------------

Part 1, General Rules, Rule, 114(2)(b)	Serious	Inadequate Accident Prevention Program	\$2,000
Part 45, Fall Protection 1926.503(c)(1)(2)(3)	Serious	Fall protection retraining.	\$2,000
Part 45, Fall Protection 1926.502(i)(3)	Serious	Roof covers were not secured.	\$2,000
Part 45, Fall Protection 1926.502(i)(4)	Serious	Roof covers were not identified.	grouped
Part 45, Fall Protection 1926.503(b)(1)	Repeat/Other	Fall protection certification	\$100
		Total	\$6,100

RJO Mechanical & Residential Plumbing, #308948330

Rule/Standard	Classification	Description	Penalty
Part 1, General Rules, Rule, 114(2)(b)	Serious	Inadequate Accident Prevention Program	\$2,000
Part 45, Fall Protection 1926.503(a)(1)	Serious	Fall protection training.	\$2,000
Part 45, Fall Protection 1926.502(i)(3)	Serious	Roof covers were not secured.	\$2,000
Part 45, Fall Protection 1926.502(i)(4)	Serious	Roof covers were not identified.	grouped
		Total	\$6,000

Total penalty for all five inspections: \$40,350.00