


Michigan's Deteriorating Roads and Bridges

November 2014



Southwest Region



**I-196 under M-63 (Hager Shore Road), Berrien County
Fallen Concrete from Deck on Top of the Mesh False Decking**



**I-94 BL Eastbound over I-69, Marshall Township, Calhoun County
Temporary supports to support beams**



**I-94 BL Eastbound over I-69, Marshall Township, Calhoun County
Crack in abutment requiring temporary supports**



**I-196 under M-63 (Hager Shore Road), Berrien County
Hole in Beam / Section Loss of Beam**



**I-196 under M-63 (Hager Shore Road), Berrien County
Beams with Temporary Supports at Piers Due to Severe Section
Loss on Beam Ends**



**Kruger Road over I-94, near New Buffalo, Berrien County
Painted Orange Lines Delineate Delamination of Concrete**



**Sprinkle Road over I-94, Kalamazoo, Kalamazoo County
Wood False Decking over Traffic under Poor Deck**



**Sprinkle Road over I-94, Kalamazoo, Kalamazoo County
Poor Bridge Deck Bottom in Tail Span**



**I-94 over East Michigan(40th Street), Charleston Township, Kalamazoo County
Deck Fascia with Severe Spalling to Rebar**




**I-94 BL (MLK Drive) over I-94, City of Battle Creek, Calhoun County
Poor Bridge Deck with Wood False Decking**



**I-94 WB Hartford to Lawrence Township, Van Buren County
Excessive Joint Deterioration/Failure & Patching**



**I-94 WB Lawrence Township, Van Buren County
Excessive Joint Deterioration/Failure & Patching**



**I-94 WB inside lane, south of New Buffalo near mile marker 1, Berrien County
Concrete Pavement Failure (Poor Ride Quality)**