
VIAP ASSESSMENT AND MITIGATION IN A COMPLEX SETTING



Joel Parker, Hamp, Mathews & Associates jparker@hampmathews.com

Jeff Crum, Hamp, Mathews & Associates jcrum@hampmathews.com

Case Study Overview

- Exposure Setting Complexities and Challenges
- VIAP CSM
 Assessment
- VIAP Mitigation
- Outcomes




Mason Esker

Site Setting

Americhem Sales Corp.


340 North Street, Mason






Hamp, Mathews & Associates, Inc.

Environmental Setting




- Chemical Distributorship
- Mason Esker
- Bifurcated Plume
 - North Plume VC
 - South Plume TCE
 - Source Everything
- Americhem Sales
 - Due Diligence in '97
 - Discovery of NAPLMass
- MDEQ Takes Lead
 - SWQIF funded

Original Site



- Old tank farm tight to the facility, <u>NO</u> containment and rusted tanks.
- Old fuel island with no containment
- No security

Historic Tank Locations



- PVOCs
- CVOCs
- Solvents

Hamp, Mathews & Associates, Inc.


Improvements




Speech given to the NACD (National Association of Chemical Distributors) members on safe site layout and safety practices.

Hamp, Mathews & Associates, Inc.

Environmental History



Hamp, Mathews & Associates, Inc.




Major Work Areas

- North Plume
- Source Area
- South Plume
- Off-Site VIAP


Mason Esker

"Hogsback"





Off-Site VIAP Setting



- Mixed Use
- Mason Esker
- 12 Properties



Hamp, Mathews & Associates, Inc.

Rapid VIAP Assessment


- Assess TCE in Shallow Groundwater as Potential Vapor Source
 - 60 shallow piezometers
 - 6 Vertical Aquifer Sample Borings
- Assess TCE in Soil Gas
 - 35 nested soil gas points (deep & shallow)
- August to October 2017

Rapid VIAP Assessment

- Home or Property Specific Assessments
 - 12 properties (IAs & VPs)
 - November December 2017
- Utility/Sewer Special Assessments
 - Multiple sewer video surveys


August 2017 Shallow GW - TCE


- Groundwater flow to the east and slow until it reaches Esker
- Flows fast and follows the Esker South
- Does not underflow the Sycamore



August 2017 Soil Gas - "Early Snapshot"

- All exterior building soil gas, two depth intervals
- TCE > RIASLs and TS RIASLs
- Some homes we expected to Mitigate remained "Assessment"
- Some homes we expected to "Assess" only required Mitigation
- Confounded by second source (Home 3 – furniture restoration)






Overlying Soil Gas Plume


"Bullseyes" don't match

Utilities influence transport



Utilities as Secondary Transport Mechanism

- Chloroform from sewer and water
- Coincident with gaps and cracks
- Utilities capable of transport




Final Mitigation Locations

5 Mitigation Properties

7 Monitor & Assess

 Spatial Relationship to Source/Site Not Reliable for Predictions






Home 10 Mitigation


- 3-Unit Apartment
- Old Basement, c. 1800's
- 2 Suction Points
- 1 Fan
- Sealed Many Cracks
- Prove-Out Successful





Home 3 Mitigation


- Former Body Shop
- Furniture Repair Shop
- Mixed Use Building
- 6 Suction Pits
- 4 Fans
- Several Sub-slab Obstructions
- Building Specific Design
- Prove-Out Challenging but Successful



Home 2 Mitigation


- Residential Old Basement & Crawl
- Sealed Significant Cracks
- 2 Suction Pits & 1 Fan

 Prove-Out Challenging but Successful





Home 7 Mitigation


- Residential Old Basement
- Sealed Sump & Significant Cracks
- 1 Suction Pit & 1 Fan
- Simple Design Due to Detailed Diagnostics
- Prove-Out Successful



Vapor Source Bioremediation









Vapor Source Bioremediation


Before




After




Vapor Source Bioremediation







Dehalococcoides Concentration 2 x 10⁸ cells/liter




Hamp, Mathews & Associates, Inc.


Improvements in Soil Gas Quality





Improvements in Soil Gas Quality





Outcomes & Findings

- Assessed 12 Private Properties
- Installed 5 VIAP Mitigation Systems
 - 4 SSDS
 - 1 Air Purifying Units + Bioremediation
- Remediation of Vapor Source
 - Significant Improvement in Vapor Plume
- "Monitor & Assess" at 7 Properties
 - IA < RIASLs After 1 Year, i.e., VIAP Not Complete
- VIAP CSM and Mitigation Very Home Specific
- 100' Inclusion Zone Valid

Future Activities

- Continued Off-Site Vapor Source Remediation
- Continued VIAP Mitigation System O&M
- Increased Source Area Remediation
 - Intensified Bio
 - N₂ Sparge Pilot to Enhance Bio & Physical Removal

Key Contributors

- Americhem/Bruce Whetter
- MDEQ/EGLE
- Roy F. Weston
- Environmental Consulting & Technology, Inc.
- M.Dybas & Associates LLC

Questions???