

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66636	Lead 250	1	CF003 ROOM 15	PRE	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66650	Lead 250	0	CF003 ROOM 15	3S 1	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66664	Lead 250	0	CF003 ROOM 15	3S 2	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66637	Lead 250	2	CF004 ROOM 17	PRE	Copper 250	110	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present. Particulate sample was taken. This is a science faucet, not used for drinking water.
UH66651	Lead 250	5	CF004 ROOM 17	3S 1	Copper 250	180	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator was not reinstalled prior to sampling.
UH66665	Lead 250	5	CF004 ROOM 17	3S 2	Copper 250	210	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator was not reinstalled prior to sampling.
UH66638	Lead 250	30	CF005 ROOM 17	PRE	Copper 250	100	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	No aerator present. Water was discolored. This is a science faucet, not used for drinking water.
UH66652	Lead 250	11	CF005 ROOM 17	3S 1	Copper 250	110	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66666	Lead 250	9	CF005 ROOM 17	3S 2	Copper 250	140	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66639	Lead 250	11	CF006 ROOM 26	PRE	Copper 250	310	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present. Particulate sample was taken.
UH66653	Lead 250	8	CF006 ROOM 26	3S 1	Copper 250	200	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66667	Lead 250	9	CF006 ROOM 26	3S 2	Copper 250	270	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66640	Lead 250	5	CF007 ROOM 26	PRE	Copper 250	250	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66654	Lead 250	1	CF007 ROOM 26	3S 1	Copper 250	140	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66668	Lead 250	1	CF007 ROOM 26	3S 2	Copper 250	190	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66641	Lead 250	1	CF010 LOUNGE ROOM 27	PRE	Copper 250	60	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66655	Lead 250	0	CF010 LOUNGE ROOM 27	3S 1	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66669	Lead 250	0	CF010 LOUNGE ROOM 27	3S 2	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66642	Lead 250	0	CF012 COMMUNITY ROOM	PRE	Copper 250	60	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66656	Lead 250	1	CF012 COMMUNITY ROOM	3S 1	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66670	Lead 250	2	CF012 COMMUNITY ROOM	3S 2	Copper 250	50	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66646	Lead 250	0	CF018 ROOM 4	PRE	Copper 250	50	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66660	Lead 250	2	CF018 ROOM 4	3S 1	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator was not reinstalled prior to sampling.
UH66674	Lead 250	1	CF018 ROOM 4	3S 2	Copper 250	0	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator was not reinstalled prior to sampling.
UH66648	Lead 250	22	CF022 ROOM 6	PRE	Copper 250	60	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66662	Lead 250	10	CF022 ROOM 6	3S 1	Copper 250	60	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66676	Lead 250	8	CF022 ROOM 6	3S 2	Copper 250	50	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66649	Lead 250	3	CF023 ROOM 7	PRE	Copper 250	70	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66663	Lead 250	1	CF023 ROOM 7	3S 1	Copper 250	70	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66677	Lead 250	1	CF023 ROOM 7	3S 2	Copper 250	60	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66643	Lead 250	0	KC015 ROOM 1	PRE	Copper 250	200	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66657	Lead 250	0	KC015 ROOM 1	3S 1	Copper 250	140	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66671	Lead 250	0	KC015 ROOM 1	3S 2	Copper 250	110	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66644	Lead 250	0	KC016 ROOM 1	PRE	Copper 250	170	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66658	Lead 250	0	KC016 ROOM 1	3S 1	Copper 250	140	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66672	Lead 250	0	KC016 ROOM 1	3S 2	Copper 250	110	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66645	Lead 250	0	KC017 ROOM 2	PRE	Copper 250	130	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66659	Lead 250	0	KC017 ROOM 2	3S 1	Copper 250	80	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66673	Lead 250	0	KC017 ROOM 2	3S 2	Copper 250	70	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66647	Lead 250	0	KC019 ROOM 4	PRE	Copper 250	80	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present. Particulate sample was taken.
UH66661	Lead 250	2	KC019 ROOM 4	3S 1	Copper 250	80	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	
UH66675	Lead 250	3	KC019 ROOM 4	3S 2	Copper 250	80	OXLEY DRIVE	FLINT	48504	BROWNELL STEM ACADEMY	Aerator had particulate matter present.
UH66511	Lead 250	2	01CF001	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66533	Lead 250	12	01CF001	3S 1	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66555	Lead 250	26	01CF001	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66512	Lead 250	0	01CF003	PRE	Copper 250	120	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66534	Lead 250	0	01CF003	3S 1	Copper 250	100	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66556	Lead 250	0	01CF003	3S 2	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66515	Lead 250	1	01CF008	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66537	Lead 250	2	01CF008	3S 1	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66559	Lead 250	1	01CF008	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66517	Lead 250	7	01CF009 ROOM 154	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66539	Lead 250	68	01CF009 ROOM 154	3S 1	Copper 250	150	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66561	Lead 250	80	01CF009 ROOM 154	3S 2	Copper 250	110	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66518	Lead 250	5	01CF012 ROOM 153	PRE	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66540	Lead 250	6	01CF012 ROOM 153	3S 1	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66562	Lead 250	5	01CF012 ROOM 153	3S 2	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66523	Lead 250	64	01CF014 ROOM 152	PRE	Copper 250	250	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken. Water was discolored.
UH66545	Lead 250	11	01CF014 ROOM 152	3S 1	Copper 250	110	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66567	Lead 250	10	01CF014 ROOM 152	3S 2	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66524	Lead 250	28	01CF016 ROOM 151	PRE	Copper 250	110	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66546	Lead 250	30	01CF016 ROOM 151	3S 1	Copper 250	130	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66568	Lead 250	43	01CF016 ROOM 151	3S 2	Copper 250	100	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Low flow during sampling
UH66516	Lead 250	1	01CF018	PRE	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	No particulates observed, but used procedure to collect small particulates if present.
UH66538	Lead 250	2	01CF018	3S 1	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66560	Lead 250	0	01CF018	3S 2	Copper 250	60	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66527	Lead 250	3	01KC044 OFFICE KITCHEN	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66549	Lead 250	2	01KC044 OFFICE KITCHEN	3S 1	Copper 250	50	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66571	Lead 250	2	01KC044 OFFICE KITCHEN	3S 2	Copper 250	50	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66530	Lead 250	1	01KC048 ROOM 110	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66552	Lead 250	1	01KC048 ROOM 110	3S 1	Copper 250	50	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66574	Lead 250	0	01KC048 ROOM 110	3S 2	Copper 250	50	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66513	Lead 250	4	02CF019	PRE	Copper 250	100	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66535	Lead 250	4	02CF019	3S 1	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66557	Lead 250	2	02CF019	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66514	Lead 250	2	02CF021	PRE	Copper 250	100	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66536	Lead 250	1	02CF021	3S 1	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66558	Lead 250	1	02CF021	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66531	Lead 250	3	02CF024 ROOM 256	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66553	Lead 250	0	02CF024 ROOM 256	3S 1	Copper 250	0	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Faucet had been left on overnight.
UH66575	Lead 250	0	02CF024 ROOM 256	3S 2	Copper 250	0	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66532	Lead 250	1	02CF026 ROOM 259	PRE	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66554	Lead 250	1	02CF026 ROOM 259	3S 1	Copper 250	50	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66576	Lead 250	0	02CF026 ROOM 259	3S 5	Copper 250	0	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66519	Lead 250	3	02CF030 ROOM 254	PRE	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66541	Lead 250	4	02CF030 ROOM 254	3S 1	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66563	Lead 250	2	02CF030 ROOM 254	3S 2	Copper 250	60	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Sample was warm.
UH66520	Lead 250	6	02CF032 ROOM 253	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	No particulates observed, but used procedure to collect small particulates if present.
UH66542	Lead 250	6	02CF032 ROOM 253	3S 1	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66564	Lead 250	5	02CF032 ROOM 253	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66521	Lead 250	3	02CF034 ROOM 252	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66543	Lead 250	4	02CF034 ROOM 252	3S 1	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66565	Lead 250	4	02CF034 ROOM 252	3S 2	Copper 250	60	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Sample was warm.
UH66566	Lead 250	0	02CF035 ROOM 251	3S 2	Copper 250	60	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66522	Lead 250	2	02CF036 ROOM 251	PRE	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66544	Lead 250	5	02CF036 ROOM 251	3S 1	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66525	Lead 250	15	02CF039 ROOM 260	PRE	Copper 250	130	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66547	Lead 250	9	02CF039 ROOM 260	3S 1	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66569	Lead 250	10	02CF039 ROOM 260	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66526	Lead 250	22	02CF041 ROOM 262	PRE	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66548	Lead 250	56	02CF041 ROOM 262	3S 1	Copper 250	100	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66570	Lead 250	24	02CF041 ROOM 262	3S 2	Copper 250	80	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66528	Lead 250	29	02KC052 TEACHER'S LOUNGE	PRE	Copper 250	280	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present. Particulate sample was taken.
UH66550	Lead 250	4	02KC052 TEACHER'S LOUNGE	3S 1	Copper 250	140	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66572	Lead 250	3	02KC052 TEACHER'S LOUNGE	3S 2	Copper 250	120	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66529	Lead 250	5	03KC055 KITCHEN	PRE	Copper 250	130	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66551	Lead 250	0	03KC055 KITCHEN	3S 1	Copper 250	90	N SAGINAW ST	FLINT	48503	DOYLE RYDER	
UH66573	Lead 250	0	03KC055 KITCHEN	3S 2	Copper 250	70	N SAGINAW ST	FLINT	48503	DOYLE RYDER	Aerator had particulate matter present.
UH66266	Lead 250	1	01CF006 ROOM 47 DHHS	PRE	Copper 250	190	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	No filter unit present.
UH66295	Lead 250	1	01CF006 ROOM 47 DHHS	3S 1	Copper 250	170	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66324	Lead 250	1	01CF006 ROOM 47 DHHS	3S 2	Copper 250	150	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66269	Lead 250	0	01CF009 ROOM 39	PRE	Copper 250	80	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66298	Lead 250	0	01CF009 ROOM 39	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66327	Lead 250	0	01CF009 ROOM 39	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66272	Lead 250	2	01CF010 ROOM 39	PRE	Copper 250	130	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66301	Lead 250	2	01CF010 ROOM 39	3S 1	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66330	Lead 250	1	01CF010 ROOM 39	3S 2	Copper 250	120	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66268	Lead 250	0	01CF011 ROOM 38	PRE	Copper 250	230	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66297	Lead 250	0	01CF011 ROOM 38	3S 1	Copper 250	130	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66326	Lead 250	0	01CF011 ROOM 38	3S 2	Copper 250	120	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66271	Lead 250	1	01CF013 ROOM 36	PRE	Copper 250	190	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66300	Lead 250	0	01CF013 ROOM 36	3S 1	Copper 250	120	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66329	Lead 250	0	01CF013 ROOM 36	3S 2	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66274	Lead 250	0	01CF016 ROOM 34	PRE	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66303	Lead 250	0	01CF016 ROOM 34	3S 1	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66332	Lead 250	0	01CF016 ROOM 34	3S 2	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66275	Lead 250	0	01CF019 ROOM 32	PRE	Copper 250	120	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66304	Lead 250	0	01CF019 ROOM 32	3S 1	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66333	Lead 250	0	01CF019 ROOM 32	3S 2	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66276	Lead 250	23	01CF021 INSTRUCTIONAL MATERIAL CENTER	PRE	Copper 250	4910	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present. Water was yellow.
UH66305	Lead 250	0	01CF021 INSTRUCTIONAL MATERIAL CENTER	3S 1	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66334	Lead 250	1	01CF021 INSTRUCTIONAL MATERIAL CENTER	3S 2	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66282	Lead 250	0	01CF023 ROOM 64	PRE	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66311	Lead 250	0	01CF023 ROOM 64	3S 1	Copper 250	130	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66340	Lead 250	0	01CF023 ROOM 64	3S 2	Copper 250	80	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66281	Lead 250	2	01CF024 ROOM 70	PRE	Copper 250	150	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66310	Lead 250	1	01CF024 ROOM 70	3S 1	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66339	Lead 250	0	01CF024 ROOM 70	3S 2	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66283	Lead 250	0	01CF027 ROOM 62	PRE	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66312	Lead 250	0	01CF027 ROOM 62	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66341	Lead 250	1	01CF027 ROOM 62	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66284	Lead 250	0	01CF028 ROOM 72	PRE	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66313	Lead 250	0	01CF028 ROOM 72	3S 1	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66342	Lead 250	0	01CF028 ROOM 72	3S 2	Copper 250	50	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66285	Lead 250	3	01CF029 ROOM 61	PRE	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66314	Lead 250	0	01CF029 ROOM 61	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66343	Lead 250	0	01CF029 ROOM 61	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66286	Lead 250	0	01CF030 ROOM 59	PRE	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66315	Lead 250	0	01CF030 ROOM 59	3S 1	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66344	Lead 250	0	01CF030 ROOM 59	3S 2	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66287	Lead 250	0	01CF031 ROOM 75	PRE	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66316	Lead 250	1	01CF031 ROOM 75	3S 1	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66345	Lead 250	1	01CF031 ROOM 75	3S 2	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66317	Lead 250	0	01CF033 ROOM 58	3S 1	Copper 250	80	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66288	Lead 250	1	01CF033 ROOM 58	PRE	Copper 250	150	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66346	Lead 250	0	01CF033 ROOM 58	3S 2	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66289	Lead 250	0	01CF034 ROOM 76	PRE	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66318	Lead 250	0	01CF034 ROOM 76	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66347	Lead 250	0	01CF034 ROOM 76	3S 2	Copper 250	50	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66290	Lead 250	0	01CF035 ROOM 77	PRE	Copper 250	80	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66319	Lead 250	4	01CF035 ROOM 77	3S 1	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66348	Lead 250	1	01CF035 ROOM 77	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66291	Lead 250	0	01CF037 ROOM 78	PRE	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66320	Lead 250	0	01CF037 ROOM 78	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66349	Lead 250	0	01CF037 ROOM 78	3S 2	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66292	Lead 250	0	01CF039 ROOM 79	PRE	Copper 250	120	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66321	Lead 250	0	01CF039 ROOM 79	3S 1	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66350	Lead 250	0	01CF039 ROOM 79	3S 2	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66267	Lead 250	0	01KC004 KITCHEN	PRE	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66296	Lead 250	0	01KC004 KITCHEN	3S 1	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66325	Lead 250	0	01KC004 KITCHEN	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66270	Lead 250	0	01KC008 LOUNGE	PRE	Copper 250	70	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66299	Lead 250	3	01KC008 LOUNGE	3S 1	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66328	Lead 250	1	01KC008 LOUNGE	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66273	Lead 250	0	01KC015 MAIN OFFICE	PRE	Copper 250	320	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66302	Lead 250	1	01KC015 MAIN OFFICE	3S 1	Copper 250	280	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66331	Lead 250	1	01KC015 MAIN OFFICE	3S 2	Copper 250	280	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66293	Lead 250	3	01KC040 ROOM 53	PRE	Copper 250	150	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66322	Lead 250	0	01KC040 ROOM 53	3S 1	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66351	Lead 250	1	01KC040 ROOM 53	3S 2	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66294	Lead 250	1	01KC041 ROOM 53	PRE	Copper 250	170	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66323	Lead 250	0	01KC041 ROOM 53	3S 1	Copper 250	90	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66352	Lead 250	2	01KC041 ROOM 53	3S 2	Copper 250	110	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66280	Lead 250	3	01KC049 ROOM 13	PRE	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66309	Lead 250	4	01KC049 ROOM 13	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66338	Lead 250	8	01KC049 ROOM 13	3S 2	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66277	Lead 250	0	BCF042 ROOM 2 BASEMENT	PRE	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66306	Lead 250	0	BCF042 ROOM 2 BASEMENT	3S 1	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66335	Lead 250	0	BCF042 ROOM 2 BASEMENT	3S 2	Copper 250	0	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66278	Lead 250	3	BCF045 ROOM 3 BASEMENT	PRE	Copper 250	100	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66307	Lead 250	4	BCF045 ROOM 3 BASEMENT	3S 1	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66336	Lead 250	6	BCF045 ROOM 3 BASEMENT	3S 2	Copper 250	60	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	Aerator had particulate matter present.
UH66279	Lead 250	0	BCF048 ROOM 7 BASEMENT	PRE	Copper 250	220	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66308	Lead 250	0	BCF048 ROOM 7 BASEMENT	3S 1	Copper 250	130	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66337	Lead 250	0	BCF048 ROOM 7 BASEMENT	3S 2	Copper 250	140	UNIVERSITY AVE	FLINT	48504	DURANT TUURI MOTT	
UH66354	Lead 250	3	01CF004 ROOM 109	PRE	Copper 250	100	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66378	Lead 250	0	01CF004 ROOM 109	3S 1	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66402	Lead 250	0	01CF004 ROOM 109	3S 2	Copper 250	60	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66355	Lead 250	10	01CF006 CLINIC	PRE	Copper 250	420	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	No filter unit present.
UH66379	Lead 250	1	01CF006 CLINIC	3S 1	Copper 250	150	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	No filter unit present.
UH66403	Lead 250	5	01CF006 CLINIC	3S 2	Copper 250	140	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	No filter unit present.
UH66356	Lead 250	0	01CF008 ROOM 101	PRE	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66380	Lead 250	1	01CF008 ROOM 101	3S 1	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66404	Lead 250	1	01CF008 ROOM 101	3S 2	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66357	Lead 250	0	01CF010 ROOM 102	PRE	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66381	Lead 250	0	01CF010 ROOM 102	3S 1	Copper 250	60	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66405	Lead 250	0	01CF010 ROOM 102	3S 2	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66360	Lead 250	3	01CF012 ROOM 103	PRE	Copper 250	100	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66384	Lead 250	3	01CF012 ROOM 103	3S 1	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66408	Lead 250	1	01CF012 ROOM 103	3S 2	Copper 250	50	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66361	Lead 250	1	01CF014 ROOM 104	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66385	Lead 250	4	01CF014 ROOM 104	3S 1	Copper 250	100	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66409	Lead 250	2	01CF014 ROOM 104	3S 2	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66367	Lead 250	1	01CF016 ROOM 106	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66391	Lead 250	2	01CF016 ROOM 106	3S 1	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66415	Lead 250	24	01CF016 ROOM 106	3S 2	Copper 250	50	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66368	Lead 250	0	01CF018 ROOM 107	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66392	Lead 250	0	01CF018 ROOM 107	3S 1	Copper 250	60	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66416	Lead 250	1	01CF018 ROOM 107	3S 2	Copper 250	50	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66366	Lead 250	89	01CF046 LIBRARY MIC	PRE	Copper 250	90	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66390	Lead 250	91	01CF046 LIBRARY MIC	3S 1	Copper 250	200	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66414	Lead 250	279	01CF046 LIBRARY MIC	3S 2	Copper 250	390	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66353	Lead 250	0	01KC005 COMMUNITY ROOM	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66377	Lead 250	1	01KC005 COMMUNITY ROOM	3S 1	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66401	Lead 250	1	01KC005 COMMUNITY ROOM	3S 2	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66371	Lead 250	2	01KC019 ROOM 108	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66395	Lead 250	2	01KC019 ROOM 108	3S 1	Copper 250	60	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66419	Lead 250	3	01KC019 ROOM 108	3S 2	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66358	Lead 250	0	02CF021 ROOM 201	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66382	Lead 250	2	02CF021 ROOM 201	3S 1	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66406	Lead 250	2	02CF021 ROOM 201	3S 2	Copper 250	50	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66359	Lead 250	0	02CF022 ROOM 202	PRE	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66383	Lead 250	1	02CF022 ROOM 202	3S 1	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66407	Lead 250	1	02CF022 ROOM 202	3S 2	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66362	Lead 250	1	02CF024 ROOM 203	PRE	Copper 250	90	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66386	Lead 250	2	02CF024 ROOM 203	3S 1	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66410	Lead 250	2	02CF024 ROOM 203	3S 2	Copper 250	50	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66363	Lead 250	0	02CF026 ROOM 204	PRE	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66387	Lead 250	1	02CF026 ROOM 204	3S 1	Copper 250	60	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66411	Lead 250	0	02CF026 ROOM 204	3S 2	Copper 250	0	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66364	Lead 250	1	02CF028 ROOM 205	PRE	Copper 250	100	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66388	Lead 250	1	02CF028 ROOM 205	3S 1	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66412	Lead 250	1	02CF028 ROOM 205	3S 2	Copper 250	60	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66365	Lead 250	2	02CF030 ROOM 206	PRE	Copper 250	160	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66389	Lead 250	2	02CF030 ROOM 206	3S 1	Copper 250	120	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66413	Lead 250	2	02CF030 ROOM 206	3S 2	Copper 250	90	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66369	Lead 250	4	02CF032 ROOM 207	PRE	Copper 250	140	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66393	Lead 250	2	02CF032 ROOM 207	3S 1	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66417	Lead 250	1	02CF032 ROOM 207	3S 2	Copper 250	50	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66370	Lead 250	2	02CF034 ROOM 208	PRE	Copper 250	120	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66394	Lead 250	3	02CF034 ROOM 208	3S 1	Copper 250	140	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66418	Lead 250	3	02CF034 ROOM 208	3S 2	Copper 250	70	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66372	Lead 250	2	02CF036 ROOM 209	PRE	Copper 250	130	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66396	Lead 250	2	02CF036 ROOM 209	3S 1	Copper 250	100	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66420	Lead 250	3	02CF036 ROOM 209	3S 2	Copper 250	80	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66373	Lead 250	0	03KC040 UNIT 1 OUTBUILDING	PRE	Copper 250	190	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66397	Lead 250	0	03KC040 UNIT 1 OUTBUILDING	3S 1	Copper 250	160	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66421	Lead 250	0	03KC040 UNIT 1 OUTBUILDING	3S 2	Copper 250	150	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66374	Lead 250	0	03KC041 UNIT 1 OUTBUILDING	PRE	Copper 250	150	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	No filter unit present.
UH66398	Lead 250	3	03KC041 UNIT 1 OUTBUILDING	3S 1	Copper 250	210	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	No filter unit present.
UH66422	Lead 250	0	03KC041 UNIT 1 OUTBUILDING	3S 2	Copper 250	130	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	No filter unit present.
UH66375	Lead 250	0	04KC043 UNIT 2 OUTBUILDING	PRE	Copper 250	200	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66399	Lead 250	4	04KC043 UNIT 2 OUTBUILDING	3S 1	Copper 250	220	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66423	Lead 250	2	04KC043 UNIT 2 OUTBUILDING	3S 2	Copper 250	170	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66376	Lead 250	0	04KC044 UNIT 2 OUTBUILDING	PRE	Copper 250	180	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	Aerator had particulate matter present.
UH66400	Lead 250	1	04KC044 UNIT 2 OUTBUILDING	3S 1	Copper 250	150	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66424	Lead 250	0	04KC044 UNIT 2 OUTBUILDING	3S 2	Copper 250	150	PERSHING ST	FLINT	48503	EISENHOWER ELEMENTARY	
UH66207	Lead 250	2	CF004 ROOM 1	PRE	Copper 250	160	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66227	Lead 250	0	CF004 ROOM 1	3S 1	Copper 250	100	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66247	Lead 250	0	CF004 ROOM 1	3S 2	Copper 250	120	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66210	Lead 250	0	CF006A ROOM 2 FAUCET	PRE	Copper 250	120	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66230	Lead 250	0	CF006A ROOM 2 FAUCET	3S 1	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66250	Lead 250	0	CF006A ROOM 2 FAUCET	3S 2	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66209	Lead 250	0	CF007A ROOM 3 FAUCET	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66229	Lead 250	0	CF007A ROOM 3 FAUCET	3S 1	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66249	Lead 250	0	CF007A ROOM 3 FAUCET	3S 2	Copper 250	100	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66212	Lead 250	0	CF008A ROOM 4 FAUCET	PRE	Copper 250	130	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66232	Lead 250	0	CF008A ROOM 4 FAUCET	3S 1	Copper 250	130	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66252	Lead 250	0	CF008A ROOM 4 FAUCET	3S 2	Copper 250	140	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66211	Lead 250	0	CF009A ROOM 5 FAUCET	PRE	Copper 250	60	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66231	Lead 250	0	CF009A ROOM 5 FAUCET	3S 1	Copper 250	100	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66251	Lead 250	0	CF009A ROOM 5 FAUCET	3S 2	Copper 250	120	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66214	Lead 250	0	CF010A ROOM 6 FAUCET	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66234	Lead 250	0	CF010A ROOM 6 FAUCET	3S 1	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66254	Lead 250	0	CF010A ROOM 6 FAUCET	3S 2	Copper 250	120	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66213	Lead 250	0	CF011A ROOM 7 FAUCET	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present. Particulate sample was taken. No filter unit present.
UH66233	Lead 250	0	CF011A ROOM 7 FAUCET	3S 1	Copper 250	80	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66253	Lead 250	0	CF011A ROOM 7 FAUCET	3S 2	Copper 250	70	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	No filter unit present.
UH66215	Lead 250	0	CF012A ROOM 9 FAUCET	PRE	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66235	Lead 250	0	CF012A ROOM 9 FAUCET	3S 1	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66255	Lead 250	0	CF012A ROOM 9 FAUCET	3S 2	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66216	Lead 250	0	CF013 ROOM 10	PRE	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66236	Lead 250	0	CF013 ROOM 10	3S 1	Copper 250	220	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66256	Lead 250	3	CF013 ROOM 10	3S 2	Copper 250	230	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66217	Lead 250	3	CF015 ROOM 11	PRE	Copper 250	150	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66237	Lead 250	5	CF015 ROOM 11	3S 1	Copper 250	160	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66257	Lead 250	2	CF015 ROOM 11	3S 2	Copper 250	130	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66218	Lead 250	6	CF016 ROOM 11 FAUCET	PRE	Copper 250	330	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66238	Lead 250	0	CF016 ROOM 11 FAUCET	3S 1	Copper 250	240	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66258	Lead 250	0	CF016 ROOM 11 FAUCET	3S 2	Copper 250	210	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66219	Lead 250	0	CF017 ROOM 15	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66239	Lead 250	1	CF017 ROOM 15	3S 1	Copper 250	90	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66259	Lead 250	0	CF017 ROOM 15	3S 2	Copper 250	80	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66220	Lead 250	0	CF020 ROOM 17	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66240	Lead 250	0	CF020 ROOM 17	3S 1	Copper 250	80	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66260	Lead 250	0	CF020 ROOM 17	3S 2	Copper 250	70	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66221	Lead 250	0	CF022 ROOM 12	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66241	Lead 250	0	CF022 ROOM 12	3S 1	Copper 250	70	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66261	Lead 250	0	CF022 ROOM 12	3S 2	Copper 250	60	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66222	Lead 250	0	CF024 ROOM 19	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66242	Lead 250	0	CF024 ROOM 19	3S 1	Copper 250	90	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66262	Lead 250	0	CF024 ROOM 19	3S 2	Copper 250	70	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66223	Lead 250	0	CF025 ROOM 14	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66243	Lead 250	0	CF025 ROOM 14	3S 1	Copper 250	70	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66263	Lead 250	0	CF025 ROOM 14	3S 2	Copper 250	60	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66224	Lead 250	0	CF027 ROOM 21	PRE	Copper 250	0	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66244	Lead 250	0	CF027 ROOM 21	3S 1	Copper 250	70	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66264	Lead 250	0	CF027 ROOM 21	3S 2	Copper 250	60	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66206	Lead 250	85	CF029 DHHS OFFICE	PRE	Copper 250	1910	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66226	Lead 250	2	CF029 DHHS OFFICE	3S 1	Copper 250	170	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66246	Lead 250	2	CF029 DHHS OFFICE	3S 2	Copper 250	170	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66225	Lead 250	0	CF030 RAINBOW PRE K	PRE	Copper 250	150	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66245	Lead 250	0	CF030 RAINBOW PRE K	3S 1	Copper 250	120	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66265	Lead 250	0	CF030 RAINBOW PRE K	3S 2	Copper 250	110	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66208	Lead 250	0	KC003 COMMUNITY ROOM	PRE	Copper 250	120	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66228	Lead 250	0	KC003 COMMUNITY ROOM	3S 1	Copper 250	90	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	
UH66248	Lead 250	0	KC003 COMMUNITY ROOM	3S 2	Copper 250	100	OGEMA AVE	FLINT	48507	FREEMAN ELEMENTARY	Aerator had particulate matter present.
UH66577	Lead 250	0	01CF013 ROOM B110	PRE	Copper 250	200	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66596	Lead 250	0	01CF013 ROOM B110	3S 1	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66616	Lead 250	0	01CF013 ROOM B110	3S 2	Copper 250	190	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66580	Lead 250	0	01CF015 ROOM B109	PRE	Copper 250	520	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66599	Lead 250	0	01CF015 ROOM B109	3S 1	Copper 250	220	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66619	Lead 250	0	01CF015 ROOM B109	3S 2	Copper 250	250	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66583	Lead 250	0	01CF020 ROOM B102	PRE	Copper 250	180	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66602	Lead 250	0	01CF020 ROOM B102	3S 1	Copper 250	190	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66622	Lead 250	0	01CF020 ROOM B102	3S 2	Copper 250	180	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66586	Lead 250	0	01CF024 ROOM B105	PRE	Copper 250	230	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66605	Lead 250	0	01CF024 ROOM B105	3S 1	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66625	Lead 250	0	01CF024 ROOM B105	3S 2	Copper 250	200	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66589	Lead 250	1	01CF028 ROOM B114	PRE	Copper 250	150	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66608	Lead 250	7	01CF028 ROOM B114	3S 1	Copper 250	130	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66628	Lead 250	3	01CF028 ROOM B114	3S 2	Copper 250	110	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66592	Lead 250	2	01CF032 COMMUNITY ROOM	PRE	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66611	Lead 250	15	01CF032 COMMUNITY ROOM	3S 1	Copper 250	170	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66631	Lead 250	3	01CF032 COMMUNITY ROOM	3S 2	Copper 250	110	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66578	Lead 250	0	01KC010 ROOM B110	PRE	Copper 250	240	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66597	Lead 250	0	01KC010 ROOM B110	3S 1	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66617	Lead 250	0	01KC010 ROOM B110	3S 2	Copper 250	190	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66579	Lead 250	0	01KC011 ROOM B110	PRE	Copper 250	220	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66598	Lead 250	0	01KC011 ROOM B110	3S 1	Copper 250	170	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66618	Lead 250	0	01KC011 ROOM B110	3S 2	Copper 250	220	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66581	Lead 250	0	01KC016 ROOM B109	PRE	Copper 250	320	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66600	Lead 250	0	01KC016 ROOM B109	3S 1	Copper 250	320	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66620	Lead 250	0	01KC016 ROOM B109	3S 2	Copper 250	300	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66582	Lead 250	2	01KC017 ROOM B109	PRE	Copper 250	530	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66601	Lead 250	0	01KC017 ROOM B109	3S 1	Copper 250	280	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66621	Lead 250	0	01KC017 ROOM B109	3S 2	Copper 250	300	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66584	Lead 250	0	01KC021 ROOM B102	PRE	Copper 250	230	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66603	Lead 250	0	01KC021 ROOM B102	3S 1	Copper 250	170	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66623	Lead 250	0	01KC021 ROOM B102	3S 2	Copper 250	200	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66585	Lead 250	0	01KC022 ROOM B102	PRE	Copper 250	240	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66604	Lead 250	0	01KC022 ROOM B102	3S 1	Copper 250	190	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66624	Lead 250	0	01KC022 ROOM B102	3S 2	Copper 250	220	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66587	Lead 250	0	01KC025 ROOM B105	PRE	Copper 250	380	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66606	Lead 250	0	01KC025 ROOM B105	3S 1	Copper 250	270	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66626	Lead 250	0	01KC025 ROOM B105	3S 2	Copper 250	250	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66588	Lead 250	0	01KC026 ROOM B105	PRE	Copper 250	300	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66607	Lead 250	1	01KC026 ROOM B105	3S 1	Copper 250	280	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66627	Lead 250	2	01KC026 ROOM B105	3S 2	Copper 250	280	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66590	Lead 250	0	01KC029 ROOM B114	PRE	Copper 250	190	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66609	Lead 250	0	01KC029 ROOM B114	3S 1	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66629	Lead 250	0	01KC029 ROOM B114	3S 2	Copper 250	130	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66591	Lead 250	6	01KC030 ROOM B114	PRE	Copper 250	390	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66610	Lead 250	0	01KC030 ROOM B114	3S 1	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66630	Lead 250	1	01KC030 ROOM B114	3S 2	Copper 250	160	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66593	Lead 250	0	01KC033 COMMUNITY ROOM	PRE	Copper 250	340	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66612	Lead 250	1	01KC033 COMMUNITY ROOM	3S 1	Copper 250	250	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66632	Lead 250	2	01KC033 COMMUNITY ROOM	3S 2	Copper 250	240	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66594	Lead 250	0	01KC034 COMMUNITY ROOM	PRE	Copper 250	290	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66613	Lead 250	2	01KC034 COMMUNITY ROOM	3S 1	Copper 250	280	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	

Flint Community Schools  
Round 2, Weeks 1 2  
2/16/18

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66633	Lead 250	2	01KC034 COMMUNITY ROOM	3S 2	Copper 250	270	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66614	Lead 250	8	01KC036 MAIN OFFICE	3S 1	Copper 250	110	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66634	Lead 250	12	01KC036 MAIN OFFICE	3S 2	Copper 250	70	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66595	Lead 250	14	01KC037 SUPPLY ROOM	PRE	Copper 250	110	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66615	Lead 250	5	01KC037 SUPPLY ROOM	3S 1	Copper 250	70	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	
UH66635	Lead 250	4	01KC037 SUPPLY ROOM	3S 2	Copper 250	70	OXLEY DRIVE	FLINT	48504	HOLMES STEM ACADEMY	Aerator had particulate matter present.
UH66145	Lead 250	2	01CF007 ROOM 101	PRE	Copper 250	150	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66166	Lead 250	2	01CF007 ROOM 101	3S 1	Copper 250	110	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66187	Lead 250	2	01CF007 ROOM 101	3S 2	Copper 250	90	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66146	Lead 250	0	01CF010 ROOM 100	PRE	Copper 250	130	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66167	Lead 250	0	01CF010 ROOM 100	3S 1	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66188	Lead 250	1	01CF010 ROOM 100	3S 2	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66147	Lead 250	23	01CF011 LIBRARY	PRE	Copper 250	250	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present. Particulate sample was taken.
UH66168	Lead 250	5	01CF011 LIBRARY	3S 1	Copper 250	140	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66189	Lead 250	5	01CF011 LIBRARY	3S 2	Copper 250	100	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66148	Lead 250	0	01CF013 ROOM 105	PRE	Copper 250	110	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66169	Lead 250	0	01CF013 ROOM 105	3S 1	Copper 250	90	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66190	Lead 250	2	01CF013 ROOM 105	3S 2	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66149	Lead 250	1	01CF016 ROOM 104	PRE	Copper 250	150	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66170	Lead 250	22	01CF016 ROOM 104	3S 1	Copper 250	120	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66191	Lead 250	3	01CF016 ROOM 104	3S 2	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66150	Lead 250	6	01CF018 ROOM 106	PRE	Copper 250	130	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66171	Lead 250	2	01CF018 ROOM 106	3S 1	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66192	Lead 250	2	01CF018 ROOM 106	3S 2	Copper 250	60	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66151	Lead 250	1	01CF019 ROOM 107	PRE	Copper 250	110	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66172	Lead 250	1	01CF019 ROOM 107	3S 1	Copper 250	90	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66193	Lead 250	1	01CF019 ROOM 107	3S 2	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66152	Lead 250	6	01CF022 ROOM 109	PRE	Copper 250	160	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66173	Lead 250	3	01CF022 ROOM 109	3S 1	Copper 250	110	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66194	Lead 250	3	01CF022 ROOM 109	3S 2	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66153	Lead 250	10	01CF024 ROOM 108	PRE	Copper 250	240	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66174	Lead 250	2	01CF024 ROOM 108	3S 1	Copper 250	100	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66195	Lead 250	1	01CF024 ROOM 108	3S 2	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66154	Lead 250	2	01CF025 ROOM 110	PRE	Copper 250	120	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66175	Lead 250	1	01CF025 ROOM 110	3S 1	Copper 250	90	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66196	Lead 250	1	01CF025 ROOM 110	3S 2	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66155	Lead 250	5	01CF027 COPY ROOM	PRE	Copper 250	210	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66176	Lead 250	3	01CF027 COPY ROOM	3S 1	Copper 250	130	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66197	Lead 250	2	01CF027 COPY ROOM	3S 2	Copper 250	130	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66156	Lead 250	8	01CF028 ROOM 112	PRE	Copper 250	200	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66177	Lead 250	4	01CF028 ROOM 112	3S 1	Copper 250	190	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66198	Lead 250	1	01CF028 ROOM 112	3S 2	Copper 250	100	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66157	Lead 250	25	01CF031 ROOM 112	PRE	Copper 250	230	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66178	Lead 250	22	01CF031 ROOM 112	3S 1	Copper 250	150	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66199	Lead 250	3	01CF031 ROOM 112	3S 2	Copper 250	130	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66158	Lead 250	0	01CF032 ROOM 113	PRE	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66179	Lead 250	0	01CF032 ROOM 113	3S 1	Copper 250	0	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66200	Lead 250	0	01CF032 ROOM 113	3S 2	Copper 250	0	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66159	Lead 250	1	01CF035 ROOM 115	PRE	Copper 250	170	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66180	Lead 250	0	01CF035 ROOM 115	3S 1	Copper 250	100	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66201	Lead 250	2	01CF035 ROOM 115	3S 2	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66160	Lead 250	0	01CF037 ROOM 114	PRE	Copper 250	100	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66181	Lead 250	2	01CF037 ROOM 114	3S 1	Copper 250	90	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66202	Lead 250	2	01CF037 ROOM 114	3S 2	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66161	Lead 250	3	01CF039 ROOM 116	PRE	Copper 250	100	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present. Particulate sample was taken.
UH66182	Lead 250	11	01CF039 ROOM 116	3S 1	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66203	Lead 250	13	01CF039 ROOM 116	3S 2	Copper 250	50	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66144	Lead 250	22	01KC006 LOUNGE	PRE	Copper 250	390	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present. Particulate sample was taken.
UH66165	Lead 250	3	01KC006 LOUNGE	3S 1	Copper 250	80	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66186	Lead 250	3	01KC006 LOUNGE	3S 2	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66143	Lead 250	2	01KC040 KITCHEN	PRE	Copper 250	170	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66164	Lead 250	3	01KC040 KITCHEN	3S 1	Copper 250	60	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66185	Lead 250	2	01KC040 KITCHEN	3S 2	Copper 250	60	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66162	Lead 250	2	02KC001 DHHS OFFICE	PRE	Copper 250	0	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present. Faucet had been left on overnight to prevent pipes from freezing.
UH66183	Lead 250	24	02KC001 DHHS OFFICE	3S 1	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66204	Lead 250	0	02KC001 DHHS OFFICE	3S 2	Copper 250	70	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66163	Lead 250	5	02KC002 DHHS OFFICE	PRE	Copper 250	150	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present. Particulate sample was taken.
UH66184	Lead 250	5	02KC002 DHHS OFFICE	3S 1	Copper 250	190	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	
UH66205	Lead 250	3	02KC002 DHHS OFFICE	3S 2	Copper 250	200	CRESTBROOK LN	FLINT	48507	NEITHERCUT ELEMENTARY	Aerator had particulate matter present.
UH66678	Lead 250	0	01CF003 ROOM 109	PRE	Copper 250	150	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66696	Lead 250	2	01CF003 ROOM 109	3S 1	Copper 250	210	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66714	Lead 250	3	01CF003 ROOM 109	3S 2	Copper 250	200	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66679	Lead 250	0	01CF005 ROOM 110	PRE	Copper 250	150	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66697	Lead 250	1	01CF005 ROOM 110	3S 1	Copper 250	120	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66715	Lead 250	0	01CF005 ROOM 110	3S 2	Copper 250	100	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66680	Lead 250	0	01CF007 ROOM 108	PRE	Copper 250	170	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
UH66698	Lead 250	0	01CF007 ROOM 108	3S 1	Copper 250	130	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66716	Lead 250	0	01CF007 ROOM 108	3S 2	Copper 250	100	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66681	Lead 250	1	01CF010 ROOM 111	PRE	Copper 250	210	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66699	Lead 250	0	01CF010 ROOM 111	3S 1	Copper 250	170	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66717	Lead 250	2	01CF010 ROOM 111	3S 2	Copper 250	130	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66682	Lead 250	1	01CF011 ROOM 107	PRE	Copper 250	140	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66700	Lead 250	1	01CF011 ROOM 107	3S 1	Copper 250	130	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66718	Lead 250	1	01CF011 ROOM 107	3S 2	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66683	Lead 250	0	01CF013 ROOM 100	PRE	Copper 250	80	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66701	Lead 250	1	01CF013 ROOM 100	3S 1	Copper 250	70	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66719	Lead 250	0	01CF013 ROOM 100	3S 2	Copper 250	60	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66684	Lead 250	0	01CF014 ROOM 100	PRE	Copper 250	70	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	No filter unit present. Could not remove aerator from the faucet itself.
UH66702	Lead 250	0	01CF014 ROOM 100	3S 1	Copper 250	70	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66720	Lead 250	0	01CF014 ROOM 100	3S 2	Copper 250	60	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66686	Lead 250	0	01CF018 ROOM 301	PRE	Copper 250	90	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66704	Lead 250	1	01CF018 ROOM 301	3S 1	Copper 250	70	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66722	Lead 250	0	01CF018 ROOM 301	3S 2	Copper 250	50	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66687	Lead 250	2	01CF020 ROOM 302	PRE	Copper 250	200	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66705	Lead 250	0	01CF020 ROOM 302	3S 1	Copper 250	130	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66723	Lead 250	0	01CF020 ROOM 302	3S 2	Copper 250	130	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66688	Lead 250	2	01CF021 ROOM 306	PRE	Copper 250	140	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66706	Lead 250	2	01CF021 ROOM 306	3S 1	Copper 250	100	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66724	Lead 250	1	01CF021 ROOM 306	3S 2	Copper 250	80	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66689	Lead 250	0	01CF023 ROOM 312	PRE	Copper 250	120	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66707	Lead 250	0	01CF023 ROOM 312	3S 1	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66725	Lead 250	0	01CF023 ROOM 312	3S 2	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66690	Lead 250	2	01CF026 ROOM 307	PRE	Copper 250	270	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66708	Lead 250	3	01CF026 ROOM 307	3S 1	Copper 250	230	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66726	Lead 250	3	01CF026 ROOM 307	3S 2	Copper 250	160	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66691	Lead 250	0	01CF028 ROOM 311	PRE	Copper 250	160	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66709	Lead 250	4	01CF028 ROOM 311	3S 1	Copper 250	100	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66727	Lead 250	3	01CF028 ROOM 311	3S 2	Copper 250	80	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66692	Lead 250	3	01CF030 ROOM 308	PRE	Copper 250	130	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66710	Lead 250	5	01CF030 ROOM 308	3S 1	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66728	Lead 250	5	01CF030 ROOM 308	3S 2	Copper 250	100	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66693	Lead 250	2	01CF032 ROOM 310	PRE	Copper 250	350	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66711	Lead 250	0	01CF032 ROOM 310	3S 1	Copper 250	190	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66729	Lead 250	0	01CF032 ROOM 310	3S 2	Copper 250	120	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66695	Lead 250	1	01CF035 ROOM 112	PRE	Copper 250	140	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66713	Lead 250	0	01CF035 ROOM 112	3S 1	Copper 250	160	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66731	Lead 250	0	01CF035 ROOM 112	3S 2	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66685	Lead 250	0	01KC016 TEACHERS LOUNGE	PRE	Copper 250	170	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66703	Lead 250	0	01KC016 TEACHERS LOUNGE	3S 1	Copper 250	160	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66721	Lead 250	0	01KC016 TEACHERS LOUNGE	3S 2	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66694	Lead 250	1	02KC033 TEMP ROOM BY PARKING	PRE	Copper 250	310	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	Aerator had particulate matter present.
UH66712	Lead 250	0	02KC033 TEMP ROOM BY PARKING	3S 1	Copper 250	110	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66730	Lead 250	0	02KC033 TEMP ROOM BY PARKING	3S 2	Copper 250	140	W VERNON DR	FLINT	48503	PIERCE ELEMENTARY	
UH66440	Lead 250	0	01BF031 ROOM 3	PRE	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66468	Lead 250	0	01BF031 ROOM 3	3S 1	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66497	Lead 250	0	01BF031 ROOM 3	3S 2	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66425	Lead 250	0	01CF001 ROOM 22	PRE	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present. Sample was warm.
UH66453	Lead 250	1	01CF001 ROOM 22	3S 1	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66482	Lead 250	0	01CF001 ROOM 22	3S 2	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66426	Lead 250	11	01CF003 ROOM 17	PRE	Copper 250	1160	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present. Sample was warm.
UH66454	Lead 250	0	01CF003 ROOM 17	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66483	Lead 250	0	01CF003 ROOM 17	3S 2	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66427	Lead 250	0	01CF004 ROOM 20	PRE	Copper 250	100	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66455	Lead 250	3	01CF004 ROOM 20	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66484	Lead 250	1	01CF004 ROOM 20	3S 2	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66428	Lead 250	0	01CF007 ROOM 15	PRE	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66456	Lead 250	3	01CF007 ROOM 15	3S 1	Copper 250	300	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66485	Lead 250	1	01CF007 ROOM 15	3S 2	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66431	Lead 250	2	01CF013 ROOM 12	PRE	Copper 250	190	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66459	Lead 250	0	01CF013 ROOM 12	3S 1	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66488	Lead 250	0	01CF013 ROOM 12	3S 2	Copper 250	60	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66432	Lead 250	5	01CF014 ROOM 9	PRE	Copper 250	170	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66460	Lead 250	2	01CF014 ROOM 9	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66489	Lead 250	0	01CF014 ROOM 9	3S 2	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66433	Lead 250	26	01CF015 ROOM 10	PRE	Copper 250	130	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66461	Lead 250	2	01CF015 ROOM 10	3S 1	Copper 250	110	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66490	Lead 250	1	01CF015 ROOM 10	3S 2	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66434	Lead 250	2	01CF017 ROOM 8	PRE	Copper 250	180	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66462	Lead 250	2	01CF017 ROOM 8	3S 1	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
UH66491	Lead 250	1	01CF017 ROOM 8	3S 2	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
UH66435	Lead 250	0	01CF019 ROOM 7	PRE	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present. Sample was warm.
UH66463	Lead 250	1	01CF019 ROOM 7	3S 1	Copper 250	110	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	

Sample Number	Lead	Lead (PPB)	Sample Description	Site Code	Copper	Copper (PPB)	Street Name	City	Zip	School	Comments
LH66492	Lead 250	2	01CF019 ROOM 7	3S 2	Copper 250	100	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66436	Lead 250	0	01CF021 ROOM 6	PRE	Copper 250	190	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66464	Lead 250	2	01CF021 ROOM 6	3S 1	Copper 250	240	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66493	Lead 250	1	01CF021 ROOM 6	3S 2	Copper 250	230	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66437	Lead 250	0	01CF024 ROOM 5	PRE	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66465	Lead 250	0	01CF024 ROOM 5	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66494	Lead 250	0	01CF024 ROOM 5	3S 2	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66441	Lead 250	2	01CF027 ROOM 4	PRE	Copper 250	150	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66469	Lead 250	2	01CF027 ROOM 4	3S 1	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66498	Lead 250	2	01CF027 ROOM 4	3S 2	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66442	Lead 250	13	01CF029 ROOM 3	PRE	Copper 250	300	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66470	Lead 250	6	01CF029 ROOM 3	3S 1	Copper 250	190	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66499	Lead 250	5	01CF029 ROOM 3	3S 2	Copper 250	190	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66443	Lead 250	0	01CF033 ROOM 1A	PRE	Copper 250	180	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66471	Lead 250	0	01CF033 ROOM 1A	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66500	Lead 250	0	01CF033 ROOM 1A	3S 2	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66444	Lead 250	0	01CF035 ROOM 2A	PRE	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66472	Lead 250	1	01CF035 ROOM 2A	3S 1	Copper 250	130	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66501	Lead 250	1	01CF035 ROOM 2A	3S 2	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66445	Lead 250	1	01CF037 ROOM 38	PRE	Copper 250	130	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66473	Lead 250	1	01CF037 ROOM 38	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66502	Lead 250	1	01CF037 ROOM 38	3S 2	Copper 250	70	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66446	Lead 250	1	01CF039 ROOM 39	PRE	Copper 250	130	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66474	Lead 250	8	01CF039 ROOM 39	3S 1	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66503	Lead 250	3	01CF039 ROOM 39	3S 2	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66447	Lead 250	0	01CF041 ROOM 36	PRE	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66475	Lead 250	0	01CF041 ROOM 36	3S 1	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66504	Lead 250	0	01CF041 ROOM 36	3S 2	Copper 250	60	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66476	Lead 250	4	01CF043 ROOM 37	3S 1	Copper 250	160	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66505	Lead 250	1	01CF043 ROOM 37	3S 2	Copper 250	160	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66448	Lead 250	0	01CF045 ROOM 34	PRE	Copper 250	130	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66477	Lead 250	0	01CF045 ROOM 34	3S 1	Copper 250	100	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66506	Lead 250	0	01CF045 ROOM 34	3S 2	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66449	Lead 250	4	01CF047 ROOM 35	PRE	Copper 250	250	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66478	Lead 250	4	01CF047 ROOM 35	3S 1	Copper 250	180	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66507	Lead 250	5	01CF047 ROOM 35	3S 2	Copper 250	160	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66450	Lead 250	0	01CF050 ROOM 33	PRE	Copper 250	180	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66479	Lead 250	2	01CF050 ROOM 33	3S 1	Copper 250	200	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66508	Lead 250	1	01CF050 ROOM 33	3S 2	Copper 250	140	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66451	Lead 250	1	01CF052 ROOM 31	PRE	Copper 250	180	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66480	Lead 250	1	01CF052 ROOM 31	3S 1	Copper 250	160	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66509	Lead 250	1	01CF052 ROOM 31	3S 2	Copper 250	170	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66429	Lead 250	0	01KC008 COMMUNITY ROOM	PRE	Copper 250	100	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66457	Lead 250	2	01KC008 COMMUNITY ROOM	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66486	Lead 250	2	01KC008 COMMUNITY ROOM	3S 2	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66430	Lead 250	20	01KC009 DHHS	PRE	Copper 250	530	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66458	Lead 250	1	01KC009 DHHS	3S 1	Copper 250	130	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66487	Lead 250	2	01KC009 DHHS	3S 2	Copper 250	120	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66438	Lead 250	0	01KC025 ROOM 5	PRE	Copper 250	280	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66466	Lead 250	0	01KC025 ROOM 5	3S 1	Copper 250	200	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66495	Lead 250	0	01KC025 ROOM 5	3S 2	Copper 250	180	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66439	Lead 250	1	01KC026 ROOM 5	PRE	Copper 250	240	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66467	Lead 250	1	01KC026 ROOM 5	3S 1	Copper 250	220	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66496	Lead 250	0	01KC026 ROOM 5	3S 2	Copper 250	160	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66452	Lead 250	0	02KC056 OUT UNIT 2	PRE	Copper 250	80	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	Aerator had particulate matter present.
LH66481	Lead 250	0	02KC056 OUT UNIT 2	3S 1	Copper 250	90	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	
LH66510	Lead 250	0	02KC056 OUT UNIT 2	3S 2	Copper 250	170	N AVERILL AVE	FLINT	48506	POTTER ELEMENTARY	