Approved Customer Programming Software & Recommended Firmware Versions

January 2026 Update

MPSCS Radio Programming Unit *(RPU)* will soon begin delivering radio programming, which requires the use of updated Customer Programming Software *(CPS)* and firmware, depending on your model subscriber radios. Please review the list below for details related to your specific model requirements.

New programming templates, using several new software versions noted below, will begin being delivered to customers effective **Monday, January 12th, 2026.**

- **Motorola Solutions ***UPDATED January 2026****
  - **APX series**
    - **CPS = APX R36.00.02**
    - Firmware for standard APX models *(includes N30, N50)* = R36.61.00
    - Firmware for APX N70 models = R06.61.00
    - Firmware for APX Next models = R09.61.00
    - **Firmware for APX 6000 / SRX 2200 *(AN),* APX 7000 & APX 7500 models = R36.61.00**
      *This is the final version of firmware for end of support (AN) models as noted in the APX release notes.

      *R36.61.00 firmware is required to correct issues related to software-based ADP encryption that have been reported; all APX models are recommended to upgrade to this version at the earliest possible timeframe.

  - **XTS/XTL series**
    - **CPS = ASTRO25 R20.01.00**
    - Firmware for XTS portables = R20.50.10
    - Firmware for XTL mobiles = R20.50.10

- **JVCKenwood / EF Johnson ***UPDATED January 2026****
  - **Viking series**
    - **CPS = Armada v1.46.16.183**
    - Firmware for VPx000 portable models = v8.46.18.93
    - Firmware for VMx000 mobile models = v8.46.18.74
    - Firmware for VP8000 portable model = v8.46.18.87
    - Firmware for VM8000 mobile model = v8.46.18.80
    - Firmware for VPx00 portable and VMx00 mobile models = v8.30.16.57

  - **NX/TK series *(includes NX-5400, NX-5900, TK-5430, TK-5930)* ***UPDATED January 2026****
    - **CPS = KPG-D1N v5.30**
    - Firmware = v5.31

- **L3Harris ***UPDATED January 2026****
  - **XL/XG series**
    - **CPS = RPM2 R22A0094**
    - Firmware for XL series = R22B05.0286
    - Firmware for XG-15P, XG-25P, XG-75P, XG-75M, XG-100P, & XG-100M models = R06T02
    - Firmware for XG-25M models = R06U02

- **Tait ***UPDATED January 2026****
  - **CPS = P25 Terminals Programming Application v3.6.6.32**
  - Firmware for TP9400, TM9400, TP9600, & TP9800 models = v3.06.13
    *TP9100 / TM9100 models are no longer supported for programming

- **BK Technologies**
  - **CPS = RES v5.11.0**
  - Firmware for BKR-9000 models = v5.11.0
  - Firmware for KNG-P800, KNG2-P800, & KNG-M800 models = v5.7.12

- **Unication**
  - **PPS = v0.4.0.41**
  - Firmware for G4 / G5 models = v2.02

If there are any questions, comments, or concerns, or you require assistance related to your subscriber radio programming, contact the MPSCS Radio Programming Unit.

Phone: 517-333-2720
Email: MPSCS-RPU@michigan.gov