

MSP/MCD DECAL APPLICATION POLICY FOR SCHOOL BUSES

CHASSIS, FRAME AND UNIBODY

Frame, Cross Members, Outriggers, Body Support and Bumpers: General

YELLOW: Missing or loose bolts on motor mount cross members sufficient to allow cross member to shift or move.

RED: Any crack 1½ inch or longer in frame side rail which is directed toward the bottom flange. CVSA

RED: Any crack extending from the frame side rail web around the radius and into the bottom flange. CVSA

RED: Any cracked, loose, sagging or broken frame side rail. *NST-SBI 10.61*

RED: Any obvious bend or damage resulting from a collision. *NST-SBI 10.61*

RED: Any worn or loose mounting hole. *NST-SBI 10.61*

RED: Any cross member, outrigger or other structural support cracked, missing or deformed. *NST-SBI 10.62*

RED: Any missing, broken, shifted or corroded part that would affect the safe operation of the vehicle. *NST-SBI 10.63*

RED: Any bumper missing or not secured. *NST-SBI 10.64*