

## **MSP/MCD DECAL APPLICATION POLICY FOR SCHOOL BUSES**

### **MISCELLANEOUS EQUIPMENT**

#### **Add on Equipment:**

**RED:** Any add on equipment that presents a safety hazard to pupils, drivers, or motorists during the loading or unloading of pupils.

#### **First Aid Kits, Fusees, Reflectors and Fire Extinguisher**

**YELLOW:** First aid kit is missing, or not securely fastened.

**YELLOW:** Flares, fusees, or reflectors missing, inaccessible or not secured in drivers area.

**RED:** Any required fire extinguisher which is missing, not of proper type, size, not fully charged, has no pressure gauge, is not secured or is not accessible to the driver. *MCLA 257.681, 257.1825, NST-SBI 12.11*

#### **Heaters**

**YELLOW:** Heater core, heater hoses, or heater fittings are leaking.

**RED:** Heater missing or inoperative (winter months only).

**RED:** Any fuel leaks.

**RED:** Any heater fuel, electric, or hot water that creates a safety hazard to the occupants of the vehicle.

#### **Hood**

**RED:** All hood latches are broken.

**RED:** Safety catch is broken on forward facing hood.

#### **State Issued Decal(s)/Registration**

**RED:** Any vehicle for sale that displays any MSP decal.

**RED:** No valid registration, or proof of insurance.

#### **Radio Speakers Passenger Compartment:**

**RED:** Any active radio speaker, except two way communication devices, closer than 3 seat positions behind the driver.

**RED:** Any new vehicle delivered into the state after 8/15/06 with radio speakers installed closer than 3 seat positions behind the driver.

#### **Undercoating**

**RED:** New buses only, if vehicle has not been undercoated as required. *MCLA 257.1811 (4)*