





**Photograph No. 9: View of basement floor with open pipe visible through concrete slab**




**Photograph No. 10: View of utility room in basement containing boiler.**




**Photograph No. 11: View of water damage in basement.**



**Photograph No. 12: View of water lines on basement walls.**



**Photograph No. 13: View of office area**



**Photograph No. 14: View of Squad Room**



**Photograph No. 15: View of paint peeling from wall in office area.**




**Photograph No. 16: View of paint peeling from wall in office area.**



**Photograph No. 17: View of utility tub and pipe insulation.**



**Photograph No 18: View of treatment system vault. Metal shed is visible in left foreground that contains groundwater treatment system.**



**Photograph No 19: View of interior of metal shed showing air stripper groundwater treatment system.**



**Photograph No. 20: View of flush-mounted monitoring well cover in parking area.**