

This Standard is Being Changed Due to the ARC Report to ORR

STANDARD	RULE NUMBERS	MIOsha IMPLEMENTATION STRATEGY
<p>CS Part 32 Aerial Work Platforms</p> <p>Effective September 24, 2013</p> <p><u>Strike-Bold</u></p>	R 408.43203	The hazards associated with the rescinded rules will be addressed by Rules 114(2) and 115(2).
	R 408.43205	The hazards associated with the rescinded rules will be addressed by Rules 3205(1) and 123.
	R 408.43206	The hazards associated with the rescinded rules will be addressed by Rules 3205(1), 114(2) and 115(2).
	R 408.43208	The hazards associated with the rescinded rules will be addressed by Rules 114(2) and 115(2).
	R 408.43212	The hazards associated with the rescinded rule will be addressed by Rule 114(2).
	R 408.43214	The hazards associated with the rescinded rule will be addressed by 1926.502.
	R 408.43216	The hazards associated with the rescinded rules will be addressed by Rule 3216(1).
<p>* Only pertains to ORR recommendation changes - not work done by the advisory committee.</p>		