

**Design Services for the final design of the bridge replacement carrying E&SL over  
US-2 near city of Escanaba  
REQ #1656 QA1  
JN 115866  
12/30/2014**

- Question #1 – The MDOT RFP does not have the “Understanding of Service” box checked. Can you explain why?
- Answer #1 – The selection criteria is sufficient for the MDOT as posted.