

**Design Services for cold milling and HMA overlay with shoulder widening, guardrail,
drainage improvements in the City of Holland REQ#698 QA2
8/9/2011**

Question 1: The Hydraulic Survey Scope states that "...the hydraulic analysis is to be performed by Consultant staff...", but the "NO" box is checked for P/PMS Task 3520 (Conduct Hydraulic/Hydrologic and Scour Analysis). Is it MDOT's intent to have the consultant perform a hydraulic analysis on the culvert at Station 186+50?

Answer 1: Yes, it is MDOT's intent to have the consultant perform a hydraulic analysis on the culvert at station 186+50.

Question 2: The survey scope in the RFP calls for use of the MDOT 2009 Standards of Practice. Should this be the 2010 Standards, since they are now available?

Answer 1: This will be discussed with the selected consultant and the latest adopted MDOT design survey standards will be used for this project.