MILKING EQUIPMENT INSTALLER MANUAL



MICHIGAN DEPARTMENT OF AGRICULTURE FOOD AND DAIRY DIVISION

TABLE OF CONTENTS

Mission St	tatement and Pr	ocedure	Section A	
Dairy Facil	lity Checklist		Section B p. 1-8	
ASAE Sta	ındards:			
S51	18.2 JUL96	Milking Machine Installations (2.2MB)— Construction and Performance	Section C	
EP4	445.1 JUL96	Test Equipment and its Application (2.6M Milking Machine Operating Characteria		
3-A Sanita	ary Standards:			
		es for the Design, Fabrication, and Installa Handling Equipment, Number 606-04.		
Guideline	es for:			
<u>Cal</u>	culating cooling c	dropor branch lines	p. 1-5 Section E p. 6 Section E p. 7	
Administra	ative procedure:	2	p. 1-9	
<u>Supplement</u>				
DAIRY FACILITY CHECKLIST				
Dairy Facility Construction				
Stanchior	n or Tie Stall B	arn if Use as a Milking Facility	See <u>Administrative</u>	
2.	Barn properly v	orovided. d to gutter or drop. entilated with exhaust fans, windows on himize odors and humidity.	Procedure: 4r-4 2r-2 2r	

5	Ample stalls for all cattle. Separate stalls and pens for bulls, and calves. Walls and ceiling a light color finishes (white or near white),	2r 2r
7.	smooth, dust tight. Proper lighting available in the barn. (App. B - 100watts/10ft)	2r
	Feed storage separated and proper to minimize rodents and insects. ecommendations: Cattle trainers used.	19r
Barnyar	ds and Housing	
	Solid approaches to feed, water and barn doors; barnyard in good condition ecommendations:	4r-2
K	a. Ample stalls for all cattle. b. Clean, dry bedding used. c. Stalls and bedding easy to maintain. d. Barn properly ventilated to reduce odors and humidity.	
	lanagement	
	ecommendations:	
	Waste storage separated from cattle.	
	 Waste storage capacity sufficient for extended storage. Waste facility constructed according to the Natural Resources C guidelines. 	onservation
4	Farm has a manure management plan	
5.	Waste management plan on file with the local Natural Resource Conservation Service office.	S
6	Farm follows the manure management practices' outline by the to Farm (RTF) Program.	Right
Milking	Facility Construction	
Parlor A	ıreas	
	Floors, steps, gutters, feed troughs made of impervious material and floors graded to drain.	2r-1
2	Walls and ceiling a light color finishes (white or near white),	2r 2

Milkin

Parlor

1.	Floors, steps, gutters, feed troughs made of impervious	2r-1		
	material and floors graded to drain.			
2.	Walls and ceiling a light color finishes (white or near white),			
	smooth, dust tight.	2r-2		
3.	Tight fitting doors or separation provided between parlor and			
	cattle housing if equipment is stored in parlor?	12r-1		
4.	Lighting proper at 10 f/c.	2r-4, App. B		
5.	Ventilation proper.	2r-5		
6.	Feed storage proper to minimize rodents and insects.	19r-9,10		
7.	Separate stalls or pens for bulls and calves.	2r-6		
Recommendation:				
	a Separate facility maintained to milk fresh cows			

- a. Separate facility maintained to milk fresh cows and treated cows.
- b. Heating for facility available.

Utility Area

1. Room maintained and reasonable clean 19r-1

	2.	Room	free of rodents and insects.	19r-3
	Re	comm	nendation:	
		a.	Drug storage facility available.	
		b.	Room partitioned from milk house, barn, or parlor.	
			Room of ample size.	
		d.	Ventilation proper so doors to adjacent rooms are not	propped
		_	open.	
		e.	Exhaust fans provided to ventilate heat from compress pumps	sors or
			papc	
Milk ł			k room	
			arate milk house of ample size provided	5r-1
	2.		lk house doors to cattle housing, milking, and toilet	
			eas solid, tight fitting, and self closing. (recommend	5 7 4 4
	_		at all milk house doors be self closing)	5r-7,11
	3.		er clearance around all equipment.	A D
	4	•	ecommend 30 inches.)	Арр. В
	4.		s of concrete, sloped to drains; drains trapped if	E . O O 4
	_		onnected to a sanitary sewer .	5r-2,3,4
	ე.		s located properly so not under a bulk tank under an outlet valve.	Fr 1 Ann D
	6		and ceiling a light colored (recommend white or	5r-4, App. B
	0.		ear white), easily cleanable material.	5r-5
	7		er lighting over wash vats (20 f/c).	5r-6
		-	ght fixture or an approved alternative installed	31 0
	Ο.	-	r each opening of a bulk tank	5r-6
	9		port for hauler installed	5r-13
			y cleanable surface of adequate size (4'X4') under hose	
			ort? (Recommend 6' or more of concrete)	5r-13
	11	•	unemcumbered compartments in wash vats provided	
		(n	ot vertical wash vats, or wash vats with permanent rack	(S
			permanent lids)	5r-16
	12	. Conv	renient hand wash sink provided with water, soap,	
		ar	nd sanitary towels.	16r-1,2
	13	. Hot a	and cold water to wash vats. (recommend for	5r-14,15,16
			and sink)	16r-2
			ilter storage proper.	12r-4
	15		nouse doors opening to the outside tight fitting and	
			elf closing.	5r-11
			en doors open outward and self closing.	19r-4,5
			ows screened.	19r-4
			nouse properly ventilated 5r-	-8
	19		ents or unprotected lighting fixtures over clean utensil	5 0
	ъ.		orage area or bulk tank opening.	5r-9
	Re		nendations:	
		a.	Provide milk house with a heating system. (Note: Cold	
		h	cannot come from toilet room, milking or cattle hou	
		D.	Heating system approved. (Note: Fuel fired heaters or be vented to the outside if so designed, and fuel m	
			be vertica to the outside if so designed, and fuel if	idal be aloled

outside.)

- c. Cabinet or refrigerator available for drug storage.
- d. Provide an area to post permit, inspection sheets, and weigh slips.
- e. Install one way check valve to eliminate hot/cold water mixing in lines.
- f. Avoid installing a bulk tank outlet valve over a floor drain.
- g. All adjacent rooms should have self closing doors.
- h. Milky water from first rinse not added to grey water if used for parlor rinse down.

Cooling Systems See Administrative Procedure 18r, 14r and Comments

- 1. Cooling system properly sized for the flow rate of the milk. 18r1
 - Milk is cooled to 45°F or less within two hours of the completion of milking and never exceeds 50°F during subsequent milkings.
 - b. It is now required that the milk be cooled to 45°F within four hours of the start of milking when milking runs for an extended period of time.
- 2. Washing and sanitizing system constructed properly to provide proper cleaning.
- 3. Proper CIP/water supply separation while milk is in the bulk tank.
- 4. Pre-cooling system properly constructed and operated.
 - a. Valve or other means available for semiannual sampling of recirculated coolant (sweet water).

18r2

b. Cooling water from a safe supply.

18r2

- c. A drip shield or moisture divert apron is provided for the swing line entry into the bulk tank.
- d. The plate cooler is installed so that it is accessible and inspectable without cutting water lines.
- 5. Dairy farm bypasses the bulk tank and direct fills a bulk milk tanker.
 - a. Means to properly agitate and sample the tanker provided.

PMO Sec. 6

b. Properly designed and operated CIP system

for the bulk tanker load lines and load pump.

10r

- c. A means provided to connect and disconnect transfer hoses and provide protection from contamination.
- 6. The farm bulk milk **and flexible hose ends** comply with 3A Standards.
- 7. Bulk tank agitator shields are provided for agitator shafts bulkheaded outside of the milk house

Recommendations:

- 1. Adequate ventilation or other means for waste heat disposal from the cooling system so that cooling is maximized.
- 2. Bulk tank has an operating indicating or recording thermometer.
- 3. A recording or indicating thermometer is provided for the bulk tanker or for the bulk tanker load line.
- 4. The plate cooler is sized properly so as not to restrict CIP flow.
- 5. A bird-free overhead shelter provided for hose connections when bulk tankers are direct filled.

Toilet room 1. Toilet room provided convenient to the milking operation. 7r-1,2 2. Floor concrete or easily cleanable material. 3. Walls and ceiling easily cleanable. 4. Toilet hooked to a sanitary sewer system. 7r-1 5. Toilet properly vented to the outside. 7r-1 Windows to the outside screened. 7r-5 7. Solid walls and tight fitting, self closing doors provided. 7r-5 8. Toilet room maintained neat and clean. 7r-4 Recommendations: a. Provide a hand wash sink convenient to toilet room. b. Provide a separate heating system for toilet room. Wells 1. The geology and topography of the area around the well adequate to not require a sanitary survey. App. D 2. The area around the well slopes away so that water does not pool within 10 ft of the well head. 8r-4 3. A minimum of 50 ft (State law 75 ft.) isolation from sources of contamination such as sewage system, drain fields, septic tanks, non-concrete barnyards or manure lagoons? App. D 4. The well properly constructed. App. D 5. The well casing rises at least 2 ft above the highest known flood level. App. D 6. Wells with a pitless adaptor constructed properly. App. D 7. Wells with a submersible pump constructed properly. App. D App. D 8. Well cap tight. 9. The wire entrance to the well cap tight. App. D 10. Any well pit/pressure tank pit within 10 ft of the well is constructed properly. App. D 11. For flowing artesian wells, the overflow drain extends more than 10 feet from a well. App. D 12. Any well house constructed over the well has an adequate drain. App. D 13. The well has been sampled within 3 years, and is there a safe water sample on file. 8r-7 **Components of Water System** 1. All high pressure pumps properly protected with a low pressure cutoff switch or vacuum breaker (recommend 18" above inlet). 8r-3,4 2. Any back flush systems or teat dip and udderwash mixing pumps drawing on containers more than 1 Gal. have backflow protection. 8r-2 3. Stock tank water fill lines have air gaps, backflow preventers or an approved style float. 8r-3 4. Frost free waterers designed with a proper air gap and water overflow to eliminate any submerged inlets. 8r-2,3

5.	Any hoses used to fill tanks or vats provided with a	
	backflow preventer or proper air gap.	8r-2,3
6.	Cattle drinking cups of proper design or provided with	
	a backflow preventer.	8r-2,3
7.	Any frost free hydrants located within 10 ft of the	
	well head are provided with a hose bib backflow preventer	
	or hose threads damaged or removed to prevent	
	attachment of a hose.	8r-2
	Any frost free hydrants removed from the well heads.	8r-2
9.	Any water seal pumps, such as vacuum pumps,	
	provided with proper back flow prevention or air gap.	8r-2
10	. Any foamer used is it provided with backflow	
	prevention for the water supply, if necessary.	8r-2
11	. Well water supply lines run to any grey water tank provided	0 0
40	with backflow preventers, or proper air gaps.	8r-2
12	. Any recirculated cold water/chill water system present	
	used to cool the milk, or a recirculated hot water system	
	used to maintain CIP wash temperatures for the	
	milking system free of any cross connections with the well water system. A means is provided to	
	allow semiannual sampling of recirculated water.	8r-1,2
12	. Any farms with a reclaimed water system such as	01-1,2
10	a plate cooler discharge, have properly	
	separated it from the well water system.	8r-2
14	. Wash vat are free of submerged water inlets, or water-CIP	0
•	chemical cross connections.	8r-2
15	. Any reclaimed water storage tanks for	
	a redistribution system to cattle waterers or high	
	pressure pumps are free of well water submerged inlets.	8r-3
16	. Any boiler system with a well water	
	makeup line is free of a cross connection.	8r-3

MILKING SYSTEMS See Administrative Procedure 9r and 14r

Note: Specific recommendations in this section are based on 3-A Accepted Practices for the Design, Fabrication, and Installation of Milking and Milk Handling Equipment - Number 606-04. This 3-A Practice references the American Society of Agriculture Engineers Standard (ASAE) S518.2, Milking Machine Installation--Construction and Performance. When equipment and installations comply with these standards, they meet the requirements of the PMO.

- 1. The vacuum system is properly designed and constructed.
 - a. The vacuum system slopes properly to drain points (1/2 inch per 10 feet).
 - b. The vacuum system is constructed with appropriate materials.
 - c. The vacuum line is of adequate size without restrictions.
 - d. The sanitary trap is properly positioned so that moisture drains to the trap and not the receiver jar.
 - e. The rise in the line from the receiver jar to the moisture trap 12" or less

Recommendation:

a. A clean air supply is provided for the pulsators.

- b. The vacuum controller is properly filtered and located in a low dust area per ASAE S518.2. Vacuum controller must not be located in a bathroom or areas that produce odors. (14r-8)
- c. The vacuum pump discharges have an exhaust flap to prevent reversing of the pump.
- d. The vacuum system has a safety relief valve.
- e. Milk lines, when installed imbedded in concrete should be sleeved with oversized PVC piping to allow for line expansion, inspection of line slope, and resloping when required.
- f. The installation of the receiver group in a pit is not recommended unless an adequate means to is provided to preclude cross-contamination of the milking system with the floor drains located within the pit.
- 2. The CIP/wash system is properly constructed and operated.
 - a. The pipeline has a wash divert plugs or valves if the design requires (double slope line). Butterfly valves must be of acceptable design to be easily disassembled and cleanable and inspectable.
 - b. There is adequate hot water volume provided for all hot water needs pipeline, bulk tank, calf feeding, cleanups, etc. (See appendix)
 - c. The CIP/wash system is free of submerged inlets.
 - d. There is proper CIP/water supply separation, and separation of both from the milking system during milking.
 - e. The air injectors are properly located in the milk house or filtered if located in the parlor.
 - f. The CIP/wash system is designed to clean the moisture trap and all areas that are milk contact surfaces.
- 3. The pipeline is properly constructed and operated.
 - a. The pipeline is constructed from approved 3A materials (see 3A Accepted Practice 606-04, section C).
 - b. All welds are proper.
 - c. Any plastic components are separated by stainless or glass sections.
 - d. Any risers in the milkline, such as over a walkway, are designed to drain and wash properly. **Note:** Milk in a milk line shall not encounter an upward slope unless it is a milk transfer line that is not affected by vacuum flow, such as the line from the milk pump to the bulk tank. Milklines shall be rigidly mounted.(See 3A Accepted Practice 606-04, section S1)
 - e. The pipeline is properly sloped (at least 1in/10ft) and mounted so that the slope is continuous with no sags or humps. Supports must not be from the ceiling, pipe clamps must be insulated, supports must be every 10 feet and within 2 feet of a direction change. (See 3A Accepted Practice 606-04, section S1)
 - f. When the moisture trap and the receiver jar drain are connected for CIP, there must not be a connection between a sanitary trap drain and receiver drain during milking.
 - g. The pipeline inlets are tipped upward as required.
 - h. The pipeline inlets and inlet covers are of a proper design so that they CIP or are washed after each milking as required.
 - i. The pipeline is properly sized to handle the expected volume of milk without flooding.

- j. The pipeline is designed so there are no dead end lines over 2X the pipe diameter.
- k. There are shields around the lines where they pass through walls.
- I. There is an air blow/chase down system to empty the milk line of milk.
 - i. It is of an approved 3A design. See PMO Appendix H, II
 - ii. The air is filtered with a disposable filter.
- m. The pipeline and milking equipment have proper drainage.
- n. The pipeline is accessible for inspection, with sanitary couplers on each straight run.
- o. There is a proper source of vacuum (trapped) for weigh jars.
- p. There is a drip shield or apron on the swing line from plate cooler.
- q. The jetter washers are provided with proper storage during milking.
- r. Milk meters for takeoff systems and weigh jars are easily accessible for inspection.
- s. The vertical vat is provided with proper CIP/water separation and with dust/insect protection if it is used as a milk transfer point.
- t. There is a means to sanitize bulk tank and milking system.
- u. There is a separate source of vacuum and separate equipment for the abnormal milk system.
- v. There is proper separation/protection for chemical/water supply/milk in the back flush system if present.
- w. Milk hoses do not rise more than 7 ft. to the milkline.
- x. The plate cooler or receiver pump/receiver jar drain do not terminate in the floor drain
- y. The system has been performance tested following completion per ASAE EP 445.1.
- z. Dual filter systems with divert valves designed so milk does not set in unused filter.

Note: An alternative to a mercury manometer, such as an electronic manometer, is recommended.

Additional PDFs for your information:

<u>DY-342</u> Notice of Intent to Install Construct or Change Equipment.

DY-343 Application to Install.

<u>Update to the Supplement</u> (listed in above Table of Contents).

PMO Air Supplies Diagrams.

<u>Instruction to follow</u> for all new installations or major revisions.

Hot Water Estimator For Bulk Tank Wash.