

# GR RAPIDS, GERALD R. FORD INT'L (GRR)

FREQ	
ATIS/ASOS	118.725
CLNC	119.3
GND	121.8
TWR/CTAF*	135.65
APP/DEP (R)	
N	124.6
S	128.4
RCO	122.25
UNICOM	122.95

LOCATION

## 794'

ELEV

09852.A  
41-10

11-18      0 10      SCALE IN MILES

## GRR

Taxiway  
Next  
Pg

SKETCH      0 1500      SCALE IN FEET

**RWY LENGTH BEYOND DISPLACED THR**

08R/ — \* 08L/ — \* 17/ —  
26L/ — \* 26R/ — \* 35/ —

**COORDINATES**

42° 52.85'N  
085° 31.37'W

**License**  
Air Carrier

**FM CITY:** 6.0 mi SE

**LGT:** ROTG BCN, MALSR, HIRL, MIRL, VASI, PAPI, REIL. Aft twr clsd VASI, PAPI, REIL, HIRL, MIRL—STD PCL CTAF.

**MGR:** Brian Picardat, CEO, & CFO  
Alex Peric

Phillip Johnson, Asst

**PH:** 616-233-6000  
616-233-6055 (Aft hrs)

**FBO:** Signature Flight Support 616-336-4711  
Mayday Avionics 616-957-4920

**ATND:** 24 Hr

**NAV AIDS:** IAP, 115.95 (GRR) 353° 5.8 NM to fld, ILS.

**FUEL:** 100LL, JET A

**RPR:** Major A&P, Avncs

**WX:** ASOS 616-575-1953

**SNW RMVL:** Yes

**TRNSP:** Taxi, Rntl car (at arpt)

**MEALS:** At arpt

**RON:** 3.0 mi, CC

- FAA Class "C" Airspace durg \*twr opns 0530-2400, otr times Class "E".
- Customs ldg right arpt, ph 616-942-5245, 616-249-5380 (pgr).
- Noise abatement procedures in effect.
- Birds on & invof arpt.


# GRR, GERALD R. FORD INT'L TAXIWAY

## FREQ

ATIS/ASOS	118.725
CLNC	119.3
GND	121.8
TWR/CTAF*	135.65
APP/DEP ( R)	
N	124.6
S	128.4
UNICOM	122.95

# 794'

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.  
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.



## Runway Incursion Hot Spots

HS 1 Pilot confusion risk int Twy A, Twy M Twy A2 near Rwy 08R-26L.

HS 2 Pilot confusion risk int Twy A, Twy F, Twy B, Twy A1 near Rwy 08R-26L.

HS 3 Pilot confusion risk int Twy B, Twy V, Twy B4 near Rwy 17-35.