

Rest Area ADA Deficiencies List

Name	Ref	Route	Region	Building Type	ADA Category	ADA Deficiency	Proposed Fix	Notes					
Adair Rest Area	909-R	I-94	Bay	Q4	Parking	Missing van accessible signage. Toilet is mounted too high.	Install van sign Adjust toilet (x5)						
Alamo Rest Area	709-R	US-131	Southwest	M1	Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Accessible Route	Missing truncated domes at curb cut.	Replace accessible route						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs.	Adjust door pull force (x2)						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x2)						
					Restrooms	Toilet is mounted too high.	Move toilet (x2)						
					Restrooms	Toilet paper dispenser is mounted too far from the back wall.	Adjust toilet paper dispenser (x2)						
					Restrooms	Hand dryer is mounted too high.	Adjust hand dryer (x4)						
					Restrooms	Family rest room: toilet paper dispenser is mounted too high and far from the back wall	Adjust toilet paper dispenser (x1)						
					Restrooms	Mirror is mounted too high.	Adjust mirror (x2)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
Alger Rest Area	625-R	I-75	Bay	Q4	Entrances & Interior Doors	Door pull force exceeds 8.5 lbs.	Adjust door pull force (x4)						
Battle Creek Rest Area	703-R	I-94	Southwest	8C	Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser (x5)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Parking	Missing van accessible signage.	Add van sign						
					Accessible Route	Truck parking accessible route is steep.	Replace accessible route - truck side						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Toilet is mounted too far out from the side wall and is mounted too low.	Adjust toilet (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Drinking Fountains	Drinking fountain is mounted too low.	Adjust drinking fountain						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Replace accessible stall (x4)						
					Restrooms	Toilet is mounted too far from side wall.	Move toilet (x4)						
Bay City Rest Area	605-R	I-75	Bay	8C	Restrooms	Toilet paper dispenser is mounted too high and too far from the back wall.	Move toilet paper dispenser (x4)						
					Restrooms	No protective drain cover on sink pipes.	Add protective insulation for sink piping						
					Restrooms	Mirror is mounted too high.	Adjust mirror (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain						
					Seating, Tables & Work Areas	Picnic tables available but not located on accessible route.	Adjust picnic table (x2)						
					Accessible Route	Slope of ramp exceeds recommendations.	Replace sidewalk ramp						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs.	Adjust door pull force (x4)						
					Ramps	Slope of ramp exceeds recommendations.	Replace sidewalk ramp						
					Restrooms	Toilet is mounted too high.	Adjust toilet (x4)						
Bolleville Rest Area	911-R	I-94	Metro	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Two closest accessible designated spaces are not near accessible route.	Move accessible parking spots (x2)						
					Accessible Route	Uneven concrete.	Replace ramps (x2)						
					Accessible Route	1.5" grades.	Replace ramps (x2)						
					Accessible Route	Missing truncated domes.	Replace ramps (x2)						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs.	Adjust door pull force (x2)						
					Ramps	Handrail is too wide.	Replace handrail						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Replace accessible stall (x2)						
					Restrooms	Grab bar not available on back wall of accessible stall.	Add grab bar (x2)						
					Restrooms	Toilet is mounted too far out from side wall.	Move toilet (x2)						
Big Rapids Rest Area	534-R	US-131	Grand	M3	Parking	Missing van accessible signage.	Add van sign						
					Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser (x2)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Hand dryer is mounted too high.	Adjust hand dryer (x2)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Uneven stair treads.	Fix stair treads						
					Seating, Tables & Work Areas	Approach to the picnic table is not accessible.	Add accessible picnic table						
					Exhibits, Signage & Displays	Rest room signage is mounted too high.	Adjust restroom signage (x2)						
					Accessible Route	Several cracks in sidewalk.	Repair sidewalk						
					Accessible Route	Slope of ramp exceeds recommendations.	Replace access route - truck						
Cadillac Rest Area	306-R	US-131	North	Q4	Entrances & Interior Doors	Door pull force exceeds 8.5 lbs.	Adjust door pull force						
					Restrooms	Truck parking curb cut is steep.	Replace sidewalk						
					Restrooms	Toilet is mounted too high.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser incorrect height.	Adjust toilet paper dispenser (x4)						
					Restrooms	Toilet paper dispenser is mounted too far from back wall.	Move toilet paper dispenser (x4)						
					Restrooms	Hand dryer is mounted too high.	Adjust hand dryer (x4)						
					Restrooms	Family rest room: toilet paper dispenser is mounted too far from back wall.	Move toilet paper dispenser						
					Restrooms	Family rest room: hand dryer is mounted too high.	Adjust hand dryer						
					Restrooms	Missing grab bars.	Add grab bar (x4)						
					Restrooms	Door pull force exceeds 8.5 lbs.	Adjust door pull force (x2)						
Capac Rest Area	913-R	I-69	Bay	M3	Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Replace accessible stall (x2)						
					Restrooms	Toilet not centered from wall.	Move toilet (x2)						
					Restrooms	Sink mounted too high.	Adjust sink (x2)						
					Restrooms	Pipe insulation is missing under sinks.	Add protective insulation for sink piping (x2)						
					Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Drinking Fountains	Drinking fountain is mounted too low.	Adjust drinking fountain						
					Exhibits, Signage & Displays	Accessible restroom signage is mounted incorrectly and missing braille.	Replace restroom signage						
					Parking	Missing van sign.	Add van sign						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)						
Carleton Rest Area	826-R	I-275	University	M2	Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x2)						
					Restrooms	Toilet is mounted too low.	Adjust toilet (x2)						
					Restrooms	Toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	Move toilet paper dispenser (x2)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain						
					Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain						
					Chelsea Rest Area	832-R	I-94	University	Q4	Accessible Route	Truck parking accessible route has several cracks and missing concrete.	Replace accessible route - truck	
					Clare Welcome Center	634-R	US-127	Bay	WC	Restrooms	Toilet is mounted too far out from the side wall.	Move toilet (x4)	
										Restrooms	Sink mounted too high.	Adjust sink (x4)	
										Restrooms	Vertical grab bars missing.	Add vertical grab bars	
Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain											
Public Phones	Pay phone is mounted too high.	Adjust pay phone											
Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)											
Ramps	Hand rails are too wide.	Replace handrails											
Restrooms	Toilet is mounted too low.	Adjust toilet (x4)											
Restrooms	Toilet paper dispenser is mounted too high and close to the back wall.	Adjust toilet paper dispenser (x4)											
Restrooms	Vertical grab bars missing.	Add vertical grab bars											
Clarkston Rest Area	904-R	I-75	Metro	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Toilet is mounted too far from side wall.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser if mounted too high.	Adjust toilet paper dispenser (x5)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Public Phones	Pay phone is mounted too high.	Adjust pay phone						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
Coldwater Welcome Center	716-R	I-69	Southwest	WC	Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Adjust accessible stall (x4)						
					Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Toilet is mounted too high and too far out from the side wall.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	Move toilet paper dispenser (x4)						
					Restrooms	Missing grab bar on back of accessible designated stall.	Add grab bar (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Public Phones	Pay phone is mounted too high.	Adjust pay phone						
Clio Rest Area	612-R	I-75	Bay	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Toilet is mounted too far from side wall.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser if mounted too high.	Adjust toilet paper dispenser (x5)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Public Phones	Pay phone is mounted too high.	Adjust pay phone						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
Davisburg Rest Area	908-R	I-75	Metro	Q4	Restrooms	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Toilet is mounted too high and too far out from the side wall.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	Move toilet paper dispenser (x4)						
					Restrooms	Missing grab bar on back of accessible designated stall.	Add grab bar (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Public Phones	Pay phone is mounted too high.	Adjust pay phone						
					Exhibits, Signage & Displays	Missing emergency exit signage.	Add emergency exit signage (x2)						
					Parking	Missing van accessible signage.	No work	Leased building.					
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	No work						
DeWitt Rest Area	831-R	US-127	University	Q4	Restrooms	Toilet paper mounted too far from the back wall.	No work						
					Seating, Tables & Work Areas	Accessible counter is mounted too high.	No work						
					Parking	Missing van accessible signage.	Add van sign						
					Accessible Route	Sidewalks are uneven and crumbling.	Replace sidewalk on accessible route						
					Restrooms	Grab bars are mounted too high.	Adjust grab bars						
					Restrooms	Toilet is mounted too far out from the side wall.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser is mounted too close to the toilet.	Move toilet paper dispenser (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain						
					Restrooms	Hand dryer is mounted too high.	Adjust hand dryer (x2)						
Dodge Road Rest Area	631-R	I-75	Bay	Q4	Restrooms	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Toilet paper dispenser if mounted too high.	Adjust toilet paper dispenser (x5)						
					Restrooms	Sink is mounted too high.	Adjust sink (x5)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Sidewalks are uneven and crumbling.	Replace sidewalk						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Ramps	Side walk slope is too steep.	Replace sidewalk						
					Ramps	Handrails do not meet requirements.	Replace handrail						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Toilet is mounted too far from side wall.	Move toilet (x4)						
Dundee Welcome Center	822-R	US-23	University	WC	Restrooms	Toilet paper dispenser is mounted too high and close to the back wall.	Move toilet paper dispenser (x4)						
					Exhibits, Signage & Displays	Missing braille usage in signage.	Add signage						
					Restrooms	Toilet is mounted too high.	Adjust toilet (x4)						
					Restrooms	Toilet paper dispenser is mounted short of the proper distance from the back wall.	Adjust toilet paper dispenser (x5)						
					Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain						
					Public Phones	Pay phone is mounted too high.	Adjust pay phone						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Adjust accessible stall (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Sidewalks are uneven and crumbling.	Replace sidewalk						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
Fenton Rest Area	624-R	US-23	Bay	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Restrooms	Sidewalks are uneven and crumbling.	Replace sidewalk						
					Restrooms	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Ramps	Side walk slope is too steep.	Replace sidewalk						
					Ramps	Handrails do not meet requirements.	Replace handrail						
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x4)						
					Restrooms	Toilet is mounted too far from side wall.	Move toilet (x4)						
					Restrooms	Toilet paper dispenser is mounted too high and close to the back wall.	Move toilet paper dispenser (x4)						
					Exhibits, Signage & Displays	Missing braille usage in signage.	Add signage						
					Restrooms	Toilet is mounted too high.	Adjust toilet (x4)						

Name	Ref	Route	Region	Building Type	ADA Category	ADA Deficiency	Proposed Fix	Notes
Five Lakes Rest Area	629-R	I-69	Bay	M3	Accessible Route	Sidewalks are uneven and crumbling.	Replace sidewalks	
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)	
					Ramps	Hand rail missing on one side of stairs.	Replace stair handrail	
					Restrooms	Replace accessible route	Replace stair handrail	
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Designated accessible stall does not meet 60" x 60" turning radius.	
					Restrooms	Move toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	Move toilet paper dispenser (x2)	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Stairs are not uniform for height or depth.	Replace stairs	
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain	
					Drinking Fountains	Water flows too low.	Adjust drinking fountain pressure	
Fruitport Rest Area/Nunica	502-R	I-96	Grand	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
Galesburg Rest Area	704-R	I-94	Southwest	Q4	Accessible Route	Truck side accessible route is very ruff and uneven.	Replace accessible route - truck	
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Adjust door pull force (x4)	
					Restrooms	Toilet is mounted too far out from the side wall.	Add accessible stall (x4)	
					Restrooms	Move toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	Move toilet paper dispenser (x4)	
					Restrooms	Sink mounted too high.	Adjust sink (x4)	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
Garden Corners Rest Area	347-R	US-2	Superior	Log	Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
Gaylord Rest Area	405-R	I-75	North	M3	Parking	Cracks and missing concrete	Replace accessible sidewalk	
					Accessible Route	Cracks in accessible route	Replace accessible sidewalk	
					Accessible Route	Several cross overs from truck parking dump into car parking, no clear accessible route.	Replace accessible route - truck	
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force	
					Restrooms	Designated accessible stall does not meet 60" x 60" turning radius.	Add accessible stall (x2)	
					Restrooms	Toilet paper dispenser is mounted too close to the back wall.	Move toilet paper dispenser (x2)	
					Restrooms	Hand dryer mounted too high.	Adjust hand dryer (x2)	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
Glenn Rest Area	726-R	I-196	Grand	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Spout is mounted too high.	Adjust drinking fountain	
					Restrooms	Distance from front of toilet to door is short	Distance toilet to door too short (x4)	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
Grand Ledge Rest Area	825-R	I-96	University	Q4	Restrooms	Distance from front of toilet to door is short	Distance toilet to door too short (x4)	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	
					Restrooms	Vertical grab bars missing.	Add vertical grab bars	

Rest Area ADA Deficiencies List

Name	Ref	Route	Region	Building Type	ADA Category	ADA Deficiency	Proposed Fix	Notes									
Menominee Welcome Center	116-R	US-41	Superior	WC	Parking	Designated accessible parking space not wide enough.	Restripe for Van Accessible space										
					Parking	Missing van accessible signage.	Add van sign										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs.	Adjust door pull force (x2)										
					Entrances & Interior Doors	Door knob is round, not lever type.	Replace door knob										
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall										
					Restrooms	Toilet is mounted too high and far from the wall.	Move toilet (x2)										
					Restrooms	Toilet paper dispenser is mounted too high and close to the back wall.	Move toilet paper dispenser (x2)										
					Restrooms	Sink is mounted too low.	Adjust sink (x2)										
					Restrooms	Towel dispenser incorrect height.	Adjust tower dispenser (x2)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Drinking Fountains	Drinking fountain mounted too low.	Adjust drinking fountain										
					Public Phones	Pay phone is not located on the accessible route.	Move pay phone										
					Seating, Tables & Work Areas	Counter mounted too high.	Adjust counter.										
					Exhibits, Signage & Displays	Signage is mounted incorrectly.	Move restroom signage										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)										
Restrooms	Toilet is mounted too high.	Adjust toilet (x4)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Morley Rest Area	533-R	US-51	Grand	M3	Parking	Missing van accessible signage.	Replace accessible signage										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)										
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Replace accessible stall (x2)										
					Restrooms	Toilet is mounted too high.	Adjust toilet (x2)										
					Restrooms	Toilet paper is mounted too high and back from the wall.	Move toilet paper dispenser (x2)										
					Restrooms	Sink knee space is too low.	Adjust sink (x2)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Exhibits, Signage & Displays	Missing emergency exit signage.	Add emergency exit signage										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)										
					Restrooms	Hand dryer mounted too high.	Adjust hand dryer (x4)										
					Restrooms	Family rest room: toilet paper dispenser is mounted too far from the back wall.	Move toilet paper dispenser (x1)										
					Restrooms	Family rest room: hand dryer is mounted too high.	Adjust hand dryer (x1)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Ramps	Missing hand calls on entrance ramp.	Add handrails										
					Muskegon Rest Area	501-R	US-31	Grand	Q4	Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)					
Restrooms	Hand dryer mounted too high.	Adjust hand dryer (x4)															
Restrooms	Family rest room: toilet paper dispenser is mounted too far from the back wall.	Move toilet paper dispenser (x1)															
Restrooms	Family rest room: hand dryer is mounted too high.	Adjust hand dryer (x1)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Restrooms	Vertical grab bars missing.	Add handrails															
Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)															
Ramps	Outside ramp is less than the 60" minimum width.	Replace ramp															
Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x4)															
Restrooms	Toilet is mounted too far out from the side wall.	Move toilet (x4)															
Restrooms	Toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	Move toilet paper dispenser (x4)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain															
Public Phones	Pay phone is mounted too high	Adjust pay phone															
Nine Mile Hill Rest Area	434-R	I-75	North	M6						Restrooms	Hand dryer mounted too high	Adjust hand dryer (x2)					
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Family restroom turning radius										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Restrooms	Distance from front of toilet to door is short	Move toilet (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					No deficiencies found	No deficiencies found	No deficiencies found										
					Accessible Route	Sidewalks are uneven and crumbling.	Replace sidewalk										
					Accessible Route	Picnic table is mounted at the top of incline, does not meet 60"x60" turning radius next to the table.	Add accessible picnic table										
					Restrooms	Sink is mounted too high.	Adjust sink (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain										
					Public Phones	Pay phone is mounted too high	Adjust pay phone										
Northfield Church Rest Area	814-R	US-23	University	Q4	Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Family restroom turning radius										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Restrooms	Distance from front of toilet to door is short	Move toilet (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					No deficiencies found	No deficiencies found	No deficiencies found										
					Accessible Route	Sidewalks are uneven and crumbling.	Replace sidewalk										
					Accessible Route	Picnic table is mounted at the top of incline, does not meet 60"x60" turning radius next to the table.	Add accessible picnic table										
					Restrooms	Sink is mounted too high.	Adjust sink (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain										
					Public Phones	Pay phone is mounted too high	Adjust pay phone										
					Potterville Rest Area	829-R	I-69	University	Q4	Restrooms	Hand dryer mounted too high	Adjust hand dryer (x2)					
										Restrooms	Vertical grab bars missing.	Add vertical grab bars					
Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Family restroom turning radius															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Restrooms	Distance from front of toilet to door is short	Move toilet (x4)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
No deficiencies found	No deficiencies found	No deficiencies found															
Accessible Route	Sidewalks are uneven and crumbling.	Replace sidewalk															
Accessible Route	Picnic table is mounted at the top of incline, does not meet 60"x60" turning radius next to the table.	Add accessible picnic table															
Restrooms	Sink is mounted too high.	Adjust sink (x4)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain															
Public Phones	Pay phone is mounted too high	Adjust pay phone															
Richmond Rest Area	910-R	I-94	Bay	M1	Parking	Missing van accessible signage.	Install van sign										
					Restrooms	Toilet is mounted too far from the side wall.	Move toilet (x2)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain										
					Exhibits, Signage & Displays	Missing emergency exit signage.	Add emergency exit signage										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)										
					Restrooms	Toilet is mounted too close to the wall and too high.	Move toilet (x4)										
					Restrooms	Toilet paper dispenser is mounted to close to the back wall.	Move toilet paper dispenser (x4)										
					Restrooms	Family restroom mirror mounted too high.	Adjust mirror										
					Restrooms	Family restroom hand dryer mounted too high.	Adjust hand dryer										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Exhibits, Signage & Displays	Missing ADA document.	Add ADA document.										
					Parking	Missing van accessible signage.	Replace accessible signage										
					Accessible Route	Accessible route has several cracks and missing concrete.	Replace access route from truck parking										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)										
Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Replace accessible stall (x2)															
Restrooms	Toilet is mounted too far from side wall.	Move toilet (x2)															
Restrooms	Toilet paper dispenser is mounted to high and too far from the back wall.	Move toilet paper dispenser (x2)															
Restrooms	Sink is mounted too low.	Adjust sink (x2)															
Restrooms	Hand dryer is mounted too high.	Adjust hand dryer (x2)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Seating, Tables & Work Areas	No tables located on accessible route.	Add accessible picnic table															
Exhibits, Signage & Displays	Rest room signage mounted on door, not on latch side of door.	Replace restroom signage (x2)															
Saint Ignace Welcome Center	223-R	I-75	Superior	WC	Parking	Missing van accessible space.	Add van sign										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)										
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x2)										
					Restrooms	Toilet not centered from wall.	Move toilet (x2)										
					Restrooms	Sink mounted too high.	Adjust sink (x2)										
					Restrooms	Pipe insulation is missing under sinks.	Add protective insulation for sink pipes (x2)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Stairs	Stair steps are not uniform.	Replace stairs										
					Stairs	Missing railings.	Replace railings										
					Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain										
					Exhibits, Signage & Displays	No accessible signage on RR.	Add accessible signage										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)										
					Restrooms	Distance from front of toilet to door is short	Move toilet (x4)										
					Restrooms	Toilet is mounted too high and too close to the wall.	Move toilet (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
Public Phones	Pay phone is mounted too high	Adjust pay phone															
Saranac Rest Area	532-R	I-96	Grand	Q4	Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Accessible Route	Sidewalks are uneven and crumbling.	No work	2019 Reconstruction									
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	No work										
					Restrooms	Toilet is mounted too high and too far out from the side wall.	No work										
					Restrooms	Toilet paper dispenser is mounted too high and mounted short of the proper distance from the back wall.	No work										
					Restrooms	Sink is mounted too high.	No work										
					Drinking Fountains	Spout is mounted too high.	No work										
					Public Phones	Pay phone is mounted too high	No work										
					Exhibits, Signage & Displays	Missing emergency exit signage.	No work										
					Parking	Missing van accessible space.	Add access parking - truck										
					Parking	No accessible parking spaces on the truck side, add curb cut and stripe	Add curb ramp - truck										
					Parking	No accessible parking spaces on the truck side, add curb cut and stripe	Pavement markings - truck										
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)										
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x2)										
					Restrooms	Toilet not centered from the wall.	Move toilet (x2)										
Restrooms	Pipe insulation is missing under sinks.	Add protective insulation for sink pipes (x2)															
Restrooms	Mirror mounted too high.	Adjust mirror (x2)															
Restrooms	Towel dispenser mounted too high.	Adjust tower dispenser (x2)															
Restrooms	Door opening does not have 18" clearance on latch side.	Door opening doesn have 18" clearance (x2)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain															
Exhibits, Signage & Displays	Several signs missing Braille.	Add signage															
Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force															
Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x2)															
Restrooms	Mirror mounted too high.	Adjust mirror (x2)															
Restrooms	Towel dispenser mounted too high.	Adjust tower dispenser (x2)															
Restrooms	Vertical grab bars missing.	Add vertical grab bars															
Seating, Tables & Work Areas	Picnic tables offered, but not on accessible route.	Add picnic table															
Exhibits, Signage & Displays	Missing ADA document.	Add emergency lighting at main doors.															
Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x2)															
Restrooms	Designated family restroom does not meet 60"x60" turning radius.	Add accessible stall															
Restrooms	Towel dispenser mounted too high.	Adjust tower dispenser (x2)															
St Ignace Rest Area	241-R	I-75	Superior	M3	Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x2)										
					Restrooms	Toilet not centered from wall.	Move toilet (x2)										
					Restrooms	Sink mounted too high.	Adjust sink (x2)										
					Restrooms	Towel dispenser mounted too high.	Adjust towel dispenser (x2)										
					Restrooms	Relocate waste can in mens RR.	Relocate trash container (x2)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Drinking Fountains	Drinking fountain mounted too high.	Adjust drinking fountain										
					Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser (x4)										
					Restrooms	Vertical grab bars missing.	Add vertical grab bars										
					Swartz Creek Rest Area	627-R	I-69	Bay	Q4	Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser (x4)					
										Restrooms	Vertical grab bars missing.	Add vertical grab bars					
										Tekonsha Rest Area	721-R	I-69	Southwest	Parking	N/A - Parking area only, no building		Truck parking only.

Name	Ref	Route	Region	Building Type	ADA Category	ADA Deficiency	Proposed Fix	Notes					
Topinabee Rest Area	407-R	I-75	North	M3	Accessible Route	Accessible route too steep.	Replace accessible route						
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x2)						
					Restrooms	Toilet not centered from wall.	Move toilet (x2)						
					Restrooms	Toilet paper dispenser incorrect height.	Adjust toilet paper dispenser (x2)						
					Restrooms	Hand dryer incorrect height.	Adjust hand dryer (x2)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Seating, Tables & Work Areas	Picnic tables offered, but not on accessible route.	Add picnic table						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Public Phones	Pay phone is mounted too high	Adjust pay phone						
					Parking	No designated accessible space identified.	Add accessible signage						
					Parking	No designated accessible space identified.	Add van accessible pavement markings						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force						
					Ramps	Scenic lookout is not accessible.	Add scenic lookout access						
					Restrooms	Toilet is mounted too high.	Adjust toilet (x2)						
Restrooms	Toilet paper is mounted too high.	Adjust toilet paper dispenser (x2)											
Restrooms	Vertical grab bars missing.	Adjust vertical grab bars											
Stairs	Stairs are not uniform for height or depth at the scenic overlook.	Fix stair treads											
Seating, Tables & Work Areas	Picnic tables are not accessible at the scenic overlook.	Add accessible picnic table											
Vanderbilt Rest Area	406-R	I-75	North	M3	Accessible Route	Truck parking accessible route has several cracks and missing concrete.	Replace accessible route - truck						
					Ramps	Hand rail located on one side only and gripping dimension is too large.	Replace handrail						
					Restrooms	Designated accessible stall does not meet 60"x60" turning radius.	Add accessible stall (x2)						
					Restrooms	Toilet paper dispenser is mounted too far from back wall.	Move toilet paper dispenser (x2)						
					Restrooms	Hand dryer mounted too high.	Adjust hand dryer (x2)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Seating, Tables & Work Areas	Missing concrete to connect pad area to accessible route.	Replace sidewalk						
					Parking	No accessible parking spaces on the truck side, add curb cut and stripe	Add accessible signage - truck						
					Parking	No accessible parking spaces on the truck side, add curb cut and stripe	Add curb ramp - truck						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Toilet paper dispenser mounted too far out from back wall.	Move toilet paper dispenser (x4)						
					Restrooms	Hand dryer mounted too high.	Adjust hand dryer (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Seating, Tables & Work Areas	Picnic table not offered on truck side.	Add picnic table - truck						
					Watervliet Rest Area	706-R	I-94	Southwest	Q4	Accessible Route	No accessible parking spaces on the truck side, add curb cut and stripe.	Replace ramp - truck	
Parking	No accessible parking spaces on the truck side, add curb cut and stripe.	Restripe for accessible space - truck											
Parking	Missing van accessible signage on car side.	Add van sign											
Restrooms	Toilet paper dispenser is mounted too low and too far forward from the back wall.	Move toilet paper dispenser (x4)											
Restrooms	Vertical grab bars missing.	Add vertical grab bars											
Drinking Fountains	Drinking fountain is mounted too low.	Adjust drinking fountain											
Accessible Route	Accessible route is slightly steep.	Replace accessible route - car											
Ramps	Hand rail grip on car parking side is too wide.	Replace handrail											
Restrooms	Family RR: 60"x60" turning radius is not accessible because of waste paper container.	Move trash container (x2)											
Restrooms	Family RR: Toilet paper dispenser if mounted too far from the back wall.	Move toilet paper dispenser (x2)											
Restrooms	Family RR: Sink mounted too high.	Adjust sink (x2)											
Restrooms	Family RR: Hand dryer mounted too high.	Adjust hand dryer (x2)											
Restrooms	Family RR: Mirror is mounted too high.	Adjust mirror (x2)											
Restrooms	Vertical grab bars missing.	Add vertical grab bars											
Woodbury Road Rest Area	830-R	I-69	Bay	Q4						Parking	Missing van accessible signage.	Install van sign	
					Accessible Route	Truck parking accessible route has several cracks and missing concrete.	Replace access route from truck parking						
					Entrances & Interior Doors	Door pull force exceeds 8.5 lbs	Adjust door pull force (x4)						
					Restrooms	Toilet paper dispenser is mounted too high.	Adjust toilet paper dispenser (x4)						
					Restrooms	Vertical grab bars missing.	Add vertical grab bars						
					Drinking Fountains	Drinking fountain is mounted too high.	Adjust drinking fountain						
					Exhibits, Signage & Displays	Accessible signage is mounted too high.	Replace accessible signage						
					Public Phones	Pay phone is mounted too high	Adjust pay phone						
					Vertical grab bars missing.	Vertical grab bars missing.	Add vertical grab bars						
					Zealand Rest Area	528-R	I-196	Grand	Q4	Public Phones	Pay phone is mounted too high	Adjust pay phone	
										Vertical grab bars missing.	Vertical grab bars missing.	Add vertical grab bars	