

M-59 Service Drive (Dobry Drive) Improvements Cities of Sterling Heights and Utica April - August 2016

What Is Being Done?

The Michigan Department of Transportation (MDOT) will be investing \$2.4 million to improve 1 mile of concrete pavement on the M-59 service drive (Dobry Drive) from Utica Road to east of Ryan Road. Work will include resurfacing, concrete pavement repairs, joint sealing, drainage structure adjustments, and pavement marking.

When Will This Be Done?

Work is scheduled to begin in April and is expected to be complete in August.

How Will Traffic Be Affected?

The work will be done in stages to minimize the impact on motorists.



Stage 1 (April - May 27): At least one lane will be open at all times on the westbound service drive. The Merrill Road overpass and the turnaround immediately east of Mound Road will be closed during construction in those areas. Detours will be posted.

Stage 2A (May 31 - June 13): The service drive will be closed with traffic detoured onto westbound M-59 to southbound Dequindre Road, then Dobry Drive.

Stage 2B: This work will occur during Stage 2A on two consecutive weeknights (between Monday and Thursday). During this closure, traffic will be detoured west on Dobry Drive to northbound Dequindre Road, then eastbound M-59 to the Mound Road exit.

Stage 3 (June 14 - Aug. 3): A minimum of two lanes will be open 6 a.m. to 8 p.m. weekdays, with one lane open from 8 p.m. to 6 a.m. nights and weekends. During this work, the first crossover west of Mound Road will be closed but the next crossover will be open.

The Merrill Road overpass and the turnaround immediately east of Mound Road will be closed during work in those areas. Detours will be posted.

For More Information: Call the Macomb Transportation Service Center at 586-421-3920, or go to www.michigan.gov/drive.

MDOT: Providing the highest quality integrated transportation services for economic benefit and improved quality of life.

Prepared by: MDOT Graphic Design \Office of Communications\flyers-postcards\2016\M-59 Service Drive (CJ 5/16)