## **Maintenance Advisory Reference**

Entries in black are active advisories

\*Entries in red with an asterisk are archived advisories

Advisory #	Advisory Name	Notes
202402	CAT-350 Guardrail Terminal: Addition of Square Post Bolt Washers	
2024-01	Soil Erosion and Sedimentation Control	
2023-02	Disposal of Road Killed Animals	Replaces MM 1982-03, MM19 93-02
2021-01	Maintenance of Grade Seperations on State Trunklines	Replaces MA 2019-02, MM 2002-04
*2019-02	Maintenance of Grade Seperations on State Trunklines	See MA 2021-01
2019-01	Discontinued Use of Breakaway Cable Terminals (BCTs)	Replaces MM 2003-01
2018-05	Maintenance Work Project	
2018-04	Guidance on Using Wing-Plow	Replaces MA 2017-02, MA 2014-01, MA 2008-06
2018-03	Disposing of Surplus and Unsuitable Soils	
2018-02	Storage of Materials Under Bridges and Structures	
2018-01	Discontinue Use of X-Lite Guardrail Terminal	
*2017-02	Guidance on Using Wing-Plows	See MA 2018-04
*2017-01	Maintenance Activity Guides-TAMS replacing MARS	No longer needed.
*2014-01	Guidance on Using Wing-Plow	See MA 2018-04
2013-01	Best Practices for Applying Deicing Materials	
2012-04	Roadside Vegetation Management	
2012-03	PDRP	
2012-02	Cable Grip Slippage during Barrier Repair	
2012-01	Roadside-Spraying	
*2010-05	Maintenance Material Reporting in LAPS	No longer needed. New document posted on MLAP page.
2010-04	Insurance For Maintenance Subcontracts	
*2010-03	High Tension Cable Barrier Repairs	Was part of research project, no longer needed
2010-02	Cable Barrier Turnbuckles	Tras pare of research project, no longer neceed
*2010-01	Oil-Water Separator	Information now located in Environmental Manuals
2009-11		Thornauon now located in Environmental Manuals
2009-11	Snow Plowing Near Railroad Crossings  Abrasives in Winter Operations	
2009-10	Cable Barrier System	
*2009-08	Lights on Drums	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
*2009-07	HMA Crack Treatment	Information incorporated into PCA for crack sealing and & concrete repair
2009-06	Edge Drains	
*2009-05	Sign Sheeting Material Change	No longer applicable. Now required to follow the 2020 Standard Specifications for Construction Table 919-3.
2009-04	Illicit Discharge	
2009-03	Damaged Mailboxes	
2009-02	Calibration of salt trucks	
2009-01	White Shoulder Policy	
*2008-10	Bridge Expansion Joints	Information located in Bridge Movement White Paper
*2008-09	Disposal of Used Motor Oil	Information now located in Environmental Manuals
*2008-08	Storage of Empty Drums	Information now located in Environmental Manuals
2008-07	Rest Area Lift Stations	
*2008-06	Wing Plow	See MA 2018-04
2008-05	Liquid Deicing	
*2008-04	Attenuator	No longer applicable
*2008-03	Emergency Scene	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
*2008-02	Concrete Pavement	Information incorporated into PCA for crack sealing and & concrete repair
*2008-01	Use of Arrow Panels	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual Information now located in Michigan Manual for Uniform Traffic Control Devices and
*2007-01	Lights on Drums are Optional for Maintenance Activities	the Work Zone Safety Mobility Manual
*2006-02	Mercury Switch Dispisal	Information now located in Environmental Manuals
*2006-01	Plastic Sign Substrates	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
*2005-02	Bridge Maintenance	Information located in Structural Concrete Repair White Paper
*2005-01	Work Zone Safety	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
		11/13/2024