



## Approved Customer Programming Software & Recommended Firmware Versions

### April 2026 Update

MPSCS Radio Programming Unit (*RPU*) will soon begin delivering radio programming, which requires the use of updated Customer Programming Software (*CPS*) and firmware, depending on your model subscriber radios. Please review the list below for details related to your specific model requirements.

New programming templates, using several new software versions noted below, will begin being delivered to customers effective **Monday, April 13<sup>th</sup>, 2026.**

- **Motorola Solutions** **UPDATED April 2026**

- **APX series**

- **CPS = APX R38.00.70**
- Firmware for standard APX models (*includes N30, N50*) = R38.02.00
- Firmware for APX N70 models = R38.21.00
- Firmware for APX Next (*AN*) models = R38.04.00
- Firmware for APX Next 5G (*BN*) models = R38.20.00
- **Firmware for all APX end of support legacy models (*see detailed list below*) = R36.61.00**  
***This is the final version of firmware for end of support (AN) models as noted in the APX release notes for SR2025.3 (R38) and SR2026.1 (R39)***

***\*R36.61.00 firmware is required to correct issues related to software-based ADP encryption that have been reported; all APX models are recommended to upgrade to this version at the earliest possible timeframe, this is considered the minimum approved baseline firmware version.***

***\*\*Beginning with SR2025.3 (R38) and SR2026.1 (R39) the following (AN) models will no longer receive additional firmware updates and are considered end of support by Motorola Solutions; reference MTN-0083-25 and MTN-0061-26 documents:***

- ***APX 6000, APX 6000 Li (AN), APX 5000 (AN), SRX 2200 (AN)***
- ***APX 1500, APX 2500, APX 4500, APX 4500 Li (AN)***
- ***APX 6500, APX 6500 Li (AN)***
- ***APX 7000, APX 7500***
- ***APX Single Band & APX Dual Band Consolettes***

- **JVCKenwood / EF Johnson UPDATED April 2026**
  - **Viking VP/VM series**
    - **CPS = Armada v1.46.22.193**
    - Firmware for VPx000 portable models = v8.46.24.99
    - Firmware for VMx000 mobile models = v8.46.24.83
    - Firmware for VP8000 portable model = v8.46.24.94
    - Firmware for VM8000 mobile model = v8.46.24.88
  - **NX/TK series (includes NX-5400, NX-5900, TK-5430, TK-5930)**
    - **CPS = KPG-D1N v5.30**
    - Firmware = v5.31
- **L3Harris UPDATED April 2026**
  - **XL series**
    - **CPS = RPM2 R20B0065**
    - Firmware for all XL series = R20B14.0265
- **Tait UPDATED April 2026**
  - **CPS = P25 Terminals Programming Application v3.7.3.29**
  - Firmware for TP9400, TM9400, TP9600, & TP9800 models = v3.07.06
- **BK Technologies UPDATED April 2026**
  - **CPS = RES v5.13.2**
  - Firmware for BKR-9000 models = v5.13.1
  - Firmware for KNG-P800, KNG2-P800, & KNG-M800 models = v5.7.12
- **Unication**
  - **PPS = v0.4.0.41**
  - Firmware for G4 / G5 models = v2.02

If there are any questions, comments, or concerns, or you require assistance related to your subscriber radio programming, contact the MPSCS Radio Programming Unit.

Phone: 517-333-2720

Email: [MPSCS-RPU@michigan.gov](mailto:MPSCS-RPU@michigan.gov)