

FS-25	
11/2/2022	
PFHxS	44
PFOA	3.6
PFOS	32

FS-24	
11/1/2022	
PFHxS	130
PFOA	4.6
PFOS	770

MW-03-04	
11/1/2022	
PFHxS	170
PFOA	6.8
PFOS	640

MW-06-05	
11/1/2022	
PFHxS	2.9
PFOA	<2.0
PFOS	19

MW-05-05	
11/1/2022	
PFHxS	3.4
PFOA	<2.0
PFOS	<2.0

MCW-4	
10/31/2022	
PFHxS	1,700
PFOA	160
PFOS	3,100

MW-04-04	
11/1/2022	
PFHxS	<2.0
PFOA	<2.0
PFOS	5.5

SW-1	
11/2/2022	
PFHxS	6.2
PFOA	3.7
PFOS	58

FS-26	
11/1/2022	
PFHxS	<2.0
PFOA	<2.0
PFOS	5.2

MW-02-04	
11/2/2022	
PFHxS	5.6
PFOA	5.2
PFOS	15

MW-01-04	
11/2/2022	
PFHxS	9.9
PFOA	<2.0
PFOS	150

FS-27	
11/2/2022	
PFHxS	80
PFOA	12
PFOS	410

Direction of groundwater flow ←

Green indicates contaminant was nondetect.

Grey indicates contaminant was detected.

Yellow indicates contaminant exceeds DWL.

Blue indicates contaminant exceeds GSIC.

Green indicates contaminant exceeds both DWL and GSIC.

Former Four Star Property  
1391 Kalamazoo Street  
South Haven, MI

