Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_4833000_57440_2171.tif



Defect #	55	56	EJ	57
Feet from Start	117.51	117.83	122.85	124.00
Feet from Right	5.71	3.96	4.31	8.58
Defect Size	1.24 sq ft	3.52 sq ft	NA	10.93 sq ft
Length x Width (ft)	1.18 x 1.00	1.76 x 1.91	NA	3.10 x 3.37
Type	Delam	Delam	Joint	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_5052000_57440_2171.tif



Defect #	EJ	58	59
Feet from Start	130.67	135.64	135.85
Feet from Right	10.45	9.77	2.14
Defect Size	NA	0.77 sq ft	5.96 sq ft
Length x Width (ft)	NA	2.01 x 0.36	3.51 x 1.62
Type	Joint	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_5265000_57824_2165.tif



Defect #	60
Feet from Start	144.09
Feet from Right	7.26
Defect Size	7.06 sq ft
Length x Width (ft)	4.87 x 1.39
Type	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_5481000_57824_2165.tif



Defect #	61	62
Feet from Start	149.59	155.33
Feet from Right	6.77	7.22
Defect Size	2.02 sq ft	2.99 sq ft
Length x Width (ft)	2.08 x 0.93	4.60 x 0.62
Type	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_5698000_57824_2165.tif



Defect #	63
Feet from Start	162.12
Feet from Right	7.38
Defect Size	1.76 sq ft
Length x Width (ft)	2.31 x 0.73
Type	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_5915000_57824_2165.tif



Defect #	LB	64	65	66
Feet from Start	176.14	176.40	176.85	178.51
Feet from Right	3.55	5.66	10.41	6.83
Defect Size	NA	3.71 sq ft	4.95 sq ft	2.04 sq ft
Length x Width (ft)	NA	1.25 x 2.83	1.68 x 2.81	1.29 x 1.51
Type	Lane Bound	Delam	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 1 Image Name: 1_6130000_57824_2165.tif



Defect #	67	LB	68
Feet from Start	180.38	183.63	184.51
Feet from Right	11.23	9.52	11.89
Defect Size	5.08 sq ft	NA	4.56 sq ft
Length x Width (ft)	2.19 x 2.22	NA	2.60 x 1.68
Type	Delam	Lane Bound	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_2364000_64569_2175.tif



Defect #	LB
Feet from Start	2.88
Feet from Right	16.17
Defect Size	NA
Length x Width (ft)	NA
Type	Lane Bound

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_2554000_64569_2175.tif



Defect #	69	70	LB
Feet from Start	8.87	10.54	10.74
Feet from Right	14.78	19.66	21.36
Defect Size	3.71 sq ft	2.83 sq ft	NA
Length x Width (ft)	2.70 x 1.31	1.63 x 1.66	NA
Type	Delam	Delam	Lane Bound

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_2748000_64569_2175.tif



Defect #	71	LB
Feet from Start	17.31	17.80
Feet from Right	15.88	26.70
Defect Size	2.18 sq ft	NA
Length x Width (ft)	0.97 x 2.15	NA
Type	Delam	Lane Bound

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_3336000_64346_2169.tif



Defect #	72	EJ	73	74
Feet from Start	50.79	52.88	53.39	57.46
Feet from Right	16.48	18.19	18.11	21.41
Defect Size	3.18 sq ft	NA	1.64 sq ft	0.56 sq ft
Length x Width (ft)	2.38 x 1.28	NA	1.36 x 1.15	0.79 x 0.67
Type	Delam	Joint	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_3526000_64346_2169.tif



Defect #	EJ	75
Feet from Start	61.86	62.17
Feet from Right	25.31	15.11
Defect Size	NA	3.49 sq ft
Length x Width (ft)	NA	2.78 x 1.20
Type	Joint	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_3719000_64346_2169.tif



Defect #	76	77
Feet from Start	71.74	75.06
Feet from Right	18.05	24.99
Defect Size	9.43 sq ft	3.16 sq ft
Length x Width (ft)	3.17 x 2.84	1.97 x 1.53
Type	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_3909000_64346_2169.tif



Defect #	78	79	80
Feet from Start	81.71	82.19	88.06
Feet from Right	27.47	15.50	15.87
Defect Size	2.75 sq ft	7.50 sq ft	1.64 sq ft
Length x Width (ft)	3.28 x 0.80	3.42 x 2.10	1.04 x 1.51
Type	Delam	Delam	Delam

Return to Overview