Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_4106000_64366_2164.tif



Defect #	81	82	83	84	85
Feet from Start	89.77	90.60	92.49	95.53	95.88
Feet from Right	15.52	23.69	21.11	21.82	25.64
Defect Size	3.41 sq ft	2.55 sq ft	5.93 sq ft	4.04 sq ft	8.00 sq ft
Length x Width (ft)	1.84 x 1.77	1.61 x 1.51	2.63 x 2.15	2.08 x 1.86	1.76 x 4.36
Type	Delam	Delam	Delam	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_4303000_64366_2164.tif



Defect #	86	87	88
Feet from Start	101.50	101.64	103.00
Feet from Right	27.40	17.24	21.95
Defect Size	4.31 sq ft	1.45 sq ft	2.58 sq ft
Length x Width (ft)	3.42 x 1.20	1.49 x 0.93	1.09 x 2.26
Type	Delam	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_4495000_64366_2164.tif



Defect #	89	90
Feet from Start	110.75	117.71
Feet from Right	22.41	27.03
Defect Size	0.84 sq ft	1.16 sq ft
Length x Width (ft)	0.86 x 0.93	1.45 x 0.77
Type	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_4684000_64366_2164.tif



Defect #	EJ
Feet from Start	125.90
Feet from Right	16.92
Defect Size	NA
Length x Width (ft)	NA
Type	Joint

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_4876000_64366_2164.tif



Defect #	EJ
Feet from Start	135.33
Feet from Right	23.95
Defect Size	NA
Length x Width (ft)	NA
Type	Joint

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_5458000_64225_2160.tif



Defect #	91
Feet from Start	165.42
Feet from Right	15.68
Defect Size	1.29 sq ft
Length x Width (ft)	1.09 x 1.13
Type	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_5653000_64225_2160.tif



Defect #	92	LB	93
Feet from Start	177.97	179.08	179.93
Feet from Right	25.48	16.05	19.15
Defect Size	8.77 sq ft	NA	4.17 sq ft
Length x Width (ft)	3.83 x 2.19	NA	2.45 x 1.62
Type	Delam	Lane Bound	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_5849000_64225_2160.tif



Defect #	94	95	LB	96	97	98
Feet from Start	184.55	186.30	187.36	188.61	189.21	190.67
Feet from Right	23.76	26.90	22.02	23.63	24.53	25.82
Defect Size	6.50 sq ft	13.07 sq ft	NA	0.75 sq ft	1.85 sq ft	2.94 sq ft
Length x Width (ft)	2.87 x 2.17	5.86 x 2.13	NA	0.99 x 0.73	1.90 x 0.93	1.95 x 1.44
Type	Delam	Delam	Lane Bound	Delam	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 2 Image Name: 2_6047000_64144_2157.tif



Defect #	EJ
Feet from Start	194.73
Feet from Right	26.58
Defect Size	NA
Length x Width (ft)	NA
Type	Joint

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_2301000_59910_2183.tif



Defect #	LB
Feet from Start	1.89
Feet from Right	29.38
Defect Size	NA
Length x Width (ft)	NA
Type	Lane Bound

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_2516000_59910_2183.tif



Defect #	LB	99
Feet from Start	9.27	13.54
Feet from Right	34.10	32.13
Defect Size	NA	1.38 sq ft
Length x Width (ft)	NA	1.41 x 0.93
Type	Lane Bound	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_2720000_60316_2181.tif



Defect #	LB	100	101
Feet from Start	16.91	19.40	22.08
Feet from Right	40.12	32.17	40.51
Defect Size	NA	22.39 sq ft	1.35 sq ft
Length x Width (ft)	NA	10.12 x 2.11	1.58 x 0.82
Type	Lane Bound	Delam	Delam

Return to Overview

Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_2922000_60316_2181.tif



Defect #	102	103
Feet from Start	29.51	34.47
Feet from Right	39.85	35.12
Defect Size	2.12 sq ft	1.02 sq ft
Length x Width (ft)	1.33 x 1.53	0.64 x 1.51
Type	Delam	Delam

Return to Overview