# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_3134000_60316_2181.tif




| Defect # | 104 | 105 | 106 | 107 |
|---|---|---|---|---|
| Feet from Start | 36.43 | 38.81 | 42.24 | 42.50 |
| Feet from Right | 35.46 | 40.15 | 40.35 | 32.27 |
| Defect Size | 7.38 sq ft | 6.79 sq ft | 6.09 sq ft | 2.29 sq ft |
| Length x Width (ft) | 2.56 x 2.75 | 2.49 x 2.61 | 2.11 x 2.75 | 1.79 x 1.22 |
| Type | Delam | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_3339000_60316_2181.tif




| Defect # | EJ | 108 | 109 | 110 |
|---|---|---|---|---|
| Feet from Start | 51.02 | 51.79 | 54.28 | 55.21 |
| Feet from Right | 31.69 | 40.35 | 33.61 | 40.17 |
| Defect Size | NA | 4.04 sq ft | 2.24 sq ft | 2.02 sq ft |
| Length x Width (ft) | NA | 1.52 x 2.53 | 1.41 x 1.51 | 1.09 x 1.77 |
| Type | Joint | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_3549000_60316_2181.tif




| Defect # | 111 | EJ |
|---|---|---|
| Feet from Start | 57.23 | 60.94 |
| Feet from Right | 40.14 | 38.48 |
| Defect Size | 5.58 sq ft | NA |
| Length x Width (ft) | 2.44 x 2.19 | NA |
| Type | Delam | Joint |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_3754000_60660_2174.tif




| Defect # | 112 | 113 | 114 | 115 |
|---|---|---|---|---|
| Feet from Start | 69.23 | 69.69 | 73.14 | 75.69 |
| Feet from Right | 40.08 | 37.77 | 40.30 | 37.84 |
| Defect Size | 8.04 sq ft | 2.91 sq ft | 4.99 sq ft | 10.94 sq ft |
| Length x Width (ft) | 2.99 x 2.57 | 1.86 x 1.49 | 2.27 x 2.10 | 1.86 x 5.61 |
| Type | Delam | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_3958000_60660_2174.tif




| Defect # | 116 | 117 | 118 | 119 | 120 | 121 | 122 |
|---|---|---|---|---|---|---|---|
| Feet from Start | 77.54 | 78.50 | 79.99 | 84.66 | 85.31 | 85.91 | 86.00 |
| Feet from Right | 39.50 | 37.57 | 41.23 | 30.13 | 37.09 | 40.26 | 32.27 |
| Defect Size | 3.41 sq ft | 0.60 sq ft | 9.22 sq ft | 9.70 sq ft | 6.93 sq ft | 7.34 sq ft | 1.98 sq ft |
| Length x Width (ft) | 1.59 x 2.04 | 0.99 x 0.58 | 6.36 x 1.39 | 3.80 x 2.44 | 2.96 x 2.24 | 2.15 x 3.26 | 1.18 x 1.60 |
| Type | Delam | Delam | Delam | Delam | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_4159000_60660_2174.tif




| | |
|---|---|
| Defect # | 123 |
| Feet from Start | 92.02 |
| Feet from Right | 39.66 |
| Defect Size | 49.83 sq ft |
| Length x Width (ft) | 10.24 x 4.65 |
| Type | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_4366000_60660_2174.tif




| Defect # | 124 | 125 | 126 | 127 |
|---|---|---|---|---|
| Feet from Start | 101.64 | 102.43 | 105.83 | 106.44 |
| Feet from Right | 36.98 | 40.13 | 32.36 | 37.40 |
| Defect Size | 9.26 sq ft | 40.06 sq ft | 2.77 sq ft | 2.28 sq ft |
| Length x Width (ft) | 3.49 x 2.53 | 10.24 x 3.74 | 2.20 x 1.20 | 1.59 x 1.37 |
| Type | Delam | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_4572000_60660_2174.tif




| Defect # | 128 | 129 | 130 | 131 |
|---|---|---|---|---|
| Feet from Start | 109.59 | 111.46 | 112.82 | 117.53 |
| Feet from Right | 32.14 | 37.41 | 40.22 | 36.17 |
| Defect Size | 1.80 sq ft | 14.53 sq ft | 37.90 sq ft | 3.23 sq ft |
| Length x Width (ft) | 1.43 x 1.20 | 7.47 x 1.86 | 10.19 x 3.55 | 0.99 x 3.14 |
| Type | Delam | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_4780000_60964_2162.tif




| Defect # | 132 | 133 | 134 | EJ | 135 |
|---|---|---|---|---|---|
| Feet from Start | 120.19 | 121.12 | 124.11 | 124.89 | 127.35 |
| Feet from Right | 40.14 | 37.44 | 41.45 | 30.49 | 39.58 |
| Defect Size | 13.91 sq ft | 4.09 sq ft | 3.81 sq ft | NA | 6.74 sq ft |
| Length x Width (ft) | 3.80 x 3.50 | 2.61 x 1.49 | 3.33 x 1.09 | NA | 2.47 x 2.61 |
| Type | Delam | Delam | Delam | Joint | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_4983000_60964_2162.tif




| Defect # | 136 | 137 | EJ | 138 |
|---|---|---|---|---|
| Feet from Start | 129.76 | 131.41 | 133.77 | 134.41 |
| Feet from Right | 40.24 | 39.91 | 37.31 | 40.98 |
| Defect Size | 4.01 sq ft | 0.47 sq ft | NA | 3.16 sq ft |
| Length x Width (ft) | 2.31 x 1.66 | 0.84 x 0.53 | NA | 2.76 x 1.09 |
| Type | Delam | Delam | Joint | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_5183000_60964_2162.tif




| Defect # | EJ | 139 |
|---|---|---|
| Feet from Start | 140.00 | 147.54 |
| Feet from Right | 41.19 | 40.25 |
| Defect Size | NA | 3.48 sq ft |
| Length x Width (ft) | NA | 3.04 x 1.09 |
| Type | Joint | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_5383000_60964_2162.tif




| Defect # | 140 | 141 | 142 | 143 | 144 | 145 |
|---|---|---|---|---|---|---|
| Feet from Start | 150.79 | 153.62 | 154.67 | 155.66 | 155.95 | 158.96 |
| Feet from Right | 40.20 | 40.99 | 35.15 | 37.08 | 40.22 | 40.20 |
| Defect Size | 13.71 sq ft | 1.81 sq ft | 7.50 sq ft | 2.77 sq ft | 9.66 sq ft | 0.82 sq ft |
| Length x Width (ft) | 3.73 x 3.52 | 1.86 x 0.93 | 3.51 x 2.04 | 1.61 x 1.64 | 2.65 x 3.48 | 0.52 x 1.51 |
| Type | Delam | Delam | Delam | Delam | Delam | Delam |

Return to Overview

# Delaminations

Bridge: 5002 SB Lane: 3 Image Name: 3_5584000_60964_2162.tif




| Defect # | 146 | 147 | 148 |
|---|---|---|---|
| Feet from Start | 160.55 | 161.38 | 167.72 |
| Feet from Right | 28.36 | 40.41 | 39.81 |
| Defect Size | 1.39 sq ft | 13.61 sq ft | 9.79 sq ft |
| Length x Width (ft) | 1.97 x 0.67 | 4.46 x 2.92 | 3.42 x 2.73 |
| Type | Delam | Delam | Delam |

Return to Overview