

RECOMMENDED CITATIONS

Lawrence M. Clarke Inc.

#127034445 - Carleton Site

Citation/ Item	Classifica- tion	Standard No.	Rule No. & Rule	Description	Proposed Penalty
01-1	Willful/ Serious	Part 1	408.40114(2) - Accident prevention program criteria.	Employer did not provide and insure proper training in regards to working around excavations.	\$70,000.00
01-2	Willful/ Serious	Part 9	408.40932(5) – An on-going inspection shall be made by a qualified person.	No on-going inspection of excavation. Employee doesn't meet the criteria of a "qualified person".	\$70,000.00
01-3	Willful/ Serious	Part 9	408.40933(2) - An excavation that an employee is required to enter shall have excavated and other material stored and retained no less than 2 feet from the excavated edge.	Spoil piles were being stored too close to edge.	\$70,000.00
01-4	Willful/ Serious	Part 9	408.40941(1) – The side of an excavation more than 5 feet deep shall be sloped as prescribed in table 1, unless supported as prescribed in this part.	Excavation approx. 12 feet deep with near vertical sides. No shoring or trench box used.	\$70,000.00
02-1	Serious	Part 9	408.40933(4) – When mobilized equipment is used adjacent to an excavation where vision is restricted, stop logs, barricades, or a signal person shall be used.	Employer was operating an excavator with tracks hanging over the edge of excavation.	\$2,000.00
02-2	Serious	Part 9	408.40933(5) – An excavation 48 inches or more in depth shall have a ladder that extends a minimum of 3 feet above the top.	Employees were using a ladder that was extended only 2 feet above the top.	\$600.00
02-3	Serious	Part 9	408.40944(4) – An employee shall not work on sloped or benched excavations at levels above another employee, except where additional protection is provided.	Employee was working on the sloped part of an excavation above another employee.	\$2,000.00

02-4	Serious	Part 18	408.41867(5) – A dispensing device, hose, or nozzle shall be an approved type and shall be protected from damage.	Diesel fuel was leaking from filter device onto ground.	\$800.00
02-5	Serious	Part 22	408.42221(2) – Employer shall provide training appropriate to the work assignment covered by Part 22.	No training for traffic regulators or for traffic control.	\$1,400.00
02-6	Serious	Part 22	408.42223(3) – Signaling directions shall conform to Part 6, Michigan Manual of Uniform Traffic Control Devices.	Employees using flags instead of paddles to direct traffic.	\$1,400.00
02-7	Serious	Part 22	408.42223(10) – Traffic regulators shall wear head, eye, and foot protection.	Employee was not wearing a hard hat while directing traffic.	\$1,400.00
03-1	OTS	Part 1	408.40129(1) – Toilets shall be provided.	Employees not using toilet facility due to distance from work area.	.00
03-2	OTS	Part 22	408.42230(1) – Letter style and type specifications for paddles.	Damaged and illegible lettering on paddles.	.00