

**Design Services for US-10 from US-127 to east Leaton Road and two box culverts on US-10
over the Little Tobacco Drain**

REQ#2078 QA1

10/26/2016

Q: Were some or all geotechnical services already completed?

A: Yes. MDOT collected the pavement cores/soil borings. The scope has been revised to reflect the precautionary status.

Q: Would it be possible for MDOT to provide on ProjectWise what was already completed during the original development of the Design-Build project?

A: An ftp link was added on the website (not the scope) for this job.

Q: Will the schedule be changing?

A: At this time, the dates are as reflected in the RFP.

Q: Is the survey or existing plans available?

A: The survey will not be made available at this time. The old road plans were added to the ftp site.