

GR RAPIDS, GERALD R. FORD INT'L (GRR)

FREQ	
ATIS/ASOS	118.725
CLNC	119.3
GND	121.8
TWR/CTAF*	135.65
GREAT LAKES	
APP/DEP	
N	124.6
S	128.4
RCO	122.25
UNICOM	122.95

11-18 LOCATION

794'
ELEV

0 10
SCALE IN MILES

09852.A
41-10

SKETCH

GRR
Taxiway
Next
Pg

0 1500
SCALE IN FEET

RWY LENGTH BEYOND DISPLACED THR

08R/ — * 08L/ — * 17/ —
26L/ — * 26R/ — * 35/ —

COORDINATES

42° 52.85'N
085° 31.37'W

License
Air Carrier

FM CITY: 6.0 mi SE

LGT: ROTG BCN, MALSR, HIRL, MIRL, VASI,
PAPI, REIL. Aft twr clsd VASI, PAPI, REIL,
HIRL, MIRL—STD PCL CTAF.

MGR: Torrance Richardson, A.A.E.
Alex Peric, Phillip Johnson, Asst

PH: 616-233-6000
616-233-6055 (Aft hrs)

FBO: Signature Flight Support 616-336-4711
Mayday Avionics 616-957-4920

ATND: 24 Hr

NAV AIDS: IAP, 115.95 (GRR) 353° 5.8 NM to
fld, ILS.

FUEL: 100LL, JET A
RPR: Major A&P, Avncs
WX: ASOS 616-575-1953

SNW RMVL: Yes
TRNSP: Taxi, Rntl car (at arpt)

MEALS: At arpt
RON: 3.0 mi, CC

- FAA Class "C" Airspace durg *twr opns 0530-2400, otr times Class "E".
- Customs ldg right arpt, ph 616-942-5245, 616-249-5380 (pgr).
- Noise abatement procedures in effect.
- Birds on & invof arpt.

GRR, GERALD R. FORD INT'L TAXIWAY


FREQ

ATIS/ASOS	118.725
CLNC	119.3
GND	121.8
TWR/CTAF*	135.65
GREAT LAKES	
APP/DEP	
N	124.6
S	128.4
RCO	122.25
UNICOM	122.95

794'

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

G



Runway Incursion Hot Spots

HS 1 Pilot confusion risk int Twy A, Twy M Twy A2 near Rwy 08R-26L.

HS 2 Pilot confusion risk int Twy A, Twy F, Twy B, Twy A1 near Rwy 08R-26L.

HS 3 Pilot confusion risk int Twy B, Twy V, Twy B4 near Rwy 17-35.