




# Electro-Plating – 1696 Incident



January 3, 2020 Update



# As of January 2, 2020

- Basement Sump
  - Estimate 9,264 gallons collected
- 696-Embankment Sump
  - Estimated 1,345 gallons collected
- Subsurface Investigation
  - 10 Temporary Wells
  - 4 Permanent Wells
- Hydraulic Profiling
  - 11 Temporary Wells

# January 3, 2020

- Collect Groundwater Samples from Wells
- Additional Temporary Wells
- Additional HPT Investigation

# As of January 2, 2020

- Catch Basin Sampling
  - 3 – I-696
  - 3 – Service Drive
  - Bear Creek













