

Maintenance Advisory #	Maintenance Advisory Name
<b>2018</b>	
MA 2018-04	Guidance on Using Wing-Plows
MA 2018-03	Disposing of Surplus and Unsuitable Soils
MA 2018-02	Storage of Materials Under Bridges and Structures
MA 2018-01	Discontinue Use of X-Lite Guardrail Terminal
<b>2017</b>	
MA 2017-02	Guidance on Using Wing-Plows (Superseded by MA 2018-04)
MA 2017-01	Maintenance Activity Guides – TAMS replacing MARS
<b>2014</b>	
MA 2014-01	Wing-Plow (Superseded by MA 2018-04)
<b>2013</b>	
MA 2013-01	Best Practices for Applying Deicing Materials
<b>2012</b>	
MA 2012-04	Roadside Vegetation Management
MA 2012-03	PDRP
MA 2012-02	Cable Grip Slippage during Barrier Repair
MA 2012-01	Guidelines for Roadside Vegetation Spray Programs
<b>2010</b>	
MA 2010-05	Maintenance Material Reporting in LAPS
MA 2010-04	Insurance for Maintenance Subcontract
MA 2010-03	High Tension Cable Barrier Repairs
MA 2010-02	Cable Barrier Turnbuckles
MA 2010-01	Oil-Water Separator
<b>2009</b>	
MA 2009-11	Snow Plowing Near Railroad Crossings
MA 2009-10	Abrasives in Winter Operations
MA 2009-09	Cable Barrier System
MA 2009-08	Lights on Drums
MA 2009-07	HMA Crack Treatment
MA 2009-06	Edge Drains
MA 2009-05	Sign Sheeting Material Change
MA 2009-04	Illicit Discharge
MA 2009-03	Damaged Mailboxes
MA 2009-02	Calibration of Salt Trucks
MA 2009-01	White Shoulder Policy
<b>2008</b>	
MA 2008-10	Bridge Expansion Joints
MA 2008-09	Disposal of Used Motor Oil
MA 2008-08	Storage of Empty Drums
MA 2008-07	Rest Area Lift Stations
MA 2008-06	Wing Plow (Superseded by MA 2018-04)
MA 2008-05	Liquid Deicing
MA 2008-04	Attenuator
MA 2008-03	Emergency Scene

**Maintenance Advisory Index****10/25/2018**

MA 2008-02	Concrete Pavement
MA 2008-01	Use of Arrow Panels
<b>2007</b>	
MA 2007-01	Lights on Drums are Optional for Maintenance Activities
<b>2006</b>	
MA 2006-02	Mercury Switch Disposal
MA 2006-01	Plastic Sign Substrates
<b>2005</b>	
MA 2005-02	Bridge Maintenance
MA 2005-01	Work Zone Safety