

Response to Comments

Renewal of a Hazardous Waste Management Facility
Postclosure Operating License

for

Ford Motor Company, River Raisin Warehouse
Hazardous Waste Landfill Facility
3200 East Elm Avenue
Monroe, Michigan 48161

MID 005 057 005

October 2022



Materials Management Division
Michigan Department of Environment, Great Lakes, and Energy

OVERVIEW

On August 15, 2022, a public notice was placed in The Monroe News to solicit public comments concerning the draft hazardous waste management facility postclosure operating license (License) to be issued to Ford Motor Company (Ford), pursuant to Part 111, Hazardous Waste Management, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended, and the administrative rules promulgated pursuant to Part 111 (Part 111 Rules).

The Department of Environment, Great Lakes, and Energy (EGLE) publishes an “EGLE Calendar” that provides public notice of pending EGLE decisions. Notice regarding EGLE’s intent to issue a Part 111 License to Ford Motor Company appeared in the EGLE Calendar on August 24, 2022. The public notice was also published on the EGLE, Materials Management Division’s (MMD), Ford River Raisin Warehouse Webpage.

In accordance with R 299.9515 of the Part 111 Rules, this document was prepared to respond to significant comments submitted during the public comment period and to describe any significant changes made to the draft License. No comments were received during the comment period. EGLE made modifications to the draft License as a result of an internal review of the documents attached to the draft License. A summary of the changes made to the draft License and the reasons for each change are presented in the Summary of Changes. The License was issued on September 30, 2022.

FOR MORE INFORMATION

You are encouraged to review the *Response to Comments*, and the additional information about the Ford facility, online at Michigan.gov/FordRiverRaisinWarehouse or in person at the following locations:

- EGLE, MMD, Constitution Hall, 525 West Allegan Street, Lansing, Michigan; contact Vickie Terry at 517-284-6546; or TerryV2@Michigan.gov.
- EGLE, MMD, Jackson District Office, 301 East Louis Glick Highway, Jackson, Michigan; contact Stevie White at 517-581-0033; or WhiteS6@Michigan.gov.
- Dorsch Memorial Library, 18 East First Street, Monroe, Michigan; contact 734-241-7878.

If you have any questions, please feel free to contact either of the individuals listed below:

Christine Matlock, Permit Engineer
Engineering and Program Support Unit
Hazardous Waste Section
Materials Management Division
MatlockC2@Michigan.gov
517-290-4612
EGLE, MMD, Hazardous Waste Section
P.O. Box 30241
Lansing, MI 48909-7741

To receive future EGLE notifications concerning this facility, please contact Vickie Terry at 517-284-6546 or TerryV2@Michigan.gov, to be placed on the facility mailing list.

SUMMARY OF CHANGES

CONDITION: I.D.2

CHANGE: The expiration date was updated.

CONDITION: III.A

CHANGE: The words, “of this license” were added to the attachment reference in the license condition.

CONDITION: IV.A.1

CHANGE: The first reference to the Postclosure Groundwater Sampling and Analysis Plan was spelled out and the acronym was identified. The second reference was modified to the acronym.

CONDITION: IV.A.1.e

CHANGE: The word “Director” was added to the license condition. Also, “unless the well” was stated twice, and one of them was deleted.

CONDITION: IV.A.1.f

CHANGE: This condition was added with the pertinent language from Condition IV.A.6.

CONDITION: IV.A.4.d

CHANGE: The condition reference was updated.

CONDITION: IV.A.4.f

CHANGE: The condition reference was updated.

CONDITION: IV.A.7

CHANGE: The Hazardous Waste Section unit name was updated from Permit and Corrective Action Unit to Technical Support Unit.

CONDITION: IV.A.8

CHANGE: The condition reference was updated.

CONDITION: IV.A.9

CHANGE: The condition reference was updated.

CONDITION: IV.A.10

CHANGE: The condition reference was updated.

CONDITION: IV.B.3

CHANGE: The license attachment reference was updated.

CONDITION: IV.A.6

CHANGE: This license condition contained redundant language. The redundant language was removed, and the remaining pertinent language was added as Condition IV.A.1.f. The conditions in Part IV were renumbered from this point.

CONDITION: IV.B.3

CHANGE: The condition was modified to add a specific location in the Postclosure Plan, Attachment 4 of the License that the pertinent information could be found.