

Consumer product safety commission recalls – Fall 2024

Squeeze Plush Ball Toys

<https://www.cpsc.gov/Recalls/2024/Shawshank-LEDz-Recalls-Squeeze-Plush-Ball-Monsters-Toys-and-Easter-Squeezable-Toys-Due-to-Injury-Hazard-Sold-Exclusively-at-Ace-Hardware>

The squeeze ball toy contains a liquid and glitter combination inside a thick membrane. If the membrane is ruptured, the glittery water can splash onto a child's face and body, posing an injury hazard.

Jeune French Contemporary Upholstered Panel Cribs

[RH Baby & Child Recalls Jeune French Contemporary Upholstered Panel Cribs Due to Choking Hazard | CPSC.gov](#)

The cylindrical metal inserts in the crib's wooden frame can become loose and detach, posing a choking hazard.

LED Light-up Jelly Ring Toys

<https://www.cpsc.gov/Recalls/2024/Attom-Tech-Recalls-LED-Light-up-Jelly-Ring-Toys-Due-to-Ingestion-Hazard-Violation-of-Federal-Regulations-for-Battery-Operated-Toys-Sold-Exclusively-on-Amazon-com>

The recalled light-up jelly ring toys violate the mandatory federal battery-operated toy regulation because the rings contain button cell batteries that fit within CPSC's small parts cylinder, and can be easily accessed without requiring the use of a common household tool. When button cell batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death, posing an ingestion hazard to children.

Papablic Archie Infant Swings

[Papablic Infant Swings Recalled Due to Suffocation Hazard; Violations of Federal Regulations for Infant Sleep Products; Imported by Shenzhen Two Pony | CPSC.gov](#)

The swings pose a suffocation risk because they were marketed, intended, or designed for infant sleep, and they have an incline angle greater than 10 degrees in violation of the federal safety regulations for [Infant Sleep Products](#) and the [Safe Sleep for Babies Act](#). The swings also violate other requirements for infant swings and the labeling requirements for Reese's Law because the remote contains a button or coin-cell battery.

Besrey Twins Strollers

[Stiger Recalls Besrey Twins Strollers Due to Entrapment, Fall and Choking Hazards; Violation of Federal Regulation for Strollers; Sold Exclusively on Amazon.com | CPSC.gov](#)

The twin stroller violates multiple safety regulations for strollers. The front seat in the forward-facing configuration poses an entrapment hazard to children. In addition, failures with the restraint system and rear seat enclosure pose a fall hazard to children. In products with a black grab bar, the foam padding on the grab bar can pose a choking hazard if the child bites it.

1 Set Puzzle “Magnetic”, “Magnetism”, or “Magnetism Intelligence Strategy Game” Magnetic Battle Chess Games

<https://www.cpsc.gov/Recalls/2024/Magnetic-Chess-Games-Recalled-Due-to-Ingestion-Hazard-Violation-of-Federal-Regulations-for-Toy-Magnets-Sold-Exclusively-on-Temu-com-through-Outad-Good-Life>

The recalled magnetic chess games, which include 20 magnet pieces, violate the mandatory federal toy magnet regulation because the set contains one or more magnets that fit within CPSC’s small parts cylinder, and the magnets are stronger than permitted. When high-powered magnets are swallowed, the ingested magnets can attract each other, or another metal object, and become lodged in the digestive system. This can result in perforations, twisting and/or blockage of the intestines, infection, blood poisoning and death.