

## ***MSP/MCD DECAL APPLICATION POLICY FOR SCHOOL BUSES***

### **EXHAUST SYSTEM**

#### **Exhaust: General**

**YELLOW:** Heat shield (if required) is missing or improper.

**YELLOW:** A clamp or bracket is loose or broken resulting in compromised integrity or securement. *MCLA 257.707(3)*

**RED:** Loose, cracked or leaking manifold connection. (Some exhaust leaking around a proper connection is expected.) *MCLA 257.707(2)*

**RED:** Any part of the system that passes through the occupant compartment.

**RED:** Any leak that results from a crack, rust, or broken or missing part. (Some exhaust leaking around a proper connection is expected). *MCLA 257.707(2)*

**RED:** Any part of the exhaust system that has a measurable leak (audible or felt), or discharges under the passenger or engine compartment. *NST-SBI 10.71*

**RED:** Except for diesel engines, any oil leaking or leaks on the exhaust system.

**RED:** Any leak/leaking on the exhaust system of power steering fluid or automatic transmission fluid.