

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY REMEDIATION DIVISION

Public Record – Summary Information on Underground Storage Tanks (USTs)

General Information

Post Date: December 29, 2011

Total Number of UST Facilities: 7,184
Total Number of USTs: 19,150

Summary Information for On-Site Inspections

Number of UST Facilities Inspected: 1,950
Inspection Period Dates: **2010-10-01** to: **2011-09-30**
Percent Compliance (Combined Measure): 52%

Note: Tank, facility, and on-site inspection information is based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#)

On-site inspections measure compliance with [Site Assessments for Underground Storage Tank Systems](#).

Summary Information for Releases

Number of Confirmed UST Releases: 92 ¹

Release Reporting Period Dates: **2010-10-01** To: **2011-09-30**

Summary Information for Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	53	13%			8	15.1%	2	3.8%	11	20.8%			26	49.1%	6	11.3%
Piping	56	13.7%					11	19.6%	5	8.9%			26	75%	14	25%
Dispenser	44	10.8%											33	75%	11	25%
STP	0															
Delivery Problem	4	1%			4	100%										
Other	252	61.6%						3.2%					235	93.3%	17	6.7%
Totals	409	100%			12	2.9%	13	3.2%	16	3.9%			320	78.2%	48	11.7%

=number, % = percent of total number

Note: Release, source and cause information is based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#). Source and cause data were collected using the rules for site characterization and cleanup as given in [Part 213, Leaking Underground Storage Tanks \(LUST\)](#), of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

Obtain site-specific UST information [Underground Storage Tank List](#).

¹ Numbers are greater than source totals because releases included are over an earlier timeframe than this report period