


**DETAILED FINDINGS REPORT
HUBBELL PROCESSING AREA**

SECTION 9



**DETAILED FINDINGS REPORT – HUBBELL PROCESSING AREA
FIGURES**



- ◇ Bulk Asbestos
- Residual Process Material
- Abandoned Containers

-  Soil
-  Groundwater
-  Surface Water
-  Sediment

 Conceptual Site and Geographic Area Boundaries



Prepared By:
WESTON
SOLUTIONS of
MICHIGAN, INC
P.O. Box 577
Houghton, MI 49931

Figure 9-1a
Sampling Location Map
Hubbell Processing Area - Coal Dock
Lake Linden, Houghton County, Michigan





Figure 9-1c
Sampling Location Map
Hubbell Processing Area - Smelter
Lake Linden, Houghton County, Michigan

FILE: J:\GIS Projects\MDEQ\2017\001.001 Torch Lake.mxd\2016 CHLL SI Report\Sec09-HubProcess\Fig09 2 RPMetc Results v20160219.mxd 2:27:46 PM 2/19/2016 BROWNIK





Image Source: MIS - Public Imagery

FILE: J:\GIS Projects\WDEQ\2017\001_001_Torch Lake\mxd\2016 CHLL SI Report\Sec09-HubProcessFig09_3a_HProcess_Soil_Results_CoalDock_v20160219.mxd 1:33:11 PM 2/19/2016 BROWNK






MDEQ Part 201 Cleanup Criteria for Response Action

- 1=Statewide Default Background Level
- 2*=Groundwater Surface Water Interface Protection Criteria
- 3=Soil Saturation Concentration Screening Levels
- 4*=Residential Drinking Water Protection Criteria
- 5=Residential Soil Volatilization to Indoor Air Inhalation Criteria (VSIC)
- 6=Residential Infinite Source Volatile Soil Inhalation Criteria
- 7=Residential Finite VSIC for 5 Meter Source Thickness
- 8=Residential Finite VSIC for 2 Meter Source Thickness
- 9=Residential Particulate Soil Inhalation Criteria
- 10=Residential Direct Contact Criteria
- 11*=Nonresidential Drinking Water Protection Criteria
- 12=Nonresidential Soil Volatilization to Indoor Air Inhalation
- 13=Nonresidential Infinite Source Volatile Soil Inhalation Criteria
- 14=Nonresidential Finite VSIC for 5 Meter Source Thickness
- 15=Nonresidential Finite VSIC for 2 Meter Source Thickness
- 16=Nonresidential Particulate Soil Inhalation Criteria
- 17=Nonresidential Direct Contact Criteria
- 18=Hazardous Waste Toxicity Screening Value

* Exceedances of criteria 2, 4, and 11 shown for organics and cyanide only

Figure 9-3b
Sample Analytical Result Map - Soil
Hubbell Processing Area - Mineral Building
Lake Linden, Houghton County, Michigan






FILE: J:\GIS Projects\MDEQ\2017\001.001 Torch Lake\mxd\2016 CHLL SI Report\Sec09-HubProcess\Fig09_4a_Soil_Screening_Results_XRF_CoalDock_v20160219.mxd 2/19/2016 11:56:23 AM 2/19/2016 BROWNK


Image Source: ESRI World Imagery (NAIP 2014)

FILE: J:\GIS Projects\MI\DEQ\2017\001.001 Torch Lake\mxd\2016 CHLL SI Report\Sec09-HubProcess\Fig09 4b Soil Screening Results XRF MineralBuilding v20160219.mxd 11:59:29 AM 2/19/2016 BROWNK






FILE:J:\GIS Projects\MDEQ\2017\001.001 Torch Lake\Working Drafts\2015 CHLL SI Report\Sec09+HubProcess\Fig09_5 HubProcGW Results DRAFT\2015\008.mxd 1:52:05 PM 2/19/2016 BROWNK






FILE: J:\GIS Projects\MDEQ\2017\001.001_Torch Lake.mxd 2/19/2016 8:00:00 PM 2/19/2016 8:00:00 PM CHLL-SI-Report\Sec09-HubProcess\Fig09-6c-SED-SW-Results-Smelter-V20160219.mxd 2:19:07 PM 2/19/2016 8:00:00 PM

Image Source: MIS - Public Imagery





FILE: J:\GIS Projects\MDEQ\2017\001\001_Torch_Lake.mxd 2016 CHLL SI Report(Sec09-HubProcess\Fig09_7_PCB_Detections All Media v20160219.mxd 2:27:50 PM 2/19/2016 BROWNK