






Legend

- | | |
|---------------------------------------|-----------------------|
| FIELDS Team XRF and Laboratory Sample | Water Edge |
| FIELDS Team XRF Sample | GPS Feature - Other |
| START XRF and Laboratory Sample | Slag/Rock/Debris Pile |
| START XRF Sample | |

Source of Imagery: ESRI ArcGIS Map Service (c) 2007
Date of Photography: 06/21/2005

Figure 9a



Prepared for:
U.S. EPA REGION V
Contract No: EP-S5-06-04

TDD No.: S05-0002-0708-020
DCN: 274-2A-ABDT





Prepared by:
WESTON SOLUTIONS, INC.
2501 Jolly Road, Suite 100
Okemos, Michigan

AOI Nos. 24, 25 and 26
SITE FEATURES AND XRF LOCATIONS
TORCH LAKE AREA ASSESSMENT
KEWEENAW PENINSULA, MICHIGAN
October 2007



Source of Imagery: ESRI ArcGIS Map Service (c) 2007
Date of Photography: 06/21/2005



- Legend**
- Orange box: XRF results exceeding RDCC are shown in Orange
 - Yellow box: Laboratory results exceeding RDCC are shown in Yellow
 - Red triangle: Soil XRF Sample Exceeds Part 201 Residential Direct Contact Criteria (RDCC)
- mg/kg -- milligrams per kilogram

Figure 9b

 Prepared for: U.S. EPA REGION V Contract No: EP-S5-06-04 TDD No.: S05-0002-0708-020 DCN: 274-2A-ABDT	 Prepared by: WESTON SOLUTIONS, INC. 2501 Jolly Road, Suite 100 Okemos, Michigan	AOI Nos. 24, 25 and 26 RDCC EXCEEDANCES IN SOIL TORCH LAKE AREA ASSESSMENT KEWEENAW PENINSULA, MICHIGAN October 2007
---	---	--