

From: Sybil Kolon
To: Kolon, Sybil
Date: 4/20/2007 1:35:20 PM
Subject: Gelman - Periodic DEQ Update - Unit E Drilling Results

PLS has completed installation of a set of three monitoring wells near the intersection of Virginia and Charlton. Samples of groundwater were collected at ten foot intervals where water was encountered. Seven samples taken from 40 to 110 feet were all non-detect for 1,4-dioxane. Three samples taken from 150 to 170 feet had 1,4-dioxane of 3, 2 and 5 parts per billion, respectively. Samples taken at 200 and 210 feet were non-detect. Bedrock was encountered at 212 feet.

Three monitoring wells have been installed, screened at 50-55 feet, 165-170 feet and 202-207 feet.

Previous updates and other details can be found on the DEQ's Gelman web site, which can be accessed in two ways:

click on the following link:

http://www.michigan.gov/deq/0,1607,7-135-3311_4109_9846_9847-71595--,00.html

or enter <http://www.michigan.gov/deqrrd>, then scroll to "Contaminated Sites List" and click on "Gelman Sciences, Inc. Site of Contamination".

Additional documents are also available at the Gelman Information Repository Locations:

Ann Arbor District Library
Downtown Library
343 South Fifth Avenue
734-327-4200

Scio Township Hall
827 North Zeeb Road, Ann Arbor
734-665-2123

City of Ann Arbor Water Utilities Department
100 North Fifth Avenue
Contact: Venita Harrison 734-994-8286

Washtenaw County Department of Planning
and Environment
705 North Zeeb Road, Ann Arbor
Contact: Michael Gebhard 734-222-3855

Please contact me if you have any questions or would like to be removed from or added to this distribution list.

Sybil Kolon
Jackson District Office
Remediation and Redevelopment Division
Department of Environmental Quality
301 E. Louis Glick Hwy.
Jackson, MI 49201
phone: 517-780-7937
fax: 517-780-7855 e-mail: kolons@michigan.gov