

Michigan Disposal Waste Treatment Plant Summary of Recent Hazardous Waste Inspections

The Michigan Department of Environment, Great Lakes, and Energy (EGLE), Materials Management Division (MMD), performs routine inspections at US Ecology’s Michigan Disposal Waste Treatment Plant (MDWTP) located at 49350 North I-94 Service Drive in Belleville, Michigan. The inspections are performed to evaluate the facility’s compliance with state and federal hazardous waste laws and the conditions of the facility’s operating license. Inspections are typically unannounced and conducted four times per year. Recently, EGLE MMD made some adjustments to inspection procedures due to COVID-19, including providing notice of our inspections to ensure the safety of EGLE and facility staff. The following is a summary of the EGLE MMD hazardous waste inspections conducted over the last three years and a summary of the findings. This information is publicly available for review in the Waste Data System database available online at <https://www.egle.state.mi.us/wdspj>. For more information about EGLE MMD hazardous waste inspections at MDWTP, please contact Michael Busse at BusseM@Michigan.gov or 248-226-0975.

10/29/2020	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
7/9/2020	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
3/16/2020	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
12/13/2019	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
8/16/2019	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
5/23/2019	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
3/15/2019	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
11/30/2018	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
8/22/2018	A site inspection was performed and found one violation. One box of used fluorescent light bulbs was mislabeled. The regulation requires that the label read “universal waste lamps”, “used lamps”, or “waste lamps” and the box was labeled “bulbs.” On 8/24/2018, MDWTP documented that the label had been corrected.
6/21/2018	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
2/14/2018	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
11/29/2017	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.
8/28/2017	A site inspection was performed and MDWTP was found in compliance with all areas evaluated.