3RD QUARTER
WATER QUALITY PARAMETER MONITORING

SAMPLE POINT IDENTIFICATION				PARAMETERS AND RESULTS									
Dist. Location # (previous #)	Sample Point Name & Address	Sample date	Tech	Temperature (°C)	Conductivity (mS)	pH (su)	Total Alkalinity (mg/L $CaCO_3$)	Calcium (mg/L Ca^{2+})	Hardness (mg/L $CaCO_3$)	Turbidity (NTU)	Iron (mg/L)	Chloride (mg/L Cl^-)	Phosphate (mg/L PO_4)
#14 (1)	Davison Rd.	8/8/2017	HK	21.5	0.23	7.62	78	30.5	102	0.09	0.02	15	3.6
#16 (2)	E Court St	8/9/2017	HK	21.3	0.23	7.62	80	30.5	102	0.077	0.01	15	3.6
#17 (3)	S. Dort Hwy	8/9/2017	HK	20.7	0.23	7.58	80	30.5	102	0.074	0.01	15	3.5
#4	Corunna Rd.	8/4/2017	HK	21.6	0.23	7.49	80	32.9	102	0.279	0.03	15	3.6
#1 (5)	Chevrolet Ave.	8/4/2017	HK	21.2	0.23	7.50	78	32.9	102	0.293	0.06	15	3.7
#19 (6)	MLK Blvd.	8/3/2017	HK	22.5	0.23	7.71	78	31.3	104	0.746	0.06	15	4.0
#9 (7)	Clio Rd.	8/3/2017	HK	21.4	0.23	7.59	78	31.3	102	0.14	0.01	15	3.6
#8	N. Saginaw St.	8/3/2017	HK	20.9	0.23	7.62	80	31.3	102	0.171	0.01	15	3.7
CSII	Control Station #2 N. Dort Hwy.	8/8/2017	HK	19.7	0.23	7.46	78	30.5	102	0.153	0.01	14	1.4
#5 (CS)	Cedar Street Reservoir & Pump Station	8/7/2017	WB	20.7	0.23	7.55	80	31.3	104	0.297	0.06	15	3.6

3RD QUARTER
WATER QUALITY PARAMETER MONITORING

SAMPLE POINT IDENTIFICATION				PARAMETERS AND RESULTS									
Distribution System Location #	Sample Point Name & Address	Sample date	Tech	Temperature (°C)	Conductivity (mS)	pH (su)	Total Alkalinity (mg/L $CaCO_3$)	Calcium (mg/L Ca^{2+})	Hardness (mg/L $CaCO_3$)	Turbidity (NTU)	Iron (mg/L)	Chloride (mg/L Cl^-)	Phosphate (mg/L PO_4)
#2	Saginaw St	8/8/2017	WB	29.8	0.24	7.60	80	31.3	104	0.116	0.01	15	3.5
#3	Beecher	8/4/2017	HK	20.9	0.23	7.47	80	32.9	102	0.177	0.02	15	3.6
#6	W. Court St	8/7/2017	WB	20.8	0.23	7.56	80	31.3	104	0.363	0.05	15	3.6
#7	Foss Ave	8/3/2017	HK	22.5	0.23	7.78	78	31.3	102	0.35	0.03	15	3.7
#10	Clio Rd	8/3/2017	HK	21.3	0.23	7.62	78	31.3	100	0.122	0.01	15	3.6
#12	Garland St	8/4/2017	HK	24.5	0.23	7.48	80	32.9	102	0.46	0.06	15	3.9
#13	Richfield Rd	8/8/2017	HK	22.4	0.23	7.64	80	29.7	102	0.089	0.01	15	3.5
#15	Davison Rd	8/8/2017	HK	22.9	0.23	7.57	80	29.7	102	0.096	0.02	15	3.3
#18	Fenton Rd	8/8/2017	WB	22.2	0.24	7.65	80	31.3	104	0.098	0.02	15	3.3
#20	MLK Blvd	8/3/2017	HK	21.6	0.23	7.60	76	31.3	100	0.159	0.01	15	3.5

3RD QUARTER
WATER QUALITY PARAMETER MONITORING

SAMPLE POINT IDENTIFICATION				PARAMETERS AND RESULTS									
Distribution System Location #	Sample Point Name & Address	Sample date	Tech	Temperature (°C)	Conductivity (mS)	pH (su)	Total Alkalinity (mg/L $CaCO_3$)	Calcium (mg/L Ca^{2+})	Hardness (mg/L $CaCO_3$)	Turbidity (NTU)	Iron (mg/L)	Chloride (mg/L Cl^-)	Phosphate (mg/L PO_4)
#21	Leta Avenue	8/8/2017	WB	22.0	0.24	7.66	80	30.5	102	0.165	0.02	15	3.4
#22	W. Home Ave	8/9/2017	HK	20.3	0.25	7.61	80	30.5	102	0.089	0.01	15	3.5
#23	Western Rd	8/8/2017	HK	20.6	0.23	7.63	80	30.5	102	0.124	0.02	15	3.6
#24	Kleinpell St.	8/3/2017	HK	20.1	0.23	7.71	78	31.3	102	0.092	0.01	15	3.5
#25	Western Rd	8/4/2017	HK	21.1	0.23	7.73	80	31.3	102	0.313	0.03	15	3.5
	Dupont St	8/9/2017	WB	21.8	0.23	7.61	80	30.5	102	0.086	0.01	15	3.6