2ND QUARTER
WATER QUALITY PARAMETER MONITORING

SAMPLE POINT IDENTIFICATION				PARAMETERS AND RESULTS										**PRIOR WEEK RESULTS	
Dist. Location # (previous #)	Sample Point Name & Address	Sample date	Tech	Temperature (°C)	Conductivity (mS)	pH (su)	Total Alkalinity (mg/L $CaCO_3$)	Calcium (mg/L Ca^{2+})	Hardness (mg/L $CaCO_3$)	Turbidity (NTU)	Iron (mg/L)	Chloride (mg/L Cl^-)	Phosphate (mg/L PO_4)	Sample date	Lead (µg/L Pb)
#14 (1)	Davison Rd.	6/23/2017	HK	18.0	0.24	7.38	76	29.7	100	0.061	0.03	13	3.5	6/21/2017	ND
#16 (2)	E Court St	6/23/2017	HK	17.0	0.23	7.38	76	29.7	100	0.073	0.03	13	3.6	6/21/2017	ND
#17 (3)	S. Dort Hwy	6/23/2017	HK	17.1	0.24	7.32	76	30.5	100	0.094	0.02	13	3.5	6/21/2017	ND
#4	Corunna Rd.	6/26/2017	HK	18.2	0.23	7.38	76	32.9	100	0.104	0.02	14	3.5	6/16/2017	ND
#1 (5)	Chevrolet Ave.	6/26/2017	HK	17.5	0.23	7.45	74	31.3	98	0.135	0.03	14	3.5	6/16/2017	ND
#19 (6)	MLK Blvd.	6/22/2017	HK	20.4	0.24	7.42	76	32.1	100	0.128	0.08	13	3.3	6/15/2017	ND
#9 (7)	Clio Rd.	6/27/2017	HK	19.1	0.23	7.44	76	30.5	100	0.111	0.01	13	3.6	6/15/2017	ND
#8	N. Saginaw St.	6/27/2017	HK	17.4	0.23	7.41	76	30.5	100	0.094	0.01	13	3.5	6/15/2017	ND
CSII	Control Station #2 N. Dort Hwy.	6/27/2017	WB	12.8	0.22	7.45	74	31.3	100	0.223	0.01	14	1.3	6/20/2017	ND
#5 (CS)	Cedar Street Reservoir & Pump Station	6/22/2017	HK	14.5	0.23	7.28	74	32.1	100	0.159	0.03	13	3.6	6/19/2017	ND

2ND QUARTER
WATER QUALITY PARAMETER MONITORING

SAMPLE POINT IDENTIFICATION				PARAMETERS AND RESULTS									
Distribution System Location #	Sample Point Name & Address	Sample date	Tech	Temperature (°C)	Conductivity (mS)	pH (su)	Total Alkalinity (mg/L $CaCO_3$)	Calcium (mg/L Ca^{2+})	Hardness (mg/L $CaCO_3$)	Turbidity (NTU)	Iron (mg/L)	Chloride (mg/L Cl^-)	Phosphate (mg/L PO_4)
#2	Saginaw St	6/26/2017	HK	28.7	0.24	7.42	76	30.5	98	0.07	0.03	13	3.4
#3	Beecher	6/26/2017	HK	17.0	0.24	7.43	76	29.7	98	0.096	0.04	13	3.5
#6	W. Court St	6/22/2017	HK	21.2	0.24	7.29	74	32.1	100	0.263	0.09	13	3.3
#7	Foss Ave	6/27/2017	HK	18.5	0.24	7.56	76	30.5	100	0.12	0.03	13	3.6
#10	Clio Rd	6/27/2017	HK	18.2	0.23	7.41	76	30.5	100	0.093	0.01	14	3.5
#12	Garland St	6/22/2017	HK	19.7	0.23	7.34	74	32.1	100	0.087	0.04	13	3.5
#13	Richfield Rd	6/23/2017	HK	20.0	0.24	7.39	76	29.7	100	0.07	0.04	13	3.4
#15	Davison Rd	6/23/2017	HK	19.3	0.24	7.33	76	29.7	100	0.097	0.03	13	3.4
#18	Fenton Rd	6/23/2017	HK	19.7	0.23	7.42	76	32.9	102	0.107	0.04	13	3.4
#20	MLK Blvd	6/26/2017	HK	19.0	0.23	7.44	76	31.3	100	0.087	0.04	13	3.4

2ND QUARTER
WATER QUALITY PARAMETER MONITORING

SAMPLE POINT IDENTIFICATION				PARAMETERS AND RESULTS									
Distribution System Location #	Sample Point Name & Address	Sample date	Tech	Temperature (°C)	Conductivity (mS)	pH (su)	Total Alkalinity (mg/L $CaCO_3$)	Calcium (mg/L Ca^{2+})	Hardness (mg/L $CaCO_3$)	Turbidity (NTU)	Iron (mg/L)	Chloride (mg/L Cl^-)	Phosphate (mg/L PO_4)
#21	Leta Avenue	6/19/2017	WB	20.6	0.23	7.57	76	28.9	96	0.1	0.03	14	3.5
#22	W. Home Ave	6/27/2017	HK	17.3	0.23	7.45	76	29.7	98	0.073	0.01	14	3.5
#23	Western Rd	6/28/2017	HK	17.2	0.22	7.47	74	28.9	100	0.137	0.01	13	3.6
#24	Kleinpell St.	6/22/2017	HK	17.7	0.24	7.38	76	32.1	102	0.102	0.03	13	3.4
#25	Western Rd	6/23/2017	HK	19.9	0.24	7.55	76	28.9	102	0.069	0.03	13	3.5
WS (Sub)	E Kearsley St	6/28/2017	WB	21.4	0.22	7.56	76	29.7	100	0.195	0.03	13	3.6