

**MICHIGAN DEPARTMENT OF LICENSING
AND REGULATORY AFFAIRS
BUREAU OF FIRE SERVICES - STORAGE TANK DIVISION**

Public Record - Summary Information on Underground Storage Tanks (USTs)

General Information

Posted Date: October 19, 2020

Total Number of UST Facilities: 6679
Total Number of USTs: 17306

Summary Information for On-Site Inspections

Number of UST Facilities Inspected: 1337
Inspection Period Dates: **10/1/2019 to 9/30/2020**

Percent Compliance (Combined Measure): 88%

Note: Tank, facility, and on-site inspection information is based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#)

On-site inspections measure compliance with [Site Assessments for Underground Storage Tank Systems](#)

Summary Information for Releases

Number of Confirmed UST Releases: 202¹
Release Reporting Period Dates: **10/1/2019 To 9/30/2020**

Summary Information for Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	59	20.7%					59	45.0%								
Piping	72	25.3%					72	55.0%								
Dispenser	21	7.4%											21	87.5%		
STP																
Delivery Problem																
Other	133	46.7%			8	100.0%							3	12.5%	122	100.0%
Totals	285	100.0%			8	100.0%	131	100.0%					24	100.0%	122	100.0%

=number, % = percent of total number

Note: Release, source and cause information is based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#)
Source and cause data were collected using the rules for site characterization and cleanup as given in [Part 213, Leaking Underground Storage Tanks \(LUST\)](#), of the Natural Resources and Environmental Protection 1994 PA 451, as amended.

Obtain site-specific UST information [Underground Storage Tank List](#).

¹ Source totals are greater than release totals because there may be multiple sources for one release.