



Michigan's Deteriorating Roads and Bridges

November 2014



Superior Region



**M-123 Black Creek Sinkhole, Chippewa County
Pipe Joint Failure Leading to Road Sinkhole**



**I-75 BS NB, Sault Ste. Marie, Chippewa County
Concrete pavement joint failure due to spring freeze-thaw cycle**



**I-75 BS, Sault Ste. Marie, Chippewa County
Concrete pavement joint failure due to spring freeze-thaw cycle**



**I-75 BS Easterday to Sheridan, Sault Ste. Marie, Chippewa County
Pavement Deterioration**



**M-48 Railing & Fascia E Br Munuscong & M-48 N, Chippewa County
Deterioration-Wear & Tear**



**M-48 Bridge, Chippewa County
Deterioration-Wear & Tear**



SB I-75 Sinkhole, Mackinac County
Subgrade sinkhole due to deteriorated pipe/underdrain



**US-2, Crystal Falls, Iron County
Concrete Deterioration**