aterials esting onsultants, INC.

APPENDIX A SITE PHOTOGRAPHS



Frontal view of Billie S. Farnum Building from S. Capitol




Lobby at main level

TITLE: SITE PHOTOGRAPHS			PROJI	ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 1716218 REV. BY: RD		Matariala Tantina Osmanlianta
	DR. BY: JB			Materials Testing Consultants, INC.




Typical committee room



Office space with typical finishes

TITLE: SITE PH	TITLE: SITE PHOTOGRAPHS			PROJECT: 123 W. Allegan Street	
SCALE: NTS	DATE: 2/152018	PROJECT NO.: 17	1618	Materials Testing Consultants, INC.	
	DR. BY: JB	REV. BY: RD		Materials resting Consultants, Inc.	



Basement boiler room facilities




Additional view of boiler room

TITLE: SITE PHOTOGRAPHS			PROJI	ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 171618 REV. BY: RD		Materials Testing Consultants, INC.
	DR. BY: JB			



Corrosion inhibitor container (rear) and compressor units



Green fluid migrating towards drain from Hankison air drying unit

TITLE: SITE PHOTOGRAPHS			PROJI	ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 171618		Materials Testing Consultants, INC.
	DR. BY: JB	REV. BY: RD		Materials resting Consultants, Inc.



Commerical paints, primers, enamels, etc within boiler room



TITLE: SITE PHOTOGRAPHS			PROJI	ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 171618		Matariala Taatina Oonaaltanta
	DR. BY: JB	REV. BY: RD		Materials Testing Consultants, INC.



Penthouse mechanical and boiler room



Additional view of boiler room

TITLE: SITE PH	TITLE: SITE PHOTOGRAPHS			ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 17	1618	Materials Testing Consultants, INC.
	DR. BY: JB	REV. BY: RD		




Parking lot for Farnum Building at 215 S. Capitol Ave



Additional view looking southwest across parking lot (Note: Electical transformer)

TITLE: SITE PHOTOGRAPHS			PROJI	ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 171618 REV. BY: RD		Materials Testing Consultants, INC.
	DR. BY: JB			



Blue Cross Blue Shield Building to southwest – 232 S. Capitol Ave



BG Parking (Formerly Ellis Parking Ramp) at 205 W. Allegan Street to immediate west of Site

TITLE: SITE PHOTOGRAPHS			PROJ	ECT: 123 W. Allegan Street
SCALE: NTS	DATE: 2/15/2018	PROJECT NO.: 171618 REV. BY: RD		Materials Testing Consultants, INC.
	DR. BY: JB			