aterials esting consultants, INC.

APPENDIX B

AERIAL PHOTOGRAPHS

Farnum Building

123 W. Allegan Street Lansing, MI 48933

Inquiry Number: 5155046.5 January 12, 2018

The EDR Aerial Photo Decade Package



6 Armstrong Road, 4th floor Shelton, CT 06484 Toll Free: 800.352.0050 www.edrnet.com

EDR Aerial Photo Decade Package

Site Name:

Client Name:

01/12/18

Farnum Building 123 W. Allegan Street Lansing, MI 48933 EDR Inquiry # 5155046.5

Materials Testing Consultants 693 Plymouth NE Grand Rapids, MI 49505 Contact: Joe Bolin



Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:				
<u>Year</u>	<u>Scale</u>	Details	Source	
2012	1"=500'	Flight Year: 2012	USDA/NAIP	
2010	1"=500'	Flight Year: 2010	USDA/NAIP	
2009	1"=500'	Flight Year: 2009	USDA/NAIP	
2006	1"=500'	Flight Year: 2006	USDA/NAIP	
2005	1"=500'	Flight Year: 2005	USDA/NAIP	
1993	1"=500'	Acquisition Date: April 22, 1993	USGS/DOQQ	
1981	1"=500'	Flight Date: May 03, 1981	USDA	
1976	1"=500'	Flight Date: May 09, 1976	USDA	
1970	1"=500'	Flight Date: January 01, 1970	USDA	
1963	1"=500'	Flight Date: January 01, 1963	USDA	
1956	1"=500'	Flight Date: October 28, 1956	USGS	
1950	1"=500'	Flight Date: January 01, 1950	USDA	
1938	1"=500'	Flight Date: June 14, 1938	USGS	

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental risk for any property is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

























